Submit 3 Copies To Appropriate District State of New Mexico	Form C-103
Office District I  Energy, Minerals and Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240	WELL API NO. 30-025-37178
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	5. Indicate Type of Lease
District III 1220 South St. Francis Dr.	STATE STEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	None
87505 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	3
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	Townsend
1. Type of Well: Oil Well  Gas Well  Other	8. Well Number 1
2. Name of Operator	9. OGRID Number 228971
Matrix New Mexico Operating Company, LLC	10.70
3. Address of Operator	10. Pool name or Wildcat Trinity (Wolfcamp)
508 West Wall #700, Midland, Texas 79701	Trinity (Woncamp)
4. Well Location	
Unit Letter A : 530 feet from the North line and 330	
Section 10 Township 13S Range 38I	
11. Elevation (Show whether DR, RKB, RT, GR, etc.	(1) The second of the second o
Pit or Below-grade Tank Application ☐ or Closure 🗵	The state of the s
Pit type Reserve Depth to Groundwater 240 Distance from nearest fresh water well 1.0 mi	es Distance from nearest surface water_none
	ruction Materialcalicbe
12. Check Appropriate Box to Indicate Nature of Notice	Report or Other Data
12. Check Appropriate Box to indicate Nature of Notice	, Report of Outer Data
NOTICE OF INTENTION TO: SUI	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WO	
TEMPORARILY ABANDON	RILLING OPNS. P AND A
	RILLING OPNS. P AND A
TEMPORARILY ABANDON	RILLING OPNS. P AND A
TEMPORARILY ABANDON	RILLING OPNS. P AND A  NT JOB  Indigive pertinent dates, including estimated date
TEMPORARILY ABANDON	RILLING OPNS. P AND A  NT JOB  Indigive pertinent dates, including estimated date
TEMPORARILY ABANDON	RILLING OPNS. P AND A  NT JOB  Indigive pertinent dates, including estimated date
TEMPORARILY ABANDON	RILLING OPNS. P AND A  NT JOB  Indigive pertinent dates, including estimated date
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DEPORT OF ALTER CASING MULTIPLE COMPL CASING/CEMENT OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion.  1. Drill 12 1/4" hole to 4535' 2. Run 8 5/8", 48 #/FT, H-40 New API casing to 4535'	RILLING OPNS. P AND A D NT JOB
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DE PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT CASIN	RILLING OPNS. P AND A D NT JOB
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DEPULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT CASING	RILLING OPNS. P AND A D NT JOB
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DIFERENCE OTHER:  Run 8 5/8", 48 #/FT, H-40 New API casing to 4535'  Cement with 1385 sx Interfil C w/¼ #/sx Flocele /sx followed by 320 sx Premium 4. Bump plug @ 11:00 AM 7-5-05-Held OK.  Circulate cement to pit -70 sx	RILLING OPNS. P AND A D NT JOB
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DEPULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT CASING	RILLING OPNS. P AND A D NT JOB
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DIPULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT CASING	RILLING OPNS. P AND A D NT JOB
TEMPORARILY ABANDON	RILLING OPNS. P AND A D NT JOB
TEMPORARILY ABANDON	RILLING OPNS. P AND A D NT JOB
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DEPULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT CASING/CEMENT CASING MULTIPLE COMPL CASING/CEMENT CASING/CEMENT CASING MULTIPLE COMPL CASING/CEMENT CASING MULTIPLE COMPL CASING/CEMENT CASING MULTIPLE COMPL CASING/CEMENT CASING AND CASING MULTIPLE COMPLETIONS: As of starting any proposed work). SEE RULE 1103. For Multiple Completions: As or recompletion.  1. Drill 12 1/4" hole to 4535' 2. Run 8 5/8", 48 #/FT, H-40 New API casing to 4535' 3. Cement with 1385 sx Interfil C w/½ #/sx Flocele /sx followed by 320 sx Premium Multiple Completions: As or recompletion.  4. Bump plug @ 11:00 AM 7-5-05-Held OK. 5. Circulate cement to pit -70 sx 6. WOC 12 hours 7. Cut off & nipple up well head 8. Test casing & BOPs to 1000 psi - OK	RILLING OPNS. PAND A DATE JOB NT JOB
TEMPORARILY ABANDON	AT JOB A DAM DAM DAM DAM DAM DAM DAM DAM DAM D
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DEPULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT CASING/CEMENT CASING MULTIPLE COMPL CASING/CEMENT CASING/CEMENT CASING MULTIPLE COMPL CASING/CEMENT CASING MULTIPLE COMPL CASING/CEMENT CASING MULTIPLE COMPL CASING/CEMENT CASING AND CASING MULTIPLE COMPLETIONS: As of starting any proposed work). SEE RULE 1103. For Multiple Completions: As or recompletion.  1. Drill 12 1/4" hole to 4535' 2. Run 8 5/8", 48 #/FT, H-40 New API casing to 4535' 3. Cement with 1385 sx Interfil C w/½ #/sx Flocele /sx followed by 320 sx Premium Multiple Completions: As or recompletion.  4. Bump plug @ 11:00 AM 7-5-05-Held OK. 5. Circulate cement to pit -70 sx 6. WOC 12 hours 7. Cut off & nipple up well head 8. Test casing & BOPs to 1000 psi - OK	AT JOB A DAM DAM DAM DAM DAM DAM DAM DAM DAM D
TEMPORARILY ABANDON	AT JOB A DAM DAM DAM DAM DAM DAM DAM DAM DAM D
TEMPORARILY ABANDON	RILLING OPNS. PAND A not proposed completion of proposed completion of proposed completion of Plus  The proposed completion of Plus
TEMPORARILY ABANDON	RILLING OPNS. PAND A nd give pertinent dates, including estimated date attach wellbore diagram of proposed completion and Plus  The properties of properties of properties of
TEMPORARILY ABANDON	RILLING OPNS. PAND A nd give pertinent dates, including estimated date attach wellbore diagram of proposed completion and Plus  The properties of properties of properties of
TEMPORARILY ABANDON	RILLING OPNS. PAND A not proposed completion of proposed completion of proposed completion of Plus  The proposed completion of Plus

 **FAUX** 

Office		f New Mexico	Form C-103	
District I	Energy, Mineral	s and Natural Resources	May 27, 2004 WELL API NO.	
1625 N. French Dr., Hobbs, NM 88240 District II			30-025-37178	
1301 W. Grand Ave., Artesia, NM 88210		VATION DIVISION	5. Indicate Type of Lease	
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE FEE	
District IV	Santa I	Fe, NM 87505	6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505			None	
SUNDRY NOT	ICES AND REPORTS (		7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPO	SALS TO DRILL OR TO DE	EPEN OR PLUG BACK TO A		
DIFFERENT RESERVOIR. USE "APPLI PROPOSALS.)	CATION FOR PERMIT" (FO	RM C-101) FOR SUCH	Townsend	
1. Type of Well: Oil Well	Gas Well  Other		8. Well Number 1	
2. Name of Operator  Matrix New Mexico Operating Co	ompany,LLC		9. OGRID Number 228971	
3. Address of Operator			10. Pool name or Wildcat	
508 West Wall #700, Midland, Te	xas 79701		Trinity (Wolfcamp)	
4. Well Location				
Unit LetterA:	530 _feet from the _Nor	th line and330fee	et from the _Eestline	
Section 10	Township	13S Range 38E	NMPM Lea County	
نسف سفتگه ۴ دار قعم به وارد را در معید ۱۰ دارهٔ به به این میگرد. در در معید ۱۰ دارهٔ به در در میشد در در در میشد.	11. Elevation (Show v	whether DR, RKB, RT, GR, etc.)	المراجع والمعارض المعالية والمعارض المعارض والمعارض والم	
Ria D.L. Tolk A. Radio III	Cleans M		a little and think a figure of the same and	
Pit or Below-grade Tank Application	•		Distance from the second surface water	
Pit typeReserve Depth to Groundw	<del></del>	· · · · · · · · · · · · · · · · · · ·	Distance from nearest surface water_none	
Pit Liner Thickness: 12 mil	Below-Grade Tank: Vo			
12. Check	Appropriate Box to I	ndicate Nature of Notice, I	Report or Other Data	
NOTICE OF IN	ITENTION TO	QUBS	SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDO			
TEMPORARILY ABANDON	CHANGE PLANS	☐ COMMENCE DRIL		
PULL OR ALTER CASING □	MULTIPLE COMPL	☐ CASING/CEMENT	JOB ⊠	
	MOLFIFEE COMIFE		90D (A)	
_	AIOLTIPLE COMPL	□ OTHER:	. П	
OTHER:		OTHER:	give pertinent dates, including estimated dat	
OTHER:  13. Describe proposed or composed we of starting any proposed we	oleted operations. (Clear	ly state all pertinent details, and		
OTHER: 13. Describe proposed or comp	oleted operations. (Clear	ly state all pertinent details, and	give pertinent dates, including estimated dat	
OTHER:  13. Describe proposed or compof starting any proposed we or recompletion.	oleted operations. (Clear	ly state all pertinent details, and	give pertinent dates, including estimated dat	
OTHER:  13. Describe proposed or compof starting any proposed we or recompletion.  1. Drill 7 7/8" hole to 9807'	oleted operations. (Clear ork). SEE RULE 1103.	ly state all pertinent details, and For Multiple Completions: Atta	give pertinent dates, including estimated dat	
OTHER:  13. Describe proposed or compof starting any proposed we or recompletion.	oleted operations. (Clear ork). SEE RULE 1103.	ly state all pertinent details, and For Multiple Completions: Attacasing to 9807'	give pertinent dates, including estimated dat	
OTHER:  13. Describe proposed or composed or starting any proposed we or recompletion.  1. Drill 7 7/8" hole to 9807' 2. Run 5-1/2" 17#/ft, J-55 & 1 3. Cement with 500 sx Super 4. Bump plug @ 3:15 PM 8-0	oleted operations. (Clear ork). SEE RULE 1103. N-80, LT&C, New API H w/35 bbls Super Flush 2-05-Held OK.	ly state all pertinent details, and For Multiple Completions: Attacasing to 9807'	give pertinent dates, including estimated dat	
OTHER:  13. Describe proposed or composed we or recompletion.  1. Drill 7 7/8" hole to 9807' 2. Run 5-1/2" 17#/ft, J-55 & 1 3. Cement with 500 sx Super 4. Bump plug @ 3:15 PM 8-0 5. Top of cement @ 7768'-Bo	oleted operations. (Clear ork). SEE RULE 1103. N-80, LT&C, New API H w/35 bbls Super Flush 12-05-Held OK. ond Log measurement	ly state all pertinent details, and For Multiple Completions: Attacasing to 9807'	give pertinent dates, including estimated dat	
OTHER:  13. Describe proposed or composed we or recompletion.  1. Drill 7 7/8" hole to 9807' 2. Run 5-1/2" 17#/ft, J-55 & 1 3. Cement with 500 sx Super 4. Bump plug @ 3:15 PM 8-0 5. Top of cement @ 7768'-Bo 6. Nipple down BOP & cut of	oleted operations. (Clear ork). SEE RULE 1103. N-80, LT&C, New API H w/35 bbls Super Flush 12-05-Held OK. ond Log measurement	ly state all pertinent details, and For Multiple Completions: Attacasing to 9807'	give pertinent dates, including estimated dat	
OTHER:  13. Describe proposed or composed we or recompletion.  1. Drill 7 7/8" hole to 9807' 2. Run 5-1/2" 17#/ft, J-55 & 1 3. Cement with 500 sx Super 4. Bump plug @ 3:15 PM 8-0 5. Top of cement @ 7768'-Bo	oleted operations. (Clear ork). SEE RULE 1103. N-80, LT&C, New API H w/35 bbls Super Flush 12-05-Held OK. ond Log measurement	ly state all pertinent details, and For Multiple Completions: Attacasing to 9807'	give pertinent dates, including estimated dat	
OTHER:  13. Describe proposed or composed we or recompletion.  1. Drill 7 7/8" hole to 9807' 2. Run 5-1/2" 17#/ft, J-55 & 1 3. Cement with 500 sx Super 4. Bump plug @ 3:15 PM 8-0 5. Top of cement @ 7768'-Bo 6. Nipple down BOP & cut of	oleted operations. (Clear ork). SEE RULE 1103. N-80, LT&C, New API H w/35 bbls Super Flush 12-05-Held OK. ond Log measurement	ly state all pertinent details, and For Multiple Completions: Attacasing to 9807'	give pertinent dates, including estimated dat	
OTHER:  13. Describe proposed or composed we or recompletion.  1. Drill 7 7/8" hole to 9807' 2. Run 5-1/2" 17#/ft, J-55 & 1 3. Cement with 500 sx Super 4. Bump plug @ 3:15 PM 8-0 5. Top of cement @ 7768'-Bo 6. Nipple down BOP & cut of	oleted operations. (Clear ork). SEE RULE 1103. N-80, LT&C, New API H w/35 bbls Super Flush 12-05-Held OK. ond Log measurement	ly state all pertinent details, and For Multiple Completions: Attacasing to 9807'	give pertinent dates, including estimated dat	
OTHER:  13. Describe proposed or composed we or recompletion.  1. Drill 7 7/8" hole to 9807' 2. Run 5-1/2" 17#/ft, J-55 & 1 3. Cement with 500 sx Super 4. Bump plug @ 3:15 PM 8-0 5. Top of cement @ 7768'-Bo 6. Nipple down BOP & cut of	oleted operations. (Clear ork). SEE RULE 1103. N-80, LT&C, New API H w/35 bbls Super Flush 12-05-Held OK. ond Log measurement	ly state all pertinent details, and For Multiple Completions: Attacasing to 9807'	give pertinent dates, including estimated dat	
OTHER:  13. Describe proposed or composed we or recompletion.  1. Drill 7 7/8" hole to 9807' 2. Run 5-1/2" 17#/ft, J-55 & 1 3. Cement with 500 sx Super 4. Bump plug @ 3:15 PM 8-0 5. Top of cement @ 7768'-Bo 6. Nipple down BOP & cut of 7. Release drilling rig.	oleted operations. (Clear ork). SEE RULE 1103.  N-80, LT&C, New API of the W/35 bbls Super Flush (2-05-Held OK.)  ond Log measurement of 5½" casing	ly state all pertinent details, and For Multiple Completions: Attacasing to 9807' a prior to cement	give pertinent dates, including estimated dat ach wellbore diagram of proposed completion	
OTHER:  13. Describe proposed or composed we or recompletion.  1. Drill 7 7/8" hole to 9807' 2. Run 5-1/2" 17#/ft, J-55 & 1 3. Cement with 500 sx Super 4. Bump plug @ 3:15 PM 8-0 5. Top of cement @ 7768'-Bo 6. Nipple down BOP & cut of 7. Release drilling rig.	oleted operations. (Clear ork). SEE RULE 1103.  N-80, LT&C, New API of the W/35 bbls Super Flush (2-05-Held OK.)  ond Log measurement of 5½" casing	ly state all pertinent details, and For Multiple Completions: Attacasing to 9807' a prior to cement	give pertinent dates, including estimated dat	
OTHER:  13. Describe proposed or composed we or recompletion.  1. Drill 7 7/8" hole to 9807' 2. Run 5-1/2" 17#/ft, J-55 & 1 3. Cement with 500 sx Super 4. Bump plug @ 3:15 PM 8-0 5. Top of cement @ 7768'-Bo 6. Nipple down BOP & cut of 7. Release drilling rig.	oleted operations. (Clear ork). SEE RULE 1103.  N-80, LT&C, New API of the W/35 bbls Super Flush (2-05-Held OK.)  ond Log measurement of 5½" casing	ly state all pertinent details, and For Multiple Completions: Attacasing to 9807' a prior to cement	give pertinent dates, including estimated dat ach wellbore diagram of proposed completion	
OTHER:  13. Describe proposed or composed was or recompletion.  1. Drill 7 7/8" hole to 9807' 2. Run 5-1/2" 17#/ft, J-55 & 1 3. Cement with 500 sx Super 4. Bump plug @ 3:15 PM 8-0 5. Top of cement @ 7768'-Bo 6. Nipple down BOP & cut of 7. Release drilling rig.	oleted operations. (Clear ork). SEE RULE 1103. N-80, LT&C, New API H w/35 bbls Super Flush 2-05-Held OK. and Log measurement ff 5½" casing	ete to the best of my knowledge or guidelines \( \), a general permit \( \) o	give pertinent dates, including estimated dat ach wellbore diagram of proposed completion and belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan	
OTHER:  13. Describe proposed or composed was or recompletion.  1. Drill 7 7/8" hole to 9807' 2. Run 5-1/2" 17#/ft, J-55 & 1 3. Cement with 500 sx Super 4. Bump plug @ 3:15 PM 8-0 5. Top of cement @ 7768'-Bo 6. Nipple down BOP & cut of 7. Release drilling rig.	oleted operations. (Clear ork). SEE RULE 1103.  N-80, LT&C, New API of the W/35 bbls Super Flush (2-05-Held OK.)  ond Log measurement of 5½" casing	ete to the best of my knowledge of guidelines \( \mathbb{A}\), a general permit \( \mathbb{O}\) outlines details, and For Multiple Completions: Attack casing to 9807' in prior to cement	give pertinent dates, including estimated dat ach wellbore diagram of proposed completion and belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan	
OTHER:  13. Describe proposed or composed was or recompletion.  1. Drill 7 7/8" hole to 9807' 2. Run 5-1/2" 17#/ft, J-55 & 1 3. Cement with 500 sx Super 4. Bump plug @ 3:15 PM 8-0 5. Top of cement @ 7768'-Bo 6. Nipple down BOP & cut of 7. Release drilling rig.	oleted operations. (Clear ork). SEE RULE 1103. N-80, LT&C, New API H w/35 bbls Super Flush 2-05-Held OK. and Log measurement ff 5½" casing	ete to the best of my knowledge guidelines \( \), a general permit \( \) o TITLE \( \) Agent \( \) jwmulloy@jwmulloyassoc.com	give pertinent dates, including estimated dat ach wellbore diagram of proposed completion and belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan  DATE 8-18-05  m Telephone No. 432-687-0323	
OTHER:  13. Describe proposed or composed was or recompletion.  1. Drill 7 7/8" hole to 9807' 2. Run 5-1/2" 17#/ft, J-55 & 1 3. Cement with 500 sx Super 4. Bump plug @ 3:15 PM 8-0 5. Top of cement @ 7768'-Bo 6. Nipple down BOP & cut of 7. Release drilling rig.	oleted operations. (Clear ork). SEE RULE 1103. N-80, LT&C, New API H w/35 bbls Super Flush 2-05-Held OK. and Log measurement ff 5½" casing	ete to the best of my knowledge guidelines \( \), a general permit \( \) o TITLE \( \) Agent \( \) jwmulloy@jwmulloyassoc.com	give pertinent dates, including estimated dat ach wellbore diagram of proposed completion and belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan	