Form 3160-5 (November 1983) (Formerly 9-331)

UNITED STATES

N.M. Oil Cons. Division

DEPARTMENT OF THE INTERIOR OF

Budget Bureau No. 1004-0135 Expires August 31, 1985

BUREAL	U OF LAND MANAGEMENT IC			
			5. LEASE DESIGNATION AND SERIAL NO. LC-059576	
SUNDRY NOTICES AND REPORTS ON WELLS			6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.			o. Il INDIAN, ALLOTTEE OR TRI	BE NAME
Use "APPL	ICATION FOR PERMIT - " for such propos	a omereni reservoir. sals.)		
1.			7. UNIT AGREEMENT NAME	
OIL GAS OTHER WIW			Maljamar Grayburg Unit	
			Winding Chayburg Ch	ш
2. NAME OF OPERATOR			8. WELL NAME AND NO.	
The Wiser Oil Company			10	
3. ADDRESS OF OPERATOR			9. API WELL NO.	
P.O. Box 2568 Hobbs, New Mexico 88241			30-025-00449	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.			10. FIELD AND POOL, OR WILDCAT	
See also space 17 below.) At surface			Maljamar Grayburg San Andres	
660' FSL & 660' FWL			11. SEC., T., R., M., OR BLK. AND	
Unit M			SURVEY OR AREA	
			Sec. 3-T17S-R32E	
14. PERMIT NO 15 FLEVATIONS (Show whether DE BT CD etc.)				
14. TERMIT NO	15. ELEVATIONS (Show whether DF, 1 4168'	RT, GR, etc.)	12. COUNTY OR PARISH	13. STATE
01:1			Lea County	NM
16. Check	Appropriate Box to indicate Natur	re of Notice, Report, or Othe	r Data	
NOTICE OF INTENTION TO:			OGEOLIENE BERORE OF	
30B			BSEQUENT REPORT OF:	
TEST WATER SHUT OFF	PULL OR ALTER CASING	WATER SHUT-OFF	DED ADD TO THE T	
├		WAILK SHOT-OFF	REPAIRING WELL	
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING	1 1
SHOOT OR ACIDIZE	AD ANDONE			
	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT *	
REPAIR WELL	CHANGE PLANS	(Other) Temporary Abandon		
(Note: Report results of			fmultiple completion on Well	المسيدها
(Other) Completion or Recomp			pletion Report and Log form.)	
17. DESCRIBE PROPOSED OR COMPLET	TED OPERATIONS: (Clearly state all pertin	nent details, and give pertinent dates,	including estimated date of starting any	
proposed work. If well is directionally dr	rilled, give subsurface locations and measure	d and true vertical depths for all mar	kers and zones pertinent to this work.)	
11/26/02 MIRU Bunice Well Service. ND WH.	RU BOP. Unset 5-1/2" perma-latch pkr. POH w/2-	-3/8" IPC tbg. LD pkr. RIH w/5-1/2" CIBI	on 2-3/8" IPC the to 3850'. Set CTBP. Test of	so to 500# Held
Circulate 115 bbls. pkr. fluid. Ran MIT 500# for 30 min. (Copy of pressure chart attached, original to NMOCD). Performed/witnessed by Nick Jimenez with Gandy Corporation. POH & LD 125 jts.				
2-3/8" IPC tbg. RD BOP. NU WH w/	l jt. 2-3/8" tbg., valve & gauge. RDMO. Well is TA	A'D.	,	
		ACCEPTE	0A 252	625
ACCEPTED FOR RECORD 222324 252627				2583
The same of the sa				* 07.833\
	1/3 1	, - 0)		
This Approval	5 2003 (3 7 📆			
Abandonment Exp	8 4			
CARLSBAD, NEW MEXICUTE POR CONTROL CON				
		CANLSBAU, N	EM WEXICOS	
			12	007/
			2/5/2110	168 L
18. I hereby certify that the foregoing is true as	nd correct.		EW MEXICO STATESTALLIO	
SIGNED Many On THERE	TITLE Producti	on Tech II		
5.6.122	IIILE Floqued	on rech ii	DATE December 22, 2002	-
(This space for Federal og State office use)	. ^		MAV A 1 2002	
MAY U 1 2003				
APPROVED BY Hay W. C	MLE HELD REPRESE	ENTATIVE II/STAFF MANA	DAFE	
CONDITIONS OF APPROVAL, IF ANY:	-			
V				

*See Instruction On Reverse Side

