· · ·						
Submit 3 Copies To Appropriate District Office	State of New Mexico				Form C-103	
District I	Energy, Minerals and Natural Resources				Revised March 25, 1999	
1625 N. French Dr., Hobbs, NM 88240 District II				WELL API NO.	V1 10000	
811 South First, Artesia, NM 88210	a, NM 88210 OIL CONSERVATION DIVISION			5. Indicate Type	041-10209	
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.			STATE		
District IV	Santa Fe, NM 87505				Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505				E-10	1	
SUNDRY NOTICES AND REPORTS ON WELLS					r Unit Agreement Name:	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well:						
Oil Well Gas Well Other WIW -				Todd Lwr SA Unit Sec. 36		
2. Name of Operator				8. Well No.		
Saga Petroleum, LLC. 3. Address of Operator				9. Pool name or Wildcat		
415 W. Wall - Suite 1900 - Midland, TX 79701				Todd Lower SA Assoc.		
4. Well Location				1044 10401		
Unit LetterJ:	2110 feet from the	South	$\_$ line and $\_19$	980 feet from	m the <u>East</u> line	
Section 36	Township 7	<b>1</b> 0 <b>1</b> 0	ange 35E	NMPM	County Roosevelt	
Section         36         Township         7S         Range         35E         NMPM         County         Roosevelt           10.         Elevation (Show whether DR, RKB, RT, GR, etc.)         100						
4158' GR						
11. Check A	ppropriate Box to In	dicate N	ature of Notice, F	Report or Other	Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:						
PERFORM REMEDIAL WORK PLUG AND ABANDON						
				LING OPNS. 🔲		
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST AND roved as to plugging of the Well Bore. CEMENT JOB Liability under bond is retained until			
OTHER:			OTHER:	face restoration is	completed.	
	d appretions (Clearly at		I	va nartinant datas	including estimated date	
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion						
or recompilation.						
4-5-7-2003 - Moved inand rigged up pulling unit and plugging equipment. Nippled down						
wellhead and nippled up BOP. Rigged up tubing equipment and floor. Rigged up wireline.						
RIH with wireline set CIBP and set CIBP at 4230'. POOH and rigged down wireline. Shut						
well in for weekend. 4-8-2003 - RIH open ended to 4230'. Circulated hole with plugging mud. Capped ABP with						
5 sacks of Class C Neat cement from 4230-4158'. Pulled up hole to 2008. Spotted 25						
sacks Class C Neat cement from 2038-1676'. POOH. Shut well in Ar night						
4-9-2003 - Rigged down tubing equipment. Nippled down BOP and we'llhead Rigged up 4-1/2"						
pull sub. Frepointed 4-1/2" casing - shows not to be free. Rigged down pull sub. Nippled						
up wellhead and BOP. Rigged up tubing equipment. Rigged up witeline. Rigboand perforated 4-1/2" casing at 1000'. POOH & rigged down wireline. RIH with pecker and bubing and						
set packer at 677'. Pressured up to 1500 psi. POOH with packer. BIH open ended to 1063'.						
Spotted 25 sacks Class	Spotted 25 sacks Class C Neat cement from 1063-701'. POOH. WOC. Ship, well, for night.					
4-10-2003 - RIH with t	ubing - did not t	ag. Sj	potted 25 sacks	s Class C Neat	cement from	
1063-701'. POOH. WOC						
I hereby certify that the information above is true and complete to the best of my knowledge and belief. CONTINUED ON NEXT PAGE:						
SIGNATURE Kuster Tu	$\sim$	TITLE	Agent for BCM	1 & Assoc.	DATE <u>April 18</u> , 2003	
Type or print name Rusty Kle	in			Telent	10ne No. 505-748-2159	
(This space for State use)	<u>^</u>					
c/ I	11°h -	-	EPRESENTATIVE IVS	STAFF MANAGER	MAY 0 1 2003	
APPPROVED BY Kay W.	Umb 🧖	rnfift <sup>y R</sup>	ČLKČOHA MULTE IMA		DATE	

SAGA PETROLEUM, LLC. Todd Lwr SA Unit Sec. 36 #10 Section 36-T7S-R35E Roosevelt County, New Mexico

SUNDRY NOTICE CONTINUED:

tubing. Rigged up wireline. RIH and perforated 4-1/2" casing at 354'. POOH & rigged down wireline. Shut well in for night.
4-11-2003 - Squeezed with 45 sacks Class C Neat cement from 354-254' at 1000 psi. WOC 4 hours. Rigged up wireline. RIH and tagged cement at 236'. POOH & rigged down wireline.
POOH with packer and tubing. Rigged down tubing equipment. Nippled downBOP. RIH with tubing to 60'. Circulated 5 sacks Class C Neat cement from 60' to surface. POOH. Shut well in for night.
4-12-2003 - Hole stayed full. Rigged down pulling unit and plugging equipment. Cleaned location. Installed regulation abandonment marker. PLUCCED AND ABANDONED - FINAL REPORT.

location. Installed regulation abandonment marker. <u>PLUGGED AND ABANDONED - FINAL REPORT.</u> Plugging completed April 11, 2003.

Rusty Kl/din Agent for BCM & Associates April 18, 2003

Approved as to plugging of the Well Bore. Liability under bond is retained until surface restoration is completed.