

District I  
1625 N. French Dr., Hobbs, NM 87240  
District II  
811 South First, Artesia, NM 87210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

AMENDED

Form C-103  
Revised March 25, 1999

OIL CONSERVATION DIVISION  
2040 South Pacheco  
Santa Fe, NM 87505

WELL API NO.	30-025-11716
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	

<p><b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)</p> <p>( PAGE 1 of 2 )</p> <p>1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other</p>		7. Lease Name or Unit Agreement Name WIMBERLY, WN
2. Name of Operator HENRY PETROLEUM LP	8. Well No. 1	
3. Address of Operator 3525 ANDREWS HIGHWAY - SUITE 200 MIDLAND TX 79703-5000	9. Pool name or Wildcat JAMAT-TAN-YATES-7 RIVER (GAS)	
4. Well Location		
Unit Letter F 1980 feet from the NORTH line and 1980 feet from the WEST line		
Section 23 Township 25-S Range 37-E NMPM LEA County NEW MEXICO		
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3090' GR		

<p>11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data</p> <p><b>NOTICE OF INTENTION TO:</b></p> <p>PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/></p> <p>TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/></p> <p>PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/></p> <p>OTHER: <input type="checkbox"/></p>		<p><b>SUBSEQUENT REPORT OF:</b></p> <p>REMEDIAL WORK <input checked="" type="checkbox"/> ALTERING CASING <input type="checkbox"/></p> <p>COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/></p> <p>CASING TEST AND CEMENT JOBS <input type="checkbox"/></p> <p>OTHER: T.A. WELL <input checked="" type="checkbox"/></p>
--	--	---

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work). SEE RULE 1103. For Multiple Completions: Attach diagram of proposed completion or recompletion.

02/14/03: RE-ACTIVATE GAS WELL - MIRU PU - RAN 8-3/4" BIT & DRILL COLLARS - SDFN.  
02/17/03: TRIP IN HOLE & FOUND CEMENT AT 2875' - DRILLED CEMENT & CIBP AT 2890 - CIRC. HOLE.  
02/18/03: DRILLED ON CIBP AND PUSHED TO 3427' - CIRC. HOLE CLEAN - POOH - TRIP IN W/BIT & SCRAPER TO 2200' - SDON.  
02/19/03: TRIP IN HOLE TO PBTD 3427' - RAN LOG 3427' TO 2400' - SET PACKER AT 3422' - PRESSURE TO 500# FOR 10" - HELD OK - RELEASED PACKER & PULL UP TO 3000' - SET PKR. & PRESSURE UP ON 9-5/8" CASING FROM 3427' - 3000' TESTING OLD 7 RIVERS QUEEN SQUEEZED PERFS TO 500# - HELD OK - POOH WITH PACKER.  
02/20/03: PERFS. 9-5/8" CASING 3048' TO 3332' TOTAL OF 45 HOLES - TIH & SET RBP AT 3370' - SET PACKER AT 3360' - TEST RBP W/500# - OK - PULL PACKER UP TO 3268' - SET PACKER - PUMP 2000 GALS 15% NEFE - RELEASED RBP - SET AT 3272'.  
02/21/03: SET PACKER AT 3144' - PUMP 2000 GALS 15% ACID - RELEASED PKR. & RBP - SET RBP AT 3155' & PACKER AT 3033' - PUMP 2000 GALS 15% - MOVE RBP DOWN TO 3370' & SET PACKER AT 3033' - SDON 2003  
02/22/03: SWAB DRY - SDON.  
02/23/03: SHUT IN.  
02/24/03: SWAB DRY - SDON.

( CONTINUE ON PAGE 2 )

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

*Roy R. Johnson*

TITLE REGULATORY TECH.

DATE 03/11/2003

Type or print name ROY R. JOHNSON

Telephone No. (915)694-3000

(This space for State Official SIGNED BY

GARY W. WINK

APPROVED BY OC FIELD REPRESENTATIVE II/STAFF MANAGER

DATE MAR 13 2003

Conditions of approval, if any: