

Submit 3 Copies To Appropriate District

Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 87210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico.
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

WELL API NO.

30-025-09830

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

B934

7. Lease Name or Unit Agreement Name:

Humble State

8. Well No.

2

9. Pool name or Wildcat

Jalmat

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Southwest Royalties, Inc.

3. Address of Operator

P.O. Box 11390 Midland Tx 79702

4. Well Location

Unit Letter H : 1980 feet from the North line and 660 feet from the East line

Section 36 Township 25S Range 36E NMPM den County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

NA

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. MIREU WL. Set CIBP@ 2955'. Capped w/ 35' cut 11/08/02 witnessed by Bud, 11/11 Hobbs NMCD).

2. MIREU plugging Contractors T14 & load csg w/ mud.

3. Perforate 7" csg @ 1400'. Squeeze w/ 25sx cut. Spot 35 sx inside csg. -TAG

4. Perforate 7" csg @ 475'. Squeeze w/ 35 sx cut. Spot 50 sx inside csg. -TAG

5. Spot 50 sx cut dr ± 150' to 3' below surface.

6. Cut of WHG. Install P&A marker. Restore location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

[Signature]

TITLE

Area Supv.

DATE

05/20/03

Type or print name

C.M. Bloodworth

Telephone No.

932-686-9927

(This space for State use)

10C FIELD REPRESENTATIVE II/STAFF MANAGER

APPROVED BY

[Signature]

TITLE

DATE

MAY 22 2003

Conditions of approval, if any:

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

SOUTHWEST ROYALTIES

PROJECT Humble State No 2
Jalmat Field

PAGE 1 OF 1
BY WJB DATE 9/18/02

