

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

FILE IN TRIPLICATE

**OIL CONSERVATION DIVISION**

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

2040 Pacheco St.  
Santa Fe, NM 87505

DISTRICT II  
811 S. 1st Street, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd, Aztec, NM 87410

WELL API NO.	30-025-23007
5. Indicate Type of Lease	FED <input type="checkbox"/> STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	NORTH HOBBS (G/SA) UNIT
8. Well No.	121
9. Pool name or Wildcat	HOBBS (G/SA)
Section 32	
10. Elevation (Show whether DF, RKB, RT GR, etc.) 3635' GL	

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101 FOR SUCH PROPOSALS.)

1. Type of Well:	Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>
2. Name of Operator	Occidental Permian Ltd.
3. Address of Operator	1017 W. Stanolind Rd., HOBBS, NM 88240 505/397-8200
4. Well Location	Unit Letter <u>E</u> : <u>1730</u> Feet From The <u>NORTH</u> Line and <u>330</u> Feet From The <u>WEST</u> Line Section <u>32</u> Township <u>18S</u> Range <u>38E</u> NMPM LEA County
10. Elevation (Show whether DF, RKB, RT GR, etc.) 3635' GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG & ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <u>Open Grayburg Zone</u>	<input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)  
SEE RULE 1103.

1. RUPU. Pull production equipment.
2. Spot sand from CIBP @4060' to 3960'.
3. Stimulate new perms 1000 g 15% NEFE HCL acid.
4. Frac w/40,000# sand.
5. Clean out sand to PBTD @4057'.
6. RIH w/5.5" Guiberson UNI VI pkr and set pkr @3858'.
7. Bottom of tbg @3858'.
8. Circ csg w/pkr fluid.
9. Test csg to 540 psi for 30 min and chart for the NMOCD.
10. RDPU. Clean Location.




Rig Up Date: 04/30/2003  
Rig Down Date: 05/08/2003

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE	<u>Robert Gilbert</u>	TITLE	<u>SR. ENGR TECH</u>	DATE	<u>05/09/2003</u>
TYPE OR PRINT NAME	<u>ROBERT GILBERT</u>	TELEPHONE NO.	<u>505/397-8206</u>		

(This space for State Use)

APPROVED BY	<u>Gayle W. Wink</u>	TITLE	<u>OC FIELD REPRESENTATIVE II / STAFF MANAGER</u>	DATE	<u>MAY 22 2003</u>
CONDITIONS OF APPROVAL IF ANY:					



Exp Permian  
NHU 32-121

R. G. Gilbert

GRAPHIC CONTROLS CORPORATION  
BUFFALO, NEW YORK

11277  
Oxy (NHU 32-121)  
Paul Boser  
S. E. C. 3

Nacklesky  
BR 2221