

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

SUNDY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	WELL API NO. 30-025-30201
2. Name of Operator Jetta Operating Co., Inc.	5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
3. Address of Operator 777 Taylor St., Suite P1-D Fort Worth, TX 76102	6. State Oil & Gas Lease No.
4. Well Location Unit Letter <u>W</u> : <u>660</u> feet from the <u>South</u> line and <u>1980</u> feet from the <u>East</u> line Section <u>5</u> Township <u>16S</u> Range <u>34E</u> NMPM Lea County	7. Lease Name or Unit Agreement Name: Humble Hume 5 State
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 14.7' KB	

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: TEMPORARILY ABANDON ☒

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. MIRU
2. POOH laying down pump and rods.
3. POOH with tubing
4. Set CIBP @ 4940', dump 10' cement.
5. Pressure test casing to 500#
6. TIH with tubing, circ inhibited KCL
7. Secure well
8. RDMO
9. Performed Mechanical Integrity Test: see attached chart. Please place well on TA status for Engineering and Geology review.

This Approval of Temporary Abandonment Expires

5/28/08

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David Patterson TITLE Operations Manager DATE 5/21/03

Type or print name David Patterson Telephone No. (817) 335-1179

(This space for State use)

APPROVED BY Hayden Winkler FIELD REPRESENTATIVE II/STAFF MANAGER DATE MAY 28 2003

Conditions of approval, if any:

