

Submit 3 Copies To Appropriate District Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised March 25, 1999

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. <u>30-025-31529</u>
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: West Lovington Unit
8. Well No. #83
9. Pool name or Wildcat San Andres

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/> T&A SWD	
2. Name of Operator Pure Resources	
3. Address of Operator 500 W. Illinois Midland, Texas 79701	
4. Well Location  Unit Letter <u>J</u> : 2625' feet from the South line and 2625' feet from the East line  Section <u>5</u> Township <u>17S</u> Range <u>36E</u> NMPM <u>Lea</u> County	
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3819' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
<b>NOTICE OF INTENTION TO:</b> PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input checked="" type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/> OTHER: <input type="checkbox"/>	<b>SUBSEQUENT REPORT OF:</b> REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: <u>T &amp; A well</u> <input type="checkbox"/>


12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

85/8 casing 24# set 1350' (cement circ. surf.)  
51/2 casing 15.5# set 5230' (cement circ. surf.)  
Perforations 4765'- 5112'  
CIBP set at 4726' Put 20' of cement on top CIBP

This Approval of Temporary  
Abandonment Expires

5/28/08

Had tubing stuck in hole and could not retrieve. Work over Date: May 13, 2003 thru May 20, 2003  
Well quit pumping pulled and shear tool parted. Pump stuck in SN. Could not pull tubing, tubing stuck, ran free point and tubing stuck below anchor catcher. Shot tubing off with 9 joints, SN, and mud anchor. Could not get all the tubing out of well. Temporarily Abandon well.  
Post work over mechanical integrity test was not witnessed by NMOCD.  
Starting Pressure: 600 P.S.I.  
Final Pressure: 600 P.S.I.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mike Northcutt TITLE Production Foreman DATE 5-22-03

Type or print name Mike Northcutt Telephone No. 505-396 7503  
(This space for State use)

APPROVED BY Larry W. Wink TITLE REPRESENTATIVE II/STAFF MANAGER DATE MAY 28 2003  
Conditions of approval, if any

