

Submit 3 Copies To Appropriate District Office

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

WELL API NO.

30-025-31529

5. Indicate Type of Lease

STATE ☐ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name:

West Lovington Unit

8. Well No.

#83

9. Pool name or Wildcat

San Andres

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☐ Other ☐ T&A SWD

2. Name of Operator

Pure Resources

3. Address of Operator

500 W. Illinois Midland, Texas 79701

4. Well Location

Unit Letter J: 2625' feet from the South line and 2625' feet from the East line

Section

5

Township 17S

Range 36E

NMPM

Lea

County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

3819' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☒ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: T & A well ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

85/8 casing 24# set 1350' (cement circ. surf.)
51/2 casing 15.5# set 5230' (cement circ. surf.)
Perforations 4765' - 5112'
CIBP set at 4726' Put 20' of cement on top CIBP

This Approval of Temporary
Abandonment Expires 5/28/08

Had tubing stuck in hole and could not retrieve. Work over Date: May 13, 2003 thru May 20, 2003

Well quit pumping pulled and shear tool parted. Pump stuck in SN. Could not pull tubing, tubing stuck, ran free point and tubing stuck below anchor catcher. Shot tubing off with 9 joints, SN, and mud anchor. Could not get all the tubing out of well. Temporarily Abandon well.

Post work over mechanical integrity test was not witnessed by NMOCD.

Starting Pressure: 600 P.S.I.

Final Pressure: 600 P.S.I.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mike Northcutt TITLE Production Foreman DATE 5-22-03

Type or print name Mike Northcutt

Telephone No. 505-396 7503

(This space for State use)

APPROVED BY

Conditions of approval, if any:

ORIGINAL SIGNED BY

GARY W. WINKLE

OC FIELD REPRESENTATIVE II/STAFF MANAGER

DATE

MAY 28 2003

