
Submit 3 Copies To Appropriate District Office District I	State of New Mexico Energy, Minerals and Natural Resources		Form C-103 Revised March 25, 1999	
1625 N. French Dr., Hobbs, NM 87240				
<u>District II</u> 811 South First, Artesia, NM 87210	OIL CONSERVATION DIVISION		5. Indicate Type	30-025-30345
District III 1000 Rio Brazos Rd., Aztec, NM 87410	2040 South Pacheco		STATE C	
District IV 2040 South Pacheco, Santa Fe, NM 87505	Santa Fe, NI	M 87505	6. State Oil & C	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well Gas Well OtherWIW			B-9613 7. Lease Name or Unit Agreement Name WEST DOLLARHIDE QUEEN UNIT Agreement 8910084910	
2. Name of Operator SAGA PETROLEUM LLC			8. Well No. 136	5
3. Address of Operator 415 W Wall, Suite 1900 Midland, TX 79701			Pool name or Wildcat Dollarhide Queen	
4. Well Location				
Unit Letter E : 1950 feet from the NORTH line and 350 feet from the WEST line				
Section 32	Township24S	Range 38E	NMPM	CountyLEA
	10. Elevation (Show whet Gr 3151' KB	ther DR, RKB, RT, GR, etc.)		
11. Check Ap	ppropriate Box to Indic	ate Nature of Notice,	Report or Other	Data
NOTICE OF IN	TENTION TO: PLUG AND ABANDON	SUE REMEDIAL WOR	SEQUENT RE	PORT OF: ALTERING CASING [
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DR	ILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING TEST A	ND	ABANDONWENT
OTHER:		☐ OTHER:HIT repa	air	
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work). SEE RULE 1103. For Multiple Completions: Attach diagram of proposed completion or recompletion. 5-23-03 Blow well dwn, pull tension on pkr, load csg, would not hold, unset 2-3/8" x 5-1/2" AD-1 pkr, POOH w/tbg 115 jts (3645') 2-3/8" 8rd EUE J55 IPC tbg, SN, 5-27-03 Basin Testers test tbg in hole 7000 psi below slips, 2 HIT's & bust 4 jts. Set pkr, test csg to 500 psi held for 10-mins. Unset pkr, circ pkr fluid, set 2-3/8" x 5-1/2" AD-1 pkr pkr - test csg to 500 psi, ran 30 min chart w/no press loss - chart attached 114 jts (3500) 2-3/8" 8rd EUE J55 IPC 13 4 5 6 7 8 9 7 0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				
I hereby certify that the information	n above is true and complet	e to the best of my knowle		Hobbs OCD
SIGNATURE GONNICE	Youshand_1	TITLE PROD ANALYST		DATE 06/03/2003
Type or print nameBONNIE HUSBAND Telephone No. (432)684-4293				
(This space for State use)				
APPROVED BY Conditions of approval, if any:	!Wank ∞ F	TILE.		



Vince Bereau (r.)

Larra 100 HTAG

PORT AND ON DESIGNATION