## State of New Mexico

Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

FEE [

ubnut 3 copies to Appropriate District Office

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1. Type of Well:

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe. New Mexico 87504-2088

WELL API NO

5. Indicate Type of Lease

30-025-32791

STATE 🗸

6. State Oil / Gas Lease No.

7. Lease Name or Unit Agreement Name CENTRAL VACUUM UNIT

197

**VACUUM GRAYBURG SAN ANDRES** 

B-1113-1

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI
(FORM C-101) FOR SLICH PROPOSALS

**OTHER** 

GAS WELL

2. Name of Operator CHEVRON USA INC

717

3. Address of Operator 15 SMITH ROAD, MIDLAND, TX 79705

4. Well Location

WELL

Feet From The NORTH Line and 1093

Range 35-E

NMPM

8. Well No.

10. Elevation (Show whether DF, RKB, RT,GR, etc.)

3982' GR

LEA COUNTY

Line

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

## SUBSEQUENT REPORT OF:

9. Pool Name or Wildcat

Feet From The WEST

PERFORM REMEDIAL WORK

**TEMPORARILY ABANDON** 

Unit Letter

Section 6

PLUG AND ABANDON

Township 18-S

REMEDIAL WORK CHANGE PLANS

COMMENCE DRILLING OPERATION

PLUG AND ABANDONMENT

ALTERING CASING

**PULL OR ALTER CASING** CASING TEST AND CEMENT JOB OTHER:

OTHER:

TBG STUCK - ACIDIZE

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-09-03: TRIED TO REL TAC - NO LUCK. TIH W/FREE POINT. TBG STUCK @ 4540'. TIH W/CHEMICAL CUTTER & CUT TBG @ 4233'.

4-10-03: TIH W/GRAPPEL, BMPR SUB, JARS & 2 7/8" TBG. TAG & CAUGHT FSH @ 4256. STARTED JARRING. TURNED LOOSE & TOH W/WS TO 3962'.

4-11-03: TIH W/BIT & PU TBG TO 4187'.

4-14-03: LOWER BIT TO TOW @ 4250. PMP 280 BBLS FW & BROKE CIRC. LOWER BIT TO 4546 & TAGGED, C/O TO 4720.

4-15-03: TIH W/PKR, SN & TBG. SET PKR @ 4192. TP @ 4699. PMP 100 GALS CONVERTER ACR OPENHOLE FR 4720-4260. FLUSH W/20 BBLS FW. SET PKR @ 3918. TP @ 4412. LOAD & TEST PKR TO 500 PSI.

4-16-03: ACIDIZE OPENHOLE FR 4260-4720' W/4000 GALS NEFE & 3000# ROCK SALT. RU SWAB.

4-17-03: CHEMICAL SQUEEZE. FLUSH W/20 BFW. PUMP 24 BFW W/220 GALS TH-793. PUMP 400 BFW W/4 1/2 GALS 603 & 30 GALS ALFA 160 &10 GALS 7W4273 MIXED.

4-18-03: REL PKR @ 3917. LOWER TO 4700. NO FILL. TIH W/DMP VALVE, XO SUB, SN, TBG, & TAC. SN @ 4586. TAC @ 4174. SET TAC W/12 POINTS.

4-21-03: TIH W/PMP & RDS.

4-22-03: HANG WELL ON, RU TO FLOWLINE, LOAD & TEST TBG TO 500 PSI8, RIG DOWN,

FINAL REPORT

e/lp the best of my knowledge and belief

TITLE

Regulatory Specialist

DATE

6/12/2003

TYPE OR PRINT NAME

Denise Leake

Telephone No.

915-687-7375

APPROVED S TITLE CONDITIONS OF APPROVAL, IF ANY:

OC FIELD REPRESENTATIVE II/STAFF MANAGE