

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised May 08, 2003

WELL API NO. 30-025-22362
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name E K QUEEN UNIT
8. Well Number 007
9. OGRID Number 012627
10. Pool name or Wildcat E-K QUEEN EAST (20330)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	
2. Name of Operator KEVIN O. BUTLER & ASSOCIATES, INC.	
3. Address of Operator P. O. BOX 1171, MIDLAND, TX 79702	
4. Well Location Unit Letter <u>G</u> : <u>2310</u> feet from the <u>NORTH</u> line and <u>1980</u> feet from the <u>EAST</u> line Section <u>22</u> Township <u>18-S</u> Range <u>34-E</u> NMPM County <u>LEA</u>	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

PLUG & ABANDON WELL

SEE ATTACHED

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE PRESIDENT DATE 6/20/03

Type or print name KEVIN O. BUTLER Telephone No. (432) 682-1178
(This space for State use) OCC FIELD REPRESENTATIVE II/STAFF MANAGER

APPROVED BY [Signature] TITLE [Signature] DATE JUN 24 2003
Conditions of approval, if any:

MAYO MARRS CASING PULLING INC.
BOX 863
KERMIT, TEXAS 79745

KEVIN O. BUTLER & ASSOCIATES

Lease: EAST E-K QUEEN UNIT # 7
Project: P & A – CEMENTING REPORT

03-20-2003 - RIH & SPOT 25 SXS @ 4450'-4085' TAGGED
03-20-2003 – SPOT 25 SXS @ 3141'-2766'
03-21-2003 – PERF @ 2370 – TEST TO 1000# - SPOT 25 SXS @ 2415'-2040'
03-21-2003 – PULLED 465' OF 4 ½" CASING
03-21-2003 - SPOT 50 SXS @ 515'-429' TAGGED
03-24-2003 - SPOT 35 SXS @ 429'-285' TAGGED
03-24-2003 - SPOT 20 SXS @ 60' TO SURFACE

INSTALL DRY HOLE MARKER
CIRCULATE 10# MUD