			*			
Submit 3 Copies To Appropriate District Office	State of New Mexico			Form C-103		
District 1	Energy, Minerals and Natural Resources			Revised March 25, 1999		
1625 N. French Dr., Hobbs, NM 88240 District II				WELL API NO.		
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION			30-025-32032 5. Indicate Type of Lease		
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.			STATE K		
District IV	Santa Fe, NM 87505			6. State Oil & Ga		
1220 S. St. Francis Dr., Santa Fe, NM 87505					220000 110.	
SUNDRY NOTION	CES AND REPORTS ON	WELLS	3	7. Lease Name or	I Init A greement	Nome
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				7. Lease Name or Unit Agreement Name:		
PROPOSALS.)	ATION FOR PERMIT (FOR	M C-101) F	OR SUCH	WTYSRU		
1. Type of Well:				WIISKU		1
Oil Well Gas Well X	Other					
2. Name of Operator Chesapeake Operating,	Tno		**	8. Well No.		
3. Address of Operator	Inc.			433		
	8496, Oklahoma City, OK 73154-0496			9. Pool name or Wildcat Teas; Yates-Seven Rivers, West		
4. Well Location	,			Teas; Tates-se	ven kivers,	West
	1650	0 (1				1
Unit Letter J :	1650 feet from the	South	line and	1980 feet from	the East	line
Section 4	Townshin		. 225			_
Cootion	Township 2	OS Ka	ange 33E	NMPM Lea	County	
	GL: 355		N, NND, KI, GK, eK			
11. Check A	ppropriate Box to Inc	dicate N	ature of Notice	Report or Other F)ata	
NOTICE OF IN	TENTION TO:			SEQUENT REP		
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WOR		ALTERING CASIN	VG []
TEMPORARILY ABANDON	CHANCE DI ALIO	_			2 0	10 LJ
IEMPOKAKITA ARAMDON []	CHANGE PLANS		COMMENCE DRI		PLUG AND	
PULL OR ALTER CASING	MULTIPLE	Δ	CASING TEST AN	ND [f	ABANDONMENT	
	COMPLETION		CEMENT JOB			
OTHER:			OTHER: Conve	rt To WIW		-
12. Describe proposed or completed	operations. (Clearly stat	e all perti	inent details and air	Ve portinent deter in	1	
butting any proposed work). SE	E RULE 1103. For Mult	iple Com	pletions: Attach we	ellbore diagram of pro	nuding estimated	date of
recompnation.				•	=	
05/01/03 Clean out we	II to 3260', RU fo	oam uni	it, circ 2 hrs	, well clean we	≥11, RD foam	L
machine, POOH, PU bust hole in tbg,	POOH ID the had	0 3200'	', test csg to	500#, OK, go ι	up to 750#,	
05/02/03 PU 5-1/2" pk	r. 99 2-3/8" n1:	nole i astic c	coating tubing	, SUFN	Dlen florid	
attempt to set pkr	@3165', no succe	ss. had	l to set okr @	3136', test CP	to 450# on	
chart for 30 min.,	held OK, had OCD	man on	location whi	le running rest	L. RD. tie	
Cudd on tbg, pump	24 bbls NE-Fe acid	d w/60	BPW @2-1/2" B	PM @1100#, when	SD went on	
vacuum, RDMO well.				•		
				/	4567897077	
				(2 ³	· .	
					000	(A)
				31.	Hopps	छ
				293037	אַכּייִבּיאַאַ	167
hombroneis de de la companya de la c				03	6002 NAC	7/2
hereby certify that the information a	bove is true and complete	to the be	est of my knowledge	and belief.		<u> </u>
SIGNATURE Barbara 9/	Kale	TTLE	Regulatory An	alvst	€ ₀ _ \ _\(\(\delta\)	55 /
	,	IILE	noguratory All	ury oc I	DATE 06/18/	03
Type or print name Barbara J	• Bale			Telephor	ne No. (405)	848-2001
This space for State use)	N.		- FMRT	AFF MANAGER PHOT		
ADDDD OVED BY	1 1 1 1 m =============================	ELD REPR	ESENTATIVE 11/ST	•	JUN 2	4 2003
APPPROVED BY Jan Conditions of approval, if any	J. Wing or T	ITLE		D	DATE	
~ approvat, it any;						

*

