Form 3160-5 (August 1999)

New Mexico Oil Conservation Division, District Aproved

, 2000

DEPARTMENT OF THE INTERIOR	1625 N. Frenc	nh Bhriu	ൂം OMB NO. 1004-0135	Š
BUREAU OF LAND MANAGEMENT			EXPIRES: NOVEMBER 30),
SUNDRY NOTICES AND REPORTS ON WELLS	Hobbs, NM	88248	Lease Serial No.	_
o not use this form for proposals to drill or to re-enter an		1	NM-96249	

Do not use this form abandoned well. Use	NM-96249 6. If Indian, Allottee or Tribe Name			
SUI	BMIT IN TRIPLICATE			
1a. Type of Well 📝 Oil Well 🔲 Gas	7. Unit or CA Agreement Name and No.).		
2. Name of Operator	PATION		Kukui 31 #1	
DEVON LOUISIANA CORPOR	RATION		9. API Well No.	
Address and Telephone No.			30-025-35861	
20 North Broadway, Ste 1500			10. Field and Pool, or Exploratory	ŀ
4. Location of Well (Report location clearly	Morton Morrow			
1290 FNL 1980 FEL B- Se	ec 31 T14S R35E		12. County or Parish 13. State	
CHECK A	PPROPRIATE BOX(s) TO IND	DICATE NATURE OF NOTICE,	REPORT OR OTHER DATA	
TYPE OS SUBMISSION			FACTION	
Notice of Intent	Acidize	☐ Deepen ☐	Production (Start/Resume) Water Shut-O	ff
	Alter Casing	Fracture Treat	Reclamation Well Integrity	·
✓ Subsequent Report	Casing Repair	New Construction	Recomplete Other	
Final Abandonment Notice	Change Plans	Plug and Abandon	Temporarily Abandon	
13. Describe Proposed or Completed Operations (Cle	Convert to Injection and state all pertinent details, and give p	Plug Back	Water Disposal of starting any proposed work and approximate duration thereof.	f the proposal
the Bond No. on file with BLM/BIA. Required subsequen	surface location and measured and true it reports shall be filed within 30 days foll	e vertical depths of all pertinent markers a flowing completion of the involved operati	and zones. Attach the Bond under which the work will be performe tions. If the operation results in a multiple completion or recompleti ent, including reclamation, have been completed, and the operator	d or provide
3. Spot 30 sx cement plug at 8,970 4. Cut 5-1/2" casing at 6,323' and 5. Spot 70 sx cement plug at 6,373 6. Spot 30 sx cement plug at 3,326 7. Spot 40 sx cement plug at 507'. 8. Spot cement plug from 60' to s 9. Well plugged and abandoned of	POOH laying down casing!. WOC. Tagged TOC 81. WOC. Tagged TOC at surface. RDMO. n 8/25/05.	ing. at 6,170'. Covers 8-5/8"		616 1031 1131
14. Thereby certify that the foregoing is tru	,			
Signed Kymne Sack	Name Title	Ronnie Slack Engineering Technicia	an Date 8/29/2005	
(This space for Federal or State Office use)				
Approved by	Title		Date	
Conditions of approval, if any:	,,,,,		Date	
THE TO U.S.C. SECTION TOUT HISKES IT A LIMB FOR ADVISE	NOT BUT INSTITUTE AND WORKEN			



its jurisdiction.

