Submit I Copy To Appropriate District Office	State of New Mexico	Form C-103
District I – (575) 393-6161	Energy, Minerals and Natural Resources	Revised August 1, 2011
1625 N. French Dr., Hobbs, NOBBS OCI		WELL API NO.
District II – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	30-025-32766 5. Indicate Type of Lease
District III – (505) 334-6178 10 V 3 0 201	2 1220 South St. Francis Dr.	STATE S FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	,	0. 5.4.6 54.5 24.55
87505 RECEIVED	ES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSA DIFFERENT RESERVOIR. USE "APPLICA"	LS AND REPORTS ON WELLS LS TO DRILL OR TO DEEPEN OR PLUG BACK TO A TION FOR PERMIT" (FORM C-101) FOR SUCH	WEST DOLLARHIDE DRINKARD UNIT
PROPOSALS.) 1. Type of Well: Oil Well G	as Well Other	8. Well Number 109
2. Name of Operator CHEVRON U.S.A. INC.	/	9. OGRID Number 4323
3. Address of Operator 15 SMITH ROAD, MIDLAND TEX.	AS 79705	10. Pool name or Wildcat DOLLARHIDE, TUBB, DRINKARD
4. Well Location		
Unit Letter I: 1500	o feet from the SOUTH line and 525 for	eet from the EAST line
Section 32	Township 24-S Range 38-E	NMPM County LEA
	11. Elevation (Show whether DR, RKB, RT, GR, etc	
		116661 3 300
12. Check Ap	propriate Box to Indicate Nature of Notice,	Report or Other Data
NOTICE OF INT	ENTION TO: SHE	SEQUENT REPORT OF:
	PLUG AND ABANDON REMEDIAL WOR	
		ILLING OPNS. P AND A
	MULTIPLE COMPL CASING/CEMEN	
DOWNHOLE COMMINGLE	_	
DOMINIONE COMMINIONE		
	OTUED OF EA	LOUT & AGIDIZE
OTHER:		N OUT & ACIDIZE
OTHER: 13. Describe proposed or complete	ted operations. (Clearly state all pertinent details, ar	nd give pertinent dates, including estimated date
OTHER: 13. Describe proposed or complet of starting any proposed work	ted operations. (Clearly state all pertinent details, are). SEE RULE 19.15.7.14 NMAC. For Multiple Co	nd give pertinent dates, including estimated date
OTHER: 13. Describe proposed or complete	ted operations. (Clearly state all pertinent details, are). SEE RULE 19.15.7.14 NMAC. For Multiple Co	nd give pertinent dates, including estimated date
OTHER: 13. Describe proposed or complet of starting any proposed work proposed completion or recon	ted operations. (Clearly state all pertinent details, are). SEE RULE 19.15.7.14 NMAC. For Multiple Co	nd give pertinent dates, including estimated date impletions: Attach wellbore diagram of
OTHER: 13. Describe proposed or complet of starting any proposed work proposed completion or reconsol 10/24/12. MIRU. 10/25/12. TOH W/PROD TBG. 10/27/12. CLEAN OUT	ted operations. (Clearly state all pertinent details, and the second state of the seco	nd give pertinent dates, including estimated date impletions: Attach wellbore diagram of OP. TOH W/PKR. 10/26/12. TOH W/2-7/8" CLEAN W/100 BBLS BRINE WTR.
OTHER: 13. Describe proposed or complet of starting any proposed work proposed completion or reconsolved. 10/24/12. MIRU. 10/25/12. TOH W/PROD TBG. 10/27/12. CLEAN OUT 10/31/12. CLEAN OUT F 6150' T 62	ted operations. (Clearly state all pertinent details, are). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. (RODS & PUMP. TIH W/PKR SET @ 25' TEST BOYS & 143' T 6240'. 10/29/12. CIRCULATE WELL 63'. 11/01/12. CLEAN OUT F 6263' T 6335'. 11/	nd give pertinent dates, including estimated date impletions: Attach wellbore diagram of OP. TOH W/PKR. 10/26/12. TOH W/2-7/8" CLEAN W/100 BBLS BRINE WTR. (02/12. CLEAN OUT F 6335' T 6446'
OTHER: 13. Describe proposed or complet of starting any proposed work proposed completion or reconsults. 10/24/12. MIRU. 10/25/12. TOH W/PROD TBG. 10/27/12. CLEAN OUT 10/31/12. CLEAN OUT F 6150' T 62 CIRCULATE WELL CLEAN W/100F	ted operations. (Clearly state all pertinent details, art). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. RODS & PUMP. TIH W/PKR SET @ 25' TEST BOY F 6143' T 6240'. 10/29/12. CIRCULATE WELL 63'. 11/01/12. CLEAN OUT F 6263' T 6335'. 11/03BBLS BRINE WTR. 11/05/12. CLEAN OUT F 64	od give pertinent dates, including estimated date empletions: Attach wellbore diagram of OP. TOH W/PKR. 10/26/12. TOH W/2-7/8" CLEAN W/100 BBLS BRINE WTR. (02/12. CLEAN OUT F 6335' T 6446' 46' T 6513'. 11/06/12. CLEAN OUT F 6513'
OTHER: 13. Describe proposed or complet of starting any proposed work proposed completion or reconsistance of the proposed completion of the proposed complete of the proposed or proposed work proposed complete or p	ted operations. (Clearly state all pertinent details, are). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. RODS & PUMP. TIH W/PKR SET @ 25' TEST BOY F 6143' T 6240'. 10/29/12. CIRCULATE WELL 63'. 11/01/12. CLEAN OUT F 6263' T 6335'. 11/03BLS BRINE WTR. 11/05/12. CLEAN OUT F 64 KR @ 6148' PUMP 44 BBLS SCALE CONVERTION.	od give pertinent dates, including estimated date empletions: Attach wellbore diagram of OP. TOH W/PKR. 10/26/12. TOH W/2-7/8" CLEAN W/100 BBLS BRINE WTR. 10/2/12. CLEAN OUT F 6335' T 6446' 46' T 6513'. 11/06/12. CLEAN OUT F 6513' ER. 11/09/12. ACIDIZE W/5600 GALS 15%
OTHER: 13. Describe proposed or complet of starting any proposed work proposed completion or reconsolution of the proposed completion or reconsolution of the proposed completion of the proposed complete proposed or complete proposed complete pro	red operations. (Clearly state all pertinent details, and some state of the state o	od give pertinent dates, including estimated date impletions: Attach wellbore diagram of OP. TOH W/PKR. 10/26/12. TOH W/2-7/8" CLEAN W/100 BBLS BRINE WTR. 10/2/12. CLEAN OUT F 6335' T 6446' 46' T 6513'. 11/06/12. CLEAN OUT F 6513' ER. 11/09/12. ACIDIZE W/5600 GALS 15% IUD TO KILL WELL. 11/12/12. TIH W/ PKR
OTHER: 13. Describe proposed or complet of starting any proposed work proposed completion or recon 10/24/12. MIRU. 10/25/12. TOH W/ PROD TBG. 10/27/12. CLEAN OUT 10/31/12. CLEAN OUT F 6150' T 62 CIRCULATE WELL CLEAN W/100H TO PBTD @ 6595'. 11/07/12. SET P NEFE HCL + 300 GALS PEP-39. 11 SET @ 6145'. PUMP 220 GALS BAK	red operations. (Clearly state all pertinent details, and the second state of the seco	od give pertinent dates, including estimated date impletions: Attach wellbore diagram of OP. TOH W/PKR. 10/26/12. TOH W/2-7/8" CLEAN W/100 BBLS BRINE WTR. 10/2/12. CLEAN OUT F 6335' T 6446' 46' T 6513'. 11/06/12. CLEAN OUT F 6513' ER. 11/09/12. ACIDIZE W/5600 GALS 15% IUD TO KILL WELL. 11/12/12. TIH W/ PKR USH W/445 BBLS BRINE WTR. 11/13/12.
OTHER: 13. Describe proposed or complet of starting any proposed work proposed completion or recon 10/24/12. MIRU. 10/25/12. TOH W/PROD TBG. 10/27/12. CLEAN OUT 10/31/12. CLEAN OUT F 6150' T 62 CIRCULATE WELL CLEAN W/100H TO PBTD @ 6595'. 11/07/12. SET PNEFE HCL + 300 GALS PEP-39. 11 SET @ 6145'. PUMP 220 GALS BAK CIRCULATED WELL 270 BBLS BR	red operations. (Clearly state all pertinent details, and some state of the state o	od give pertinent dates, including estimated date impletions: Attach wellbore diagram of open the wellb
OTHER: 13. Describe proposed or complet of starting any proposed work proposed completion or recon 10/24/12. MIRU. 10/25/12. TOH W/PROD TBG. 10/27/12. CLEAN OUT 10/31/12. CLEAN OUT F 6150' T 62 CIRCULATE WELL CLEAN W/100H TO PBTD @ 6595'. 11/07/12. SET PNEFE HCL + 300 GALS PEP-39. 11 SET @ 6145'. PUMP 220 GALS BAK CIRCULATED WELL 270 BBLS BR	red operations. (Clearly state all pertinent details, are). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. RODS & PUMP. TIH W/PKR SET @ 25' TEST BOOK 19.100. RODS & PUMP. TIH W/PKR SET @ 25' TEST BOOK 19.100. RODS & PUMP. TIH W/PKR SET @ 25' TEST BOOK 19.100. RODS & PUMP. TIH W/PKR SET @ 25' TEST BOOK 19.100. RODS & PUMP. TIH W/PKR SET @ 25' TEST BOOK 19.100. RODS & PUMP 10.100. RODS & PUMP 10.	od give pertinent dates, including estimated date impletions: Attach wellbore diagram of open the wellb
OTHER: 13. Describe proposed or complet of starting any proposed work proposed completion or reconsolution of the proposed completion or reconsolution of the proposed completion of the proposed complete proposed comple	red operations. (Clearly state all pertinent details, are). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. RODS & PUMP. TIH W/PKR SET @ 25' TEST BOOK 19.100. RODS & PUMP. TIH W/PKR SET @ 25' TEST BOOK 19.100. RODS & PUMP. TIH W/PKR SET @ 25' TEST BOOK 19.100. RODS & PUMP. TIH W/PKR SET @ 25' TEST BOOK 19.100. RODS & PUMP. TIH W/PKR SET @ 25' TEST BOOK 19.100. RODS & PUMP 10.100. RODS & PUMP 10.	od give pertinent dates, including estimated date impletions: Attach wellbore diagram of open the wellb
OTHER: 13. Describe proposed or complet of starting any proposed work proposed completion or reconsulation 10/24/12. MIRU. 10/25/12. TOH W/PROD TBG. 10/27/12. CLEAN OUT 10/31/12. CLEAN OUT F 6150' T 62 CIRCULATE WELL CLEAN W/100FTO PBTD @ 6595'. 11/07/12. SET PNEFE HCL + 300 GALS PEP-39. 11 SET @ 6145'. PUMP 220 GALS BAK CIRCULATED WELL 270 BBLS BR WELL CLEAN W/150 BBLS BRINE LOCATION.	ted operations. (Clearly state all pertinent details, are). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. (RODS & PUMP. TIH W/PKR SET @ 25' TEST BOYS 6143' T 6240'. 10/29/12. CIRCULATE WELL 63'. 11/01/12. CLEAN OUT F 6263' T 6335'. 11/03BLS BRINE WTR. 11/05/12. CLEAN OUT F 64 PKR @ 6148' PUMP 44 BBLS SCALE CONVERTOWN 10/12. TOH W/PKR PUMP 45 BBLS OF 14.5# MATERIAL SER 260 INHIBITER + 55 BBLS BRINE WTR. FLINE WTR. TOH W/PKR. 11/14/12. TIH W/2-7/8" WTR. TEST PROD TBG. 11/15/12. TIH W/ROD	od give pertinent dates, including estimated date impletions: Attach wellbore diagram of open the wellb
OTHER: 13. Describe proposed or complet of starting any proposed work proposed completion or reconsolution of the proposed completion or reconsolution of the proposed completion of the proposed complete proposed comple	red operations. (Clearly state all pertinent details, are). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. RODS & PUMP. TIH W/PKR SET @ 25' TEST BOOK 19.100. RODS & PUMP. TIH W/PKR SET @ 25' TEST BOOK 19.100. RODS & PUMP. TIH W/PKR SET @ 25' TEST BOOK 19.100. RODS & PUMP. TIH W/PKR SET @ 25' TEST BOOK 19.100. RODS & PUMP. TIH W/PKR SET @ 25' TEST BOOK 19.100. RODS & PUMP 10.100. RODS & PUMP 10.	od give pertinent dates, including estimated date impletions: Attach wellbore diagram of open the wellb
OTHER: 13. Describe proposed or complet of starting any proposed work proposed completion or reconsulation 10/24/12. MIRU. 10/25/12. TOH W/PROD TBG. 10/27/12. CLEAN OUT 10/31/12. CLEAN OUT F 6150' T 62 CIRCULATE WELL CLEAN W/100FTO PBTD @ 6595'. 11/07/12. SET PNEFE HCL + 300 GALS PEP-39. 11 SET @ 6145'. PUMP 220 GALS BAK CIRCULATED WELL 270 BBLS BR WELL CLEAN W/150 BBLS BRINE LOCATION.	ted operations. (Clearly state all pertinent details, are). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. (RODS & PUMP. TIH W/PKR SET @ 25' TEST BOYS 6143' T 6240'. 10/29/12. CIRCULATE WELL 63'. 11/01/12. CLEAN OUT F 6263' T 6335'. 11/03BLS BRINE WTR. 11/05/12. CLEAN OUT F 64 PKR @ 6148' PUMP 44 BBLS SCALE CONVERTOWN 10/12. TOH W/PKR PUMP 45 BBLS OF 14.5# MATERIAL SER 260 INHIBITER + 55 BBLS BRINE WTR. FLINE WTR. TOH W/PKR. 11/14/12. TIH W/2-7/8" WTR. TEST PROD TBG. 11/15/12. TIH W/ROD	od give pertinent dates, including estimated date impletions: Attach wellbore diagram of open the wellb
OTHER: 13. Describe proposed or complet of starting any proposed work proposed completion or reconsulation of the proposed completion or reconsulation of the proposed completion or reconsulation of the proposed completion of reconsulation of the proposed completion of the proposed completion of the proposed completion of the proposed complete in the proposed complete	red operations. (Clearly state all pertinent details, are). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. RODS & PUMP. TIH W/PKR SET @ 25' TEST Brown of F 6143' T 6240'. 10/29/12. CIRCULATE WELL 63'. 11/01/12. CLEAN OUT F 6263' T 6335'. 11/03BLS BRINE WTR. 11/05/12. CLEAN OUT F 64 PKR @ 6148' PUMP 44 BBLS SCALE CONVERTIVATION OF TOH W/PKR PUMP 45 BBLS OF 14.5# MER 260 INHIBITER + 55 BBLS BRINE WTR. FLINE WTR. TOH W/PKR. 11/14/12. TIH W/2-7/8" WTR. TEST PROD TBG. 11/15/12. TIH W/ROD Rig Release Date:	op. Toh W/PKR. 10/26/12. Toh W/2-7/8" CLEAN W/100 BBLS BRINE WTR. '02/12. CLEAN OUT F 6335' T 6446' 46' T 6513'. 11/06/12. CLEAN OUT F 6513' ER. 11/09/12. ACIDIZE W/5600 GALS 15% IUD TO KILL WELL. 11/12/12. TIH W/ PKR USH W/445 BBLS BRINE WTR. 11/13/12. PROD TBG SET @ 6178.1'. CIRCULATE S & PUMP. TEST PUMP. RDMO CLEAN
OTHER: 13. Describe proposed or complet of starting any proposed work proposed completion or reconsulation of the proposed completion or reconsulation of the proposed completion or reconsulation of the proposed completion of reconsulation of the proposed completion of the proposed completion of the proposed completion of the proposed complete in the proposed complete	ted operations. (Clearly state all pertinent details, are). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. (RODS & PUMP. TIH W/PKR SET @ 25' TEST BOYS 6143' T 6240'. 10/29/12. CIRCULATE WELL 63'. 11/01/12. CLEAN OUT F 6263' T 6335'. 11/03BLS BRINE WTR. 11/05/12. CLEAN OUT F 64 PKR @ 6148' PUMP 44 BBLS SCALE CONVERTOWN 10/12. TOH W/PKR PUMP 45 BBLS OF 14.5# MATERIAL SER 260 INHIBITER + 55 BBLS BRINE WTR. FLINE WTR. TOH W/PKR. 11/14/12. TIH W/2-7/8" WTR. TEST PROD TBG. 11/15/12. TIH W/ROD	op. Toh W/PKR. 10/26/12. Toh W/2-7/8" CLEAN W/100 BBLS BRINE WTR. '02/12. CLEAN OUT F 6335' T 6446' 46' T 6513'. 11/06/12. CLEAN OUT F 6513' ER. 11/09/12. ACIDIZE W/5600 GALS 15% IUD TO KILL WELL. 11/12/12. TIH W/ PKR USH W/445 BBLS BRINE WTR. 11/13/12. PROD TBG SET @ 6178.1'. CIRCULATE S & PUMP. TEST PUMP. RDMO CLEAN
OTHER: 13. Describe proposed or complet of starting any proposed work proposed completion or reconsulation of the proposed completion or reconsulation of the proposed completion or reconsulation of the proposed completion of reconsulation of the proposed completion of the proposed completion of the proposed completion of the proposed complete proposed	red operations. (Clearly state all pertinent details, are). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. (RODS & PUMP. TIH W/PKR SET @ 25' TEST BOYS 6143' T 6240'. 10/29/12. CIRCULATE WELL 63'. 11/01/12. CLEAN OUT F 6263' T 6335'. 11/03BLS BRINE WTR. 11/05/12. CLEAN OUT F 64 PKR @ 6148' PUMP 44 BBLS SCALE CONVERTOWARD 12. TOH W/PKR PUMP 45 BBLS OF 14.5# MATER 260 INHIBITER + 55 BBLS BRINE WTR. FLINE WTR. TOH W/PKR. 11/14/12. TIH W/2-7/8" WTR. TEST PROD TBG. 11/15/12. TIH W/ROD Rig Release Date:	nd give pertinent dates, including estimated date impletions: Attach wellbore diagram of OP. TOH W/PKR. 10/26/12. TOH W/2-7/8" CLEAN W/100 BBLS BRINE WTR. 10/2/12. CLEAN OUT F 6335' T 6446' 46' T 6513'. 11/06/12. CLEAN OUT F 6513' ER. 11/09/12. ACIDIZE W/5600 GALS 15% IUD TO KILL WELL. 11/12/12. TIH W/PKR USH W/445 BBLS BRINE WTR. 11/13/12. PROD TBG SET @ 6178.1'. CIRCULATE S & PUMP. TEST PUMP. RDMO CLEAN
OTHER: 13. Describe proposed or complet of starting any proposed work proposed completion or reconsulation of the proposed completion or reconsulation of the proposed completion or reconsulation of the proposed completion of reconsulation of the proposed completion of the proposed completion of the proposed completion of the proposed complete in the proposed complete	red operations. (Clearly state all pertinent details, are). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. RODS & PUMP. TIH W/PKR SET @ 25' TEST Brown of F 6143' T 6240'. 10/29/12. CIRCULATE WELL 63'. 11/01/12. CLEAN OUT F 6263' T 6335'. 11/03BLS BRINE WTR. 11/05/12. CLEAN OUT F 64 PKR @ 6148' PUMP 44 BBLS SCALE CONVERTIVATION OF TOH W/PKR PUMP 45 BBLS OF 14.5# MER 260 INHIBITER + 55 BBLS BRINE WTR. FLINE WTR. TOH W/PKR. 11/14/12. TIH W/2-7/8" WTR. TEST PROD TBG. 11/15/12. TIH W/ROD Rig Release Date:	nd give pertinent dates, including estimated date impletions: Attach wellbore diagram of OP. TOH W/PKR. 10/26/12. TOH W/2-7/8" CLEAN W/100 BBLS BRINE WTR. 10/2/12. CLEAN OUT F 6335' T 6446' 46' T 6513'. 11/06/12. CLEAN OUT F 6513' ER. 11/09/12. ACIDIZE W/5600 GALS 15% IUD TO KILL WELL. 11/12/12. TIH W/PKR USH W/445 BBLS BRINE WTR. 11/13/12. PROD TBG SET @ 6178.1'. CIRCULATE S & PUMP. TEST PUMP. RDMO CLEAN
OTHER: 13. Describe proposed or complet of starting any proposed work proposed completion or reconsolution of the proposed completion or reconsolution of the proposed completion or reconsolution of the proposed completion of reconsolution of the proposed completion of reconsolution of the proposed completion of the proposed completion of the proposed complete of the p	Red operations. (Clearly state all pertinent details, and seed operations.) SEE RULE 19.15.7.14 NMAC. For Multiple Completion. RODS & PUMP. TIH W/PKR SET @ 25' TEST BY F 6143' T 6240'. 10/29/12. CIRCULATE WELL 63'. 11/01/12. CLEAN OUT F 6263' T 6335'. 11/03BLS BRINE WTR. 11/05/12. CLEAN OUT F 64 PKR @ 6148' PUMP 44 BBLS SCALE CONVERTED 10/12. TOH W/PKR PUMP 45 BBLS OF 14.5# MER 260 INHIBITER + 55 BBLS BRINE WTR. FLINE WTR. TOH W/PKR. 11/14/12. TIH W/2-7/8" WTR. TEST PROD TBG. 11/15/12. TIH W/ROD Rig Release Date: Prove is true and complete to the best of my knowledge.	op. TOH W/PKR. 10/26/12. TOH W/2-7/8" CLEAN W/100 BBLS BRINE WTR. W/20/12. CLEAN OUT F 6335' T 6446' W/100 F 6513' W/100 F 6513' W/100 F 6513' W/100 F 6335' T 6446' W/100 F 6513' W
OTHER: 13. Describe proposed or complete of starting any proposed work proposed completion or reconsults. 10/24/12. MIRU. 10/25/12. TOH W/PROD TBG. 10/27/12. CLEAN OUT 10/31/12. CLEAN OUT F 6150' T 62 CIRCULATE WELL CLEAN W/100FTO PBTD @ 6595'. 11/07/12. SET PNEFE HCL + 300 GALS PEP-39. 11 SET @ 6145'. PUMP 220 GALS BAK CIRCULATED WELL 270 BBLS BR WELL CLEAN W/150 BBLS BRINE LOCATION. Spud Date: I hereby certify that the information about the second	Red operations. (Clearly state all pertinent details, and seed operations.) SEE RULE 19.15.7.14 NMAC. For Multiple Completion. RODS & PUMP. TIH W/PKR SET @ 25' TEST BY F 6143' T 6240'. 10/29/12. CIRCULATE WELL 63'. 11/01/12. CLEAN OUT F 6263' T 6335'. 11/03BLS BRINE WTR. 11/05/12. CLEAN OUT F 64 PKR @ 6148' PUMP 44 BBLS SCALE CONVERTED 10/12. TOH W/PKR PUMP 45 BBLS OF 14.5# MER 260 INHIBITER + 55 BBLS BRINE WTR. FLINE WTR. TOH W/PKR. 11/14/12. TIH W/2-7/8" WTR. TEST PROD TBG. 11/15/12. TIH W/ROD Rig Release Date: Prove is true and complete to the best of my knowledge.	op. TOH W/PKR. 10/26/12. TOH W/2-7/8" CLEAN W/100 BBLS BRINE WTR. W/20/12. CLEAN OUT F 6335' T 6446' W/100 F 6513' W/100 F 6513' W/100 F 6513' W/100 F 6335' T 6446' W/100 F 6513' W
OTHER: 13. Describe proposed or complet of starting any proposed work proposed completion or reconsolution of the proposed completion or reconsolution of the proposed completion or reconsolution of the proposed completion of reconsolution of the proposed completion of reconsolution of the proposed completion of the proposed completion of the proposed complete of the p	Red operations. (Clearly state all pertinent details, and seed operations.) SEE RULE 19.15.7.14 NMAC. For Multiple Completion. RODS & PUMP. TIH W/PKR SET @ 25' TEST BY F 6143' T 6240'. 10/29/12. CIRCULATE WELL 63'. 11/01/12. CLEAN OUT F 6263' T 6335'. 11/03BLS BRINE WTR. 11/05/12. CLEAN OUT F 64 PKR @ 6148' PUMP 44 BBLS SCALE CONVERTED 10/12. TOH W/PKR PUMP 45 BBLS OF 14.5# MER 260 INHIBITER + 55 BBLS BRINE WTR. FLINE WTR. TOH W/PKR. 11/14/12. TIH W/2-7/8" WTR. TEST PROD TBG. 11/15/12. TIH W/ROD Rig Release Date: Prove is true and complete to the best of my knowledge.	ad give pertinent dates, including estimated date impletions: Attach wellbore diagram of OP. TOH W/PKR. 10/26/12. TOH W/2-7/8" CLEAN W/100 BBLS BRINE WTR. 10/2/12. CLEAN OUT F 6335' T 6446' 46' T 6513'. 11/06/12. CLEAN OUT F 6513' ER. 11/09/12. ACIDIZE W/5600 GALS 15% IUD TO KILL WELL. 11/12/12. TIH W/ PKR USH W/445 BBLS BRINE WTR. 11/13/12. PROD TBG SET @ 6178.1'. CIRCULATE S & PUMP. TEST PUMP. RDMO CLEAN TO DATE RON.COM PHONE: 432-687-7198
OTHER: 13. Describe proposed or complete of starting any proposed work proposed completion or reconsults. 10/24/12. MIRU. 10/25/12. TOH W/PROD TBG. 10/27/12. CLEAN OUT 10/31/12. CLEAN OUT F 6150' T 62 CIRCULATE WELL CLEAN W/100FTO PBTD @ 6595'. 11/07/12. SET PNEFE HCL + 300 GALS PEP-39. 11 SET @ 6145'. PUMP 220 GALS BAK CIRCULATED WELL 270 BBLS BR WELL CLEAN W/150 BBLS BRINE LOCATION. Spud Date: I hereby certify that the information about the second	Red operations. (Clearly state all pertinent details, and seed operations.) SEE RULE 19.15.7.14 NMAC. For Multiple Completion. RODS & PUMP. TIH W/PKR SET @ 25' TEST BY F 6143' T 6240'. 10/29/12. CIRCULATE WELL 63'. 11/01/12. CLEAN OUT F 6263' T 6335'. 11/03BLS BRINE WTR. 11/05/12. CLEAN OUT F 64 PKR @ 6148' PUMP 44 BBLS SCALE CONVERTED 10/12. TOH W/PKR PUMP 45 BBLS OF 14.5# MER 260 INHIBITER + 55 BBLS BRINE WTR. FLINE WTR. TOH W/PKR. 11/14/12. TIH W/2-7/8" WTR. TEST PROD TBG. 11/15/12. TIH W/ROD Rig Release Date: Prove is true and complete to the best of my knowledge.	op. TOH W/PKR. 10/26/12. TOH W/2-7/8" CLEAN W/100 BBLS BRINE WTR. W/20/12. CLEAN OUT F 6335' T 6446' W/100 F 6513'. 11/06/12. CLEAN OUT F 6513' ER. 11/09/12. ACIDIZE W/5600 GALS 15% W/IUD TO KILL WELL. 11/12/12. TIH W/ PKR USH W/445 BBLS BRINE WTR. 11/13/12. PROD TBG SET @ 6178.1'. CIRCULATE S & PUMP. TEST PUMP. RDMO CLEAN CAILIST DATE CAILIST DATE