•			× (
		مىلىنىدىنى ئىرىمىنىدىنى ئىرىمىنى	۹۰	
Form 3160-5	UNITED ST		CD Hobbs	FORM APPROVED
(A	DEPARTMENT OF			OM B No. 1004-0137 Expires: March 31, 2007
.]	BUREAU OF LAND	MANAGEMENT	HOBBS O	5. Lease Serial No.
SUNDRY NOTICES AND REPORTS ON WELLS				6. If Indian, Allottee or Tribe Name
Do not use the abandoned w	is form for propos ell. Use Form 3160	als to drill or to re -3 (APD) for such p	-enferan 7 21 roposals.2 7 21	012
	IPLICATE- Other	instructions on reve	erse side RECEIVED	7. If Unit or CA/Agreement, Name and/or No.
1. Type of Well Gas Well Gas Well Other				8. Well Name and No.
2. Name of Operator OXY USA Inc.		1669		Bootleg Gin Federal Com #1H 9. API Well No.
		3b. Phone No. (inch. 432-685-5717	ide area code)	30-0/5-40306
4. Location of Well (<i>Footage, Sec., T., R., M, or Survey Description</i>)			·	10. Field and Pool, or Exploratory Area Red Tank Bone Spring
S - 1800 FSL 330 FWL NWSW(L) Sec 1 T22S R32E				11. County or Parish, State
BH - 1650 FSL 330 FEL NESE(1)				Lea NM
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA				
TYPE OF SUBMISSION	TYPE OF ACTION			
Notice of Intent	Acidize	Deepen		(Start/Resume) Water Shut-Off
	Alter Casing	Fracture Treat		. Well Integrity . Other Clean out, test csg,
Subsequent Report	Change Plans	Plug and Abandon	<u> </u>	
Final Abandonment Notice	Convert to Injectio		Water Dispo	
If the proposal is to deepen dire Attach the Bond under which the following completion of the inv	ectionally or recomplete hor he work will be performed ov volved operations. If the op nal Abandonment Notices s	izontally, give subsurface locat or provide the Bond No. on file eration results in a multiple con	ions and measured and e with BLM/BIA. Req npletion or recompletion	of any proposed work and approximate duration thereof. I true vertical depths of all pertinent markers and zones. uired subsequent reports shall be filed within 30 days on in a new interval, a Form 3160-4 shall be filed once lamation, have been completed, and the operator has
10/9/12 RUPU, NDWH, NU BOP. RIH & tag RBP @ RBP, POOH. RIH & tag POST @ 4742', test csg to 2100# held good for 30min.				
Closed POST, test 2100# held good for 30min. DO Post, circ hole test to 2100#, lost 60# in 40min. CO to 6614', test to 2250# held good				
for 35min. CO & DO cmt to 8560'. RIH & set pkr @ 7210', test csg from 7210'-surface to 5000#, lost 100# in 35min. Test from 7210'				
below to 5000#, lost 2000# in 30min, rel pkr, POOH. RIH to 8650', run camera, picture of sleeve w/ threaded ports, POOH. RIH & tag				
fish @ 8560', mill & CO to 12632', POOH. RIH & set CIBP @ 12628', circ hole, test csg to 5000# held good for 30min. RIH & run				
CBL/USIT from 8500' to surface, POOH, NDBOP, NUWH, RDPU 10/29/12.				
· · · · · · · · · · · · · · · · · · ·				
14. I hereby certify that the fore	aging is this and			
Name (Printed/Typed)	going is true and correct			
David Stewart		Title	Regulatory Advisor	ENDEDTED EAD DECARD
Signature In'	The second secon	Date	12/12	I BULEFIED FOR RECORD
THIS SPACE FOR FEDERAL OR STATE OFFICE USE				
Approved by			Title	Dec 2 2 2012
Conditions of approval, if any, are a certify that the applicant holds legal which would entitle the applicant to	l or equitable title to those i	rights in the subject lease	Office	TIREALI OF LAND MANAGEMENT
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to anymatter within its jurisdiction.				
(Instructions on page 2)				

0 m

ŗ