30-025-40909

HOBBS OCD

JAN 04 2013

Hydrogen Sulfide Drilling Operations Plan

- 1. Company and Contract personnel admitted on location should be trained to the following:
 - A. Characteristics of H_2S .
 - B. Physical Effects and Hazards.
 - C. Proper Use of Safety Equipment and Life Support Systems.
 - D. Principle and Operation of H₂S Detectors, Warning System and Briefing.
 - E. Evacuation Procedure, Routes and First Aid.
 - F. Proper Use of 30 minute Pressure Demand Air Pack.
- 2. H₂S Detection and Alarm Systems
 - A. H₂S Detectors and Audio Alarm System to be Located at Bell Nipple, End of Blooie Line (mud pit) and on Derrick floor or doghouse.
- 3. Windsock and/or Wind Streamers
 - A. Windsock at Mud Pit Area Should be High Enough to be Visible.
 - B. Windsock at Briefing Area Should be High Enough to be Visible.
 - C. There Should be a Windsock at Entrance to Location.
- 4. Condition Flags and Signs
 - A. Warning Sign on Access Road to Location.
 - B. Flags to be Displayed on Sign at Entrance to Location.
 - 1. Green Flag, Normal Safe Condition.
 - 2. Yellow Flag, Indicates Potential Pressure and Danger.
 - 3. Red Flag, Danger H₂S Present in Dangerous Concentration Only Emergency Personnel Admitted to Location.
- 5. Well Control Equipment
 - A. See Attached Diagram.
- 6. Communication

ş. -

- A. While Working Under Masks Chalkboards Will be Used for Communication.
- B. Hand Signals will be Used Where Chalk Board is Inappropriate.
- C. Two Way Radio or Cell Phone will be Used to Communicate off Location in Case of Available at Most Drilling Foreman's Trailer or Living Quarters.
- 7. Drillstem Testing
 - A. Exhausts will be Watered.
 - B. Flare Line will be Equipped with an Electric Igniter or a propane pilot light in case gas reaches the surface.
 - C. If Location is near any Dwelling a Closed DST will be Performed.
- 8. Drilling Contractor Supervisor will be Required to be Familiar with the Effects H₂S has on tubular goods and other mechanical equipment.
- If H₂S Encountered, Mud system will be Altered if Necessary to Maintain Control of Formation. A Mud Gas Separator will be Brought into Service Along with H₂S Scavengers if Necessary.

SMAENERGY

Company Contact List:

New Mexico Operations:	Name:	Cellular:	Office:
Drilling Superintendent	Howard Smith	903-262-0001	432-400-2395
Asst. Drilling Superintendent	Keith Pagett	806-317-5159	432-400-2395
Drilling Manager	Jonathan Nix	432-296-8956	432-688-3127
HSE Manager	David Carrillo	432-664-2095	432-688-3391
Project Manager	Malcolm Kintzing	432-212-2628	432-688-3125
Drilling Engineer	Michael Mataalii	432-271-2230	432-688-3392
Lea County (Hobbs):	!		Contact Number:
Lea County (Hobbs):			575-392-5588
State Police			
City Police			
Sheriff's Office			
Ambulance			575-397-9308
Fire Department			
Local Emergency Planning Com			<u> </u>
NMOCD			575-393-3612
US Bureau of Land Managemer	n		
Eddy County (Carlsbad)			Contact Number:
State Police			
City Police			
Sheriff's Office			
Ambulance			
Fire Department			
Local Emergency Planning Com	mittee	<u> </u>	575-887-3798
US Bureau of Land Managemen	nt		575-887-6544
Emergency Services			Contact Numbers:
Boots & Coots IWC	·		1-800-256-9688 or 281-931-8884
Cudd Pressure Control			
Halliburton	i i		
B.J. Services			
Flight for Life Lubbock TX			
Aerocare Lubbock TX			
Med Flight Air Ambulance Albu			
Lifequard Air Med Albuquerque			E7E 373 311F

575-272-3115

Lifeguard Air Med Albuquerque NM



SM Energy Mapping

