

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources
OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
June 19, 2008

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-30012
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
2. Name of Operator Mack Energy Corporation		6. State Oil & Gas Lease No. Fee
3. Address of Operator P.O. Box 960 Artesia, NM 88210		7. Lease Name or Unit Agreement Name Herring Fee
4. Well Location Unit Letter <u>L</u> <u>1980</u> feet from the <u>South</u> line and <u>330</u> feet from the <u>West</u> line Section <u>30</u> Township <u>16S</u> Range <u>32E</u> NMPM County <u>Lea</u>		8. Well Number 4
11. Elevation (Show whether DR, RKB, RT, GR etc.) 4180' GR		9. OGRID Number 013837
		10. Pool Name or Wildcat Grayburg Jackson SR Q G SA

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIALWORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Notify OCD 24 hours prior to starting plugging operations.

1. Set CIBP @ 2600' w/35' cmt cap. *CIRC WELL w/MLF*
2. Pump 25sx plug from 2070-2170'. Covering base of salt. Tag plug
3. Perf @ 1010'.
4. Pump 45sx plug from 910-1010'. Covering top of salt. Tag plug
5. Perf @ 450' *475' 475'*
6. Circ 200sx plug from surface-450'. Covering surface shoe and surface plug. Top cement off.
7. Install P&A marker.

Note: All plugs set w/14.8ppg, 1.34 yield Class C.

The Oil Conservation Division Must be notified
24 hours prior to the beginning of plugging operations.

Spud Date:

11/19/1987

Rig Release Date:

11/26/1987

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Deana Weaver

TITLE Production Clerk

DATE

1.21.13

Type or print name Deana Weaver

E-mail address: dweaver@mcc.com

PHONE: (575)748-1288

For State Use Only

APPROVED BY:

[Signature]

TITLE

Dist. Mgr

DATE

1-24-2013

Conditions of Approval (if any):

Mack Energy Corporation

Herring Fee #4 Sec. 30 T16S R32E 30-025-30012

Before

After

