Submit 3 Copies To Appropriate District	State of New Me			Form C-103
Office District 1	Energy, Minerals and Natu	ral Resources	Turnit Abrasa	June 19, 2008
	- 60 r	I DIIII II	WELL API NO. 30-025-	-23070
District II 1301 W. Grand Ave., Artesia, NM 882703BS OOIL CONSERVATION DIVISION District III 1000 Rio Brazos Rd., Aztec, NM 87410 20 South St. Francis Dr. Santa Fe, NM 87505			5. Indicate Type o	
			STATE X	
District IV	22 2013 Sama Pe, 19191 8	7505	6. State Oil & Gas	
1000 Rio Brazos Rd., Aztec, NM 87410 District LV 1220 S. St. Francis Dr., Santa Fe, NM AN 87505			o. State Off & Gas	Lease IVO.
SUNDRY NOTIC	ES: AND REPORTS ON WEL	LS	7. Lease Name or	Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPE DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.)	DSÁLS TO DRILL OR TO DEEPEN C	OR PLUG BACK TO A	North Vacuum Ab	Ŭ I
1. Type of Well: Oil Well Gas Well Other Injection				59
Name of Operator XTO Energy, Inc.			9. OGRID Number	- 1
3. Address of Operator			10. Pool name or Wildcat	
200 N. Loraine, Ste. 800 Midland, TX 79701			Vacuum; Abo, North	
4. Well Location				
Unit Letter <u>H</u> :	1980 feet from the NOR	TH line and	660 feet from	m the East line
	T 1: 4=-	70	NIN (TD) (
Section 13	Township 175	Range 34E	NMPM	County Lea
	11. Elevation (Snow whether)	DR, RRD, R1; GR, e	ic.)	
12 Cl l- A		National CNI-4	D O41 1	D-4-
12. Check A	ppropriate Box to Indicate 1	valure of Notice,	Report, or Other	Data
		· · · · · · · · · · · · · · · · · · ·		•
NOTICE OF INTE	ENTION TO:	SUE	BSEQUENT REF	PORT OF:
PERFORM REMEDIAL WORK 🕱	PLUG AND ABANDON 🗌	REMEDIAL WORK		ALTERING CASING
TEMPORARILY-ABANDON	CHANGE PLANS	COMMENCE DRILL	ING OPNS.	P-AND A
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT		"
	MOLTIPLE COMPL	CYQÚAQ\CEMEIA1	10B 🗀	
DOWNHOLE COMMINGLE			•	
		0.71150		
OTHER:		OTHER:		
 Describe proposed or completed of starting any proposed work). or recompletion. 	l operations. (Clearly state all per SEE RULE 1103. For Multiple	_	-	•
XTO Energy. Inc would like	e to propose a repair of in	niection well wit	h the following i	ntent:
1. MIRU PU. Check well for				
	fluid. L&T TCA w/pkr fluid	to 450 psi for 3	Omins. If no vent	ing/lk found, run
MIT chart.	•			
	1,			
V 1 1	· ·			
Spud Date:	Rig Relea	se Date:		·
		- ' ' ' _ ' _ '		!
I hereby certify that the information a	bove is true and complete to the	best of my knowled	ge and belief.	
AL COM	(2 log ()	The state of the state of	• .	and the state of the state of
SIGNATURE STULL YUMAL			3I	
	KUNIOUU TITI			DATE 01/10/2013
Type or print name Stephanie Raba		E <u>Requlato</u> stephanie_rabadue ail address:		DATE <u>01/10/2013</u> PHONE <u>432-620-6714</u>
Type or print name <u>Stephanie Raba</u>		stephanie_rabadue		
For State Use Only		stephanie_rabadue	extoenergy.com	PHONE 432-620-6714
		stephanie_rabadue	extoenergy.com	
For State Use Only	E-many Delta Control of the Control	stephanie_rabadue	extoenergy.com	PHONE 432-620-6714