

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

BP AMERICA PRODUCTION COMPANY

3a. Address

P.O. BOX 3092, RM 6.115, HOUSTON, TX 77253

3b. Phone No. (include area code)

281-366-2052

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

S8-26S-29E, 660' FNL & 330' FEL, E2-NE-NE

5. Lease Serial No.

MM101108

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

WEST BRUSHY 8 FED 1

9. API Well No.

30-015-31675

10. Field and Pool, or Exploratory Area

BRUSHY DRAW (DELAWARE)

11. County or Parish, State

EDDY

NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☐ Subsequent Report
☒ Final Abandonment Notice

TYPE OF ACTION

- | | | | |
|---|--|--|---|
| <input type="checkbox"/> Acidize | <input type="checkbox"/> Deepen | <input type="checkbox"/> Production (Start/Resume) | <input type="checkbox"/> Water Shut-Off |
| <input type="checkbox"/> Alter Casing | <input type="checkbox"/> Fracture Treat | <input type="checkbox"/> Reclamation | <input type="checkbox"/> Well Integrity |
| <input type="checkbox"/> Casing Repair | <input type="checkbox"/> New Construction | <input type="checkbox"/> Recomplete | <input type="checkbox"/> Other _____ |
| <input type="checkbox"/> Change Plans | <input checked="" type="checkbox"/> Plug and Abandon | <input type="checkbox"/> Temporarily Abandon | |
| <input type="checkbox"/> Convert to Injection | <input type="checkbox"/> Plug Back | <input type="checkbox"/> Water Disposal | |

- 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)**

PLUGGING DATES: JULY 29 THRU AUGUST 2, 2005

SET 30 SXS CEMENT PLUG @ 5308; SET CIBP @ 4828' WITH 25 SXS CEMENT ON TOP, TOC=4410'; CIRCULATED 315 SXS OF CEMENT DOWN 5 1/2" & UP 8 5/8" CASING FROM 1007' TO SURFACE; CUT OFF WELL HEAD 4' BELOW GROUND LEVEL AND INSTALL SURFACE MARKER; FILL CELLAR; CUT OFF ANCHORS; AND CLEAN LOCATION.

Approved as to plugging of this well bore.
Liability under bond is retained until
surface restoration is completed.

APPROVED

SEP 14 2005

**LES BABYAK
PETROLEUM ENGINEER**

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

SUE SELLERS

Title

REGULATORY STAFF ASSISTANT

Date

AUGUST 30, 2005

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.