

Submit 1 Copy To Appropriate District
Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources
HOBBS OCD
OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
October 13, 2009

WELL API NO. 30-025-21821	
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>	
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name Eidson "A" WN	
8. Well Number 4	
9. OGRID Number 018100	
10. Pool name or Wildcat Shoebar WC & Townsend Abo	
4. Well Location Unit Letter <u>K</u> : 1990 feet from the <u>South</u> line and <u>1750</u> feet from the <u>West</u> line Section <u>26</u> Township <u>16S</u> Range <u>35E</u> NMPM <u>Lea</u> County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3966 GR	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

We propose to P&A this well as follows:

Tag and Dump 35' cement on top of CIBP @ 9650', Set new CIBP @ 8600' and dump 35' cmt on top.
Perforate squeeze holes @ 6284, 4850, 465 and 60'
Circulate hole with 9.5# brine w/ 12.5 # salt gel/bbl
Pump 35sx cmt @ 6284', WOC and tag
Pump 35 sx cmt @ 1800', WOC and tag
Pump 35 sx cmt @ 456', WOC and tag
Pump cement @ 60' to fill the hole inside and out of 5 1/2" casing
After plugging, a dry hole marker will be installed and the location cleaned and leveled for NMOCD final inspection

Spud Date:

7/14/1966

Rig Release Date:

8/22/1966

NOTE: Permission to plug was granted 6/19/2009 but permit expired.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE

President

DATE 2/9/2013

Type or print name Phelps White

E-mail address: pwiv@zianet.com

PHONE: 575 626 7660

For State Use Only

APPROVED BY:

TITLE

DATE 2-18-2013

Conditions of Approval (if any):

Oil Conservation Division - Hobbs office: Must be Notified
24 hours prior to the beginning of Plugging Operations begin.