

Submit 1 Copy To Appropriate District  
Office  
District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised August 1, 2011

HOBBS OGD  
RECEIVED  
FEB 20 2013

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-33524 /
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> / FEE <input type="checkbox"/>
2. Name of Operator CHEVRON U.S.A. INC.		6. State Oil & Gas Lease No.
3. Address of Operator 15 SMITH ROAD, MIDLAND, TEXAS 79705		7. Lease Name or Unit Agreement Name STATE A "26" /
4. Well Location Unit Letter L: 1980 feet from the SOUTH line and 330 feet from the WEST line Section 26 Township 19-S Range 36-E NMPM County LEA		8. Well Number 5 /
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. OGRID Number 4323 /
		10. Pool name or Wildcat MONUMENT; ABO

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER:

OTHER: RETURN TO PRODUCTION

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

10-22-12: MIRU. 10-23-12: START TO DRILL OUT CIBP. 10-24-12: TAG PLUG @ 7288. 10-25-12: SET PKR @ 7273.  
PMP 66 BBLS DN TBG. UNSET PKR. 10-26-12: TAG UP FILL @ 7530. 10-30-12: TAG FILL @ 7560. C/O TO PBTD.  
TAG FILL @ 7591. C/O. TAG FILL @ 7601. 10-31-12: SET PKR @ 7310. 11-01-12: LD PKR. PU ESP EQPT. 11-05-  
12: FINISH TIH W/TBG. LAND WH. TEST RUN ESP.

*Plans are to temporarily abandon the well due to problems in flowing due to topside issues and lifting costs.*

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

*Denise Pinkerton*

TITLE: REGULATORY SPECIALIST

DATE: 02-18-2013

Type or print name: DENISE PINKERTON

E-mail address: leakejd@chevron.com

PHONE: 432-687-7375

APPROVED BY

*Dist. Mgr.*

TITLE

DATE 2-21-2013

Conditions of Approval (if any):

FEB 21 2013