Submit I Copy To Appropriate District State of New Mexico	Form C-103
Office District 1 – (575) 748-1283	Revised August 1, 2011 WELL API NO.
District 11 – (575) 748-1283 811 S. First St., Artesia, NM 88210 ADD CO OTL CONSERVATION DIVISION	
District III = $(505) 334.6178$ AFR UO LUV12220 South St. Example Dr	5. Indicate Type of Lease STATE X FEE
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460 1220 South St. Francis Dr., 1220	6. State Oil & Gas Lease No.
87505	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name Rock Queen Unit
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	Q Wall Number
1. Type of Well: Oil Well     Gas Well     Other Injection       2. Name of Operator     Gas Well     Gas Well	9. OGRID Number
Celero Energy II, LP	247128
3. Address of Operator <sub>400</sub> W. Illinois, Ste. 1601 Midland, TX 79701	10. Pool name or Wildcat Caprock; Queen
4. Well Location	Caprock, Queen
Unit Letter D : 660 feet from the N line and 660 feet from the W line	
Section 23 Township 13S Range 31E	NMPM County Chavez
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: S PERFORM REMEDIAL WORK DILUG AND ABANDON I REMEDIAL W	UBSEQUENT REPORT OF:
TEMPORARILY ABANDON  CHANGE PLANS COMMENCE	DRILLING OPNS. PANDA
PULL OR ALTER CASING     MULTIPLE COMPL     CASING/CEN       DOWNHOLE COMMINGLE	IENT JOB
OTHER: OTHER: OTHER: OTHER: OTHER: OTHER:	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
1. RU WL & set CIBP @ 2950'. Load hole & test csg. 2. RIH w/ 2 3/8" WS & spot 35 sx on CIBP. PU, reverse clean, WOC a min 4 hrs & tag. Circ hole w/ min 9.5 ppg salt mud.	
3. PU to 2242' & spot 25 sx.	
4, PU to 1480' & spot 25 sx. POOH. 5. PU WL & perf 4 @ 359'. RIH w/ tbg to 409' & circ 5 1/2" csg & 5 1/2" by 8 5/8" annulus full w/min 120 sx. POOH LD WS.	
6. RD & set P&A marker. Clean & reclaim location.	
All plugs Class C w/ 2% CaCl2 Min 9.5 ppg salt mud between plugs.	- · · · ·
The Oil Conservation Division Must be notified	
24 hours prior to the	e beginning of plugging operations.
,, , ,, , ,, , ,, , ,, , ,, , ,, , , ,, , , , , , , , , , , , , , , , , , , ,	
Spud Date: Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowl	ledge and belief.
$\varphi$	
SIGNATURE Isa Hand TITLE Regulatory Analyst	DATE_04/04/2013
Type or print name Lisa Hunt E-mail address: <u>lhunt@celerc</u>	penergy.com PHONE: (432)686-1883
Sel Distant	2 1/0 2012
APPROVED BY: Conditions of Approval (if any)	DATE 7-0-200
	APR 09 2013

.....

. . . . . . .

- - - -



