

Submit 1 Copy To Appropriate District Office

District I – (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II – (575) 748-1283
811 S. First St., Artesia, NM 88210
District III – (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV – (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised August 1, 2011

HOBBBS OGD

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

WELL API NO. 30-025-31019
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name EAST PEARL QUEEN UNIT
8. Well Number #89
9. OGRID Number 25482
10. Pool name or Wildcat PEARL QUEEN

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐	
2. Name of Operator STATE OF NEW MEXICO formerly Xeric Oil & Gas Corp.	
3. Address of Operator 1625 N. French Drive Hobbs, NM 88240	
4. Well Location Unit Letter <u>D</u> : <u>1310</u> feet from the <u>N</u> line and <u>1310</u> feet from the <u>W</u> line Section <u>34</u> Township <u>19S</u> Range <u>35E</u> NMPM County <u>LEA</u>	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

SEE ATTACHED P&A PROCEDURE

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mark Whitaker Title COMPLIANCE OFFICER DATE 12/07/2012

Type or print name MARK WHITAKER E-mail address: Marka.Whitaker@state.nm.us PHONE: 575-393-6161
For State Use Only

APPROVED

BY: _____ TITLE _____ DATE _____

Conditions of Approval (if any):

State of New Mexico formerly Xeric Oil & Gas Corp
East Pearl Queen Unit No. 89

Set CIBP at 4600' and cap w/ 25 sx cmt. Pressure test csg.
Circulate hole w/ 9.5 ppg brine w/ 25 sx salt gel per 100 bbls.
Spot 25 sx cmt at 3400'.
Spot 25 sx cmt at 1800'.
Spot cmt from 460' to surface.
Cut off wellhead and install dry hole marker.

PLUGGING & ABANDONMENT WORKSHEET

(2 STRING CSNG)

OPERATOR ST. of NM formerly XERIC oil & GAS
LEASENAME EAST PEARL QUEEN UNIT

SECT 34 TWN 19S RNG 35E
FROM 1310 (N) S L 1310 E (W) L
TD: 5085' FORMATION @ TD QUEEN
PBTD: 5028 FORMATION @ PBTD

8 5/8"
@ 410'
TOC CIRC

5 1/2
@ 5067'
TOC CIRC

PBTD 5028'

TD 5085'

30-025-31089

	SIZE	SET @	TOC	TOC DETERMINED BY
SURFACE	<u>8 5/8</u>	<u>410</u>		<u>CIRC</u>
INTMED 1				
INTMED 2				
PROD	<u>5 1/2</u>	<u>5067'</u>		<u>CIRC</u>
	SIZE	TOP	BOT	TOC DETERMINED BY
LINER 1				
LINER 2				
	CUT & PULL @		TOP - BOTTOM	
INTMED 1			PERFS	<u>4678' - 4991'</u>
INTMED 2			OPENHOLE	-
PROD				

*REQUIRED PLUGS DISTRICT I

RUSTLER (AKNEYD)	
YATES	
QUEEN	<u>4600'</u>
GRAYBUSH	
SAN ANDREW	
T. SALT	<u>1800'</u>
CARTER REEF	
B. SALT	<u>3400'</u>
DELAWARE	
BELL CANYON	
CHERRY CANYON	
BERRY CANYON	
BOGE SPRING	
OLORIETA	
BLISSBY	
TUES	
DEINGARD	
ABO	
WOC	
PERCH	
HITMAN	
ATOKA	
WICKLOW	
LETT	
DEVOREAN	

PLUG	TYPE	SACKS	DEPTH
PLUG	PLUG	CMNT	
EXAMPLES			
PLUG #1	OH	35 SXS	6400'
PLUG #2	SHOE	50 SXS	5350' - 5450'
PLUG #3	CIRP/35'		4800'
PLUG #4	CIRP	25 SXS	4800'
PLUG #5	STUB	50 SXS	3600' - 3700'
PLUG #6	REINR SQZ	200 SXS	400'
PLUG #7	SURF	10 SXS	0-10'
PLUG #1			
PLUG #2			
PLUG #3			
PLUG #4			
PLUG #5			
PLUG #6			
PLUG #7			
PLUG #8			
PLUG #9			
PLUG #10			
PLUG #11			
PLUG #12			
PLUG #13			
PLUG #14			
PLUG #15			
PLUG #16			
PLUG #17			
PLUG #18			
PLUG #19			
PLUG #20			
PLUG #21			
PLUG #22			
PLUG #23			
PLUG #24			
PLUG #25			
PLUG #26			
PLUG #27			
PLUG #28			
PLUG #29			
PLUG #30			