## HOBBS OCD

Submit 1 Copy To Appropriate District	State of New Mexico	PROPES OCD	Form C-103
Office	English Minerals and National Base	uus oh D.D W	October 13, 2009
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Reso	WICCAPH ONE 2013 PLA	10
District II		20.025.0414	
1301 W. Grand Avc., Artesia, NM 88210	OIL CONSERVATION DIVIS		
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	RECEIVED STAT	E FEE
District IV	Santa Fe, NM 87505		& Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM			
87505	IOFO AND DEDODES ON WELLS	7 1 11	II 's Assessment Name
	ICES AND REPORTS ON WELLS  SALS TO DRILL OR TO DEEPEN OR PLUG BACK		ne or Unit Agreement Name
	CATION FOR PERMIT" (FORM C-101) FOR SUCH	l l	ment G/SA Unit Blk. 19
PROPOSALS.)		8. Well Num	
1. Type of Well; Oil Well	Gas Well Other Injection well.		<u> </u>
2. Name of Operator		9. OGRID N	umber 873
Apache Corp.			77/11
3. Address of Operator	1,00775	10. Pool nan	
P O box Drawer D Monument NM	. 88203	Eunice Monu	iment G/SA
4. Well Location			
Unit LetterE	:_1980feet from theN		feet from the
Wline			
Section 1	Township 20S Range	36E NMPM	Lea County
	11. Elevation (Show whether DR, RKB, R		gar manarang ing
The second secon			J. Dog. wo
12. Check	Appropriate Box to Indicate Nature o	f Notice, Report or Ot	her Data
12, 6110011	ippropriate Box to maleute future of	Troutes, respect of or	mor batt
NOTICE OF IT	NTENTION TO:	SUBSEQUENT	REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEI	DIAL WORK (	ALTERING CASING [
TEMPORARILY ABANDON	CHANGE PLANS   COMM	ENCE DRILLING OPNS.[	] PANDA [
PULL OR ALTER CASING	MULTIPLE COMPL   CASIN	G/CEMENT JOB [	
DOWNHOLE COMMINGLE			
OTHER:		R: 5 year press	ure test
12 Describe proposed or com	년   Dleted operations. (Clearly state all pertinent	datails and aive nortinous	detectively dispersion and detection
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
proposed completion of recompletion.			
	,		
Move in Gandy truck and pressure	he casing and chart for 32 minutes. Starting	pressure 530 # and finale	pressure 530#
	,		
	- 6.		
	*****		
Spud Date:	Rig Release Date:		
I hereby certify that the information	above is true and complete to the best of my	knowledge and helief	
in a mornation		omieage and benet.	
$\cap \cap c\mathcal{N}$	)		11
SIGNATURE X	TITLEInstrument	Tech	DATE 4-5-13
		-	
Type or print naturaJim Ellison_	E-mail address: _JD,E	Hison@apacheccorp.com_	PHONE:
For State Use Only			_
ADDRAGO DE SECTION DE LA CONTRACTION DEL CONTRACTION DE LA CONTRAC	) / Dat	2002	

APR 18 2013

