

Form 3160-5
(August 1999)UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT**SUNDRY NOTICES AND REPORTS ON WELLS**
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.*FORM APPROVED
OMB NO. 1004-0135
Expires: November 30, 20005. Lease Serial No.
LC-070397

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.
WEST PEARL QUEEN UNIT 1119. API Well No.
30-025-0324510. Field and Pool, or Exploratory
PEARL QUEEN11. County or Parish, and State
LEA COUNTY, NM**SUBMIT IN TRIPLICATE - Other instructions on reverse side.**

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other2. Name of Operator
XERIC OIL & GAS CORPORATIONContact: ANGIE CRAWFORD
E-Mail: ACrawford@xericoil.com3a. Address
P. O. BOX 352
MIDLAND, TX 797023b. Phone No. (include area code)
Ph: 915.683.3171 Ext: 235
Fx: 915.683.63484. Location of Well (Footage, Sec., T., R., M., or Survey Description)
Sec 29 T19S R35E SWNE 1980FNL 1980FEL**12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA**

TYPE OF SUBMISSION

TYPE OF ACTION

- ☐
- Notice of Intent
-
- ☒
- Subsequent Report
-
- ☐
- Final Abandonment Notice

- ☐
- Acidize
-
- ☐
- Alter Casing
-
- ☐
- Casing Repair
-
- ☐
- Change Plans
-
- ☐
- Convert to Injection

- ☐
- Deepen
-
- ☐
- Fracture Treat
-
- ☐
- New Construction
-
- ☒
- Plug and Abandon
-
- ☐
- Plug Back

- ☐
- Production (Start/Resume)
-
- ☐
- Reclamation
-
- ☐
- Recomplete
-
- ☐
- Temporarily Abandon
-
- ☐
- Water Disposal

- ☐
- Water Shut-Off
-
- ☐
- Well Integrity
-
- ☐
- Other

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

9/5/03 Spot 45 sx @ 4500'. WOC & tag @ 3854'.
9/8/03 Perf @ 1700'. Could not pump into. Spot 25 sx 1750'-1650'.
Perf @ 350'. Squeeze 100 sx. WOC & tag @ 195'.
Perf @ 65'. Squeeze 50 sx to surface.
Install P&A Marker.
Circulate mud.

14. I hereby certify that the foregoing is true and correct.

Electronic Submission #23897 verified by the BLM Well Information System
For XERIC OIL & GAS CORPORATION, sent to the Hobbs
Committed to AFMSS for processing by Linda Askwig on 09/23/2003 ()

Name (Printed/Typed) W. KYLE LEWIS

Title TREASURER

Signature (Electronic Submission)

Date 09/23/2003

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

**** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED *****Called Gary Goulet @ BLM for
status on approval. He
will fax or call 11.1.1*