

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
June 19, 2008

HOBBS OGD

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.
Santa Fe, NM 87505

FEB 25 2013

RECEIVED

WELL API NO. 30-025-25645
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: A L Christmas NCT C
8. Well Number 14
9. OGRID Number 005380
10. Pool name or Wildcat Blinebry Oil & Gas (Oil)
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3433' GL

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other
2. Name of Operator XTO Energy, Inc.
3. Address of Operator 200 N. Loraine, Ste. 800 Midland, TX 79701
4. Well Location Unit Letter D : 560' feet from the North line and 810' feet from the West line Section 18 Township 22S Range 37E NMPM County Lea
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3433' GL

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: **Reactivation & DHC (DHC-HOB-510)** ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

01/10/2013: MIRU PU01/11/2013: Tag CIBP @ 5350'. Load TCA w/12bbls 9# brine water. Press TCA to 500psi. Lost 40psi in 10mins. 01/14/2013: RIH & tag CIBP @ 5350. DO to 5352'. Lost circ. 01/15/2013: Tag CIBP @ 5352. DO CIBP. Tag @ 5515'. DO to 5751'. 01/16/2013-01/31/2012: Mill on fill/fish to 6573'. Unable to pull or DO. Fish @ 6573'. 02/04/2013: Perf Blinebry zone @ 5452-5457' w/10 holes. Perf Drinkard zone @ 6433'-6440', 6521'-6530', 6534'-6540', 6542'-6547' w/ 54 holes, 2 SPF on all. 02/05/2013: Set pkr @ 5360'. L&T TCA 2/53BFW to 500psi, monitor throughout job. Acidize perfs w/8000gals 20% HCL 90/10 Acid. 02/08/2013: RIH w/ 2.875" 6.5# J-55 tbg & ESP. 02/11/2013: RDMO PU.

Spud Date:

09/18/1977

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Stephanie Rabadue TITLE Regulatory Analyst DATE 02/13/2013
Type or print name Stephanie Rabadue E-mail address: stephanie_rabadue@xtoenergy.com PHONE 432-620-6714

For State Use Only

APPROVED BY [Signature] TITLE Petroleum Engineer DATE MAY 23 2013

Conditions of Approval (if any): DHC-HOB-510

MAY 23 2013