HOBBS OCD

Submit 1 Copy To Appropriate District Office	State of New Mexico		29 2013	Form C-103
District I - (575) 393-6161	Energy, Minerals and Natural Res	ources	WELLAPINO	Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283	OIL CONCEDUATION DIVIS	RE	CEIVED API NO.	30-041-20955
811 S. First St., Artesia, NM 88210 District III – (505) 334-6178	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.		5. Indicate Type	
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505		STATE	FEE X
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa Pe, 14M 67303		6. State Oil & Ga 39543	
87505 SUNDRY NOTIC	ES AND REPORTS ON WELLS		7. Lease Name or	Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A				
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				SON 31
1. Typc of Well: Oil Well X Gas Well Other			8. Well Number	
Name of Operator ICA ENERGY OPERATING, LLC			9. OGRID Number	er 178694
3. Address of Operator			10. Pool name or	
P.O. BOX 2712 ODESSA, TX 79760			CLR (SA	N ANDRES)
4. Well Location				/
	80feet from the _SOUTH line			ieEASTline
Section 31 Township 8-S Range 34-E NMPM County ROOSEVELT				
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4309 GL				
			4505 00 4=2=600	
12. Check Ap	propriate Box to Indicate Nature o	f Notice,	Report or Other	Data
NOTICE OF INT	ENTION TO:	CLID	SEQUENT REF	DODT OF
		DIAL WOR		ALTERING CASING
TEMPORARILY ABANDON				
	MULTIPLE COMPL CASIN	G/CEMEN [*]	TJOB 🗆	
DOWNHOLE COMMINGLE				
OTHER:	☐ OTHER	R: PERF	& ACIDIZE	Х
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date				
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
proposed completion of recon	pietion.			
2/12/13: MIRU PU. POH W/RODS/PUMP/TBG. RIH W/RBP/PKR AND TBG. SET RBP @ 4650. PUMP 17 BBLS 2% KCL TO				
LOAD. – TEST TO 500#. SET PKR @ 4520. PUMP 22 BBLS 2% KCL TO LOAD – TEST TO 500#. DUMP (2) SACKS SAND THRU TBG. INSTALL TIW VALVE.				
ortone critical ratio r				
	0-14', 4622-25' @ 3 SPF. MAX RATE =		- AVG RATE = 3.2	BPM. MAX PSI = 3727#
- AVG PSI = 15773. I	SIP = 1242#, 5 = 1039#, 10 = 958#, 15 =	888#.		
2/14/13: POH W/PKR – POH W/	RBP – RIH W/PRODUCTION STRING -	- RIH W/R	ODS AND PUMP.	HBO.
<u></u>		····		_
Spud Date:	Rig Release Date:			
L				
I hereby certify that the information abo	ove is true and complete to the best of my	knowledge	and belief.	
	1			
SIGNATURE Welley (WILL TITLE OPERATIONS	ASSISTA	NTDATE	E5/22/13
Type or print name DEPDIE CLIPBY	() E mail add daw	ionemore	., DUO	NE. 422 500 5722
Type or print name _DEBBIE CURRY For State Use Only				NE: _432-580-5722
<u> </u>	Petroleu	_		MAY 3 0 2013
APPROVED BY:	TITLE		DAT	E IIAI O U ZOIO
AUDITIONS OF A POPOVSPORTING				

MAY 3 0 2013