
Submit 1 Copy To Appropriate District Office State of New Mexico	Form C-103
District I – (575) 393-6161 HOBS Energy, Minerals and Natural Resources	October 13, 2009
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II - (575) 748-1283 811 S. First St., Artesia, NM 88210 JUN 1 2011 CONSERVATION DIVISION	30-025-10656 5. Indicate Type of Lease
District III - (505) 334-6178 1220 South St. Francis Dr.	STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460 Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	301940
87505 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	SKELLY PENROSE B UNIT
1. Type of Well: Oil Well Gas Well Other TA in	8. Well Number 036
2. Name of Operator	9. OGRID Number
PROVIDENCE ENERGY SERVICES, INC. dba KELTON OPERATING 3. Address of Operator	10. Pool name or Wildcat
P.O. BOX 928, ANDREWS, TEXAS, 79714-0928	LANGLIE MATTIX (37240)
4. Well Location	
Unit Letter P : 990 feet from the SOUTH line and 990 660 feet from the EAST line	
Section 6 Township 23S Range 37E NMPM LEA County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	_
TEMPORARILY ABANDON	_
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT	JOB 🗆
DOWNHOLE COMMINGLE	
OTHER: OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of	
proposed completion or recompletion. 1. MIRU plugging equipment.	
2. Tag CIBP @ 3560'.	
3. Circulate hole with mud laden fluid.	
4. Spot 25 sx cement on top of CIBP @ 3560'.	
5. Spot 25-six element @ 2745' 2495 WOC & Tag. (btm of sale). Spot CMT TOM 2/00 TO	
6. Spot 25 sy cement @ 1501-1251 WOC & Tag. (top of salt).	
4. Spot 25 sx cement on top of CIBP @ 3560'. 5. Spot 25 sx cement @ 2745' 2495 WOC & Tag. (btm of sale). 6. Spot 25 sx cement @ 1501-1251 WOC & Tag. (top of salt). 6. Spot 65 sx cement @ 360'-surface. 78. Cut off wellhead and install dry hole marker. Perf @ 401'. Circ. cwt to Surface.	
The second and mountain on, more markers of the country solutions.	
,	
* THIS WELL IS IN REGOGNARED. CEMENT REC	PUIRED ACROSS ENTIRE
A	SALT SECTION
Spud Date: Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE CONTINUE TITLE PERSINGLY	T DATE (-11-13
SIGNATURE TILE TEST DE	DATE
Type or print name CDRIE CETTO ME-mail address:	PHONE:
For State Use Only	
APPROVED BY DATE 13-2013	
APPROVED BY: TITLE U.S. TITLE U.S. TITLE U.S.	DATE IN TUIS
Oil Conservation Division - Hobbs office: Must be Notified 24 hours prior to the beginning of Plugging Operations begin. Form provided by Forms On-A-Disk (214) 340-9429 · FormsOnADisk.com	

JUN 1 3 2013

Kelton Operating Corporation - WELL DIAGRAM



Kelton Operating Corporation - VvELL DIAGRAM

