

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources
HOBBS OCD
OIL CONSERVATION DIVISION
JUN 19 2013 1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised August 1, 2011

RECEIVED	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <u>SWD</u>	7. Lease Name or Unit Agreement Name Corazon 4 State SWD
2. Name of Operator COG Operating LLC	8. Well Number 1
3. Address of Operator 2208 W. Main Street, Artesia, NM 88210	9. OGRID Number 229137
4. Well Location Unit Letter _____ : _____ feet from the _____ North line and _____ 2500 feet from the _____ East line Section 4 Township 21S Range 33E NMMP Lea County	10. Pool name or Wildcat SWD; Cherry Canyon-Brushy Canyon
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3805' GR	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: Completion Operations ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

4/25/13 to 4/26/13 MIRU. Tag DVT @ 5249'. Test csg to 3000#. Drill out DVT. Tag PBTD @ 7198'. Circulate clean.

4/28/13 to 5/1/13 Perforate Delaware 6500-6984' (376). Perforate Delaware 5710-6500' (582).

5/2/13 to 5/7/13 Set RBP @ 7074' & pkr @ 6624'. Acidz w/2000 gal 7 1/2% HCl acid & 250 ball sealers. Move RBP to 6624' & pkr to 6400'. Acidz w/2000 gal 7 1/2% HCl acid. Move RBP to 6400' & pkr to 6144'. Acidz w/2000 gal 7 1/2% HCl acid & 200 ball sealers. Move RBP to 6144' & pkr to 5886'. Acidz w/2500 gal 7 1/2% HCl & 200 ball sealers. Move RBP to 5875' & pkr to 5663'. Acidz w/2000 gal 7 1/2% HCl acid & 200 ball sealers. POOH w/tools.

5/8/13 to 5/9/13 Set 4 1/2" 11.6# Glassbore tbg & pkr @ 5657'. Circ well w/130 bbls pkr fluid. Pressure test to 530# for 30 mins. Test witnessed by Mark Whitaker (Hobbs OCD). Well is shut-in while building battery.

(Chart is attached.)

Non-Well PO# 2837076

Spud Date:

4/1/13

Rig Release Date:

4/16/13

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Stormi Davis TITLE: Regulatory Analyst DATE: 6/11/13

Type or print name: Stormi Davis E-mail address: sdavis@concho.com PHONE: (575) 748-6946

For State Use Only

APPROVED BY: [Signature] TITLE: Petroleum Engineer DATE: JUN 27 2013

Conditions of Approval (if any):

SWD-1374

JUN 27 2013

