## Gonzales, Elidio L, EMNRD

APT 30-025-1751Z

m:

Jones, Garry [Garry.Jones@basicenergyservices.com]

ວent:

Tuesday, May 29, 2012 8:22 PM

To:

Gonzales, Elidio L, EMNRD; 'markwhitaker@state.nm.us'; 'maxey.brown@state.nm.us';

'burrowsmarvin@rocketmail.com'; Minear, Randall; Eggleston, Gary

Subject:

P&A Mexico u # 1

5-29-2012 Mexico 'U' # 1

Road crew to location, held safety meeting.
Cut-off well-head & anchors. Clean location.
Install dry-hole marker.
RDMO plugging equipment.
Daily Total = 1780.00
Regards,
Garry Jones

Basic Energy Services Confidentiality Notice:

The information in this email is confidential. It is intended solely for the addressee. Access to this email by anyone else is unauthorized. If you are not the intended recipient, any disclosure, copying, distribution or any action taken or omitted to be taken in reliance on it, is prohibited and may be unlawful.

1

## Gonzales, Elidio L, EMNRD

om: Jones, Garry [Garry.Jones@basicenergyservices.com]

**sent:** Friday, May 25, 2012 5:34 PM

To: Gonzales, Elidio L. EMNRD: markwhitaker@state.nm.us: maxev.brown@state.nm.us:

burrowsmarvin@rocketmail.com; humpron@gmail.com; Minear, Randall

Subject: P&A Job

5-25-2012 Mexico 'U' # 1

Road crew to location, held safety meeting.

Open well

5 ½ Pkr. @ 1583 ft.

Pressure test 5 ½ csg. below Pkr. to 1500 psi. Lost 300 psi in 20 minutes.

Rel. Pkr. & TOOH

Contact OCD (m. Whitiker) Advise to tag cmt. plug & Spot cmt. to 1200 ft.

Pu perf. sub & TIH w/ 2 3/8 tbg. & tag cmt. plug @ 1851 ft. (56 jts.)

Spot 76 sks. cmt from 1851 ft. (750 ft.) w/ 2% Calcium Chloride. Disp. 4.2 bbls.

LD 20 its. & stand-back 18 stands. WOC

TIH w/ tbg. & tag cmt. plug @ 1154 ft.

LD 20 its.

Bottom Of tbg. @ 500 ft.

Spot 48 sks. cmt from 500 ft. to 25 ft. Displace ½ bbls.

LD 15 jts. tbg.

NDBOP

Fill 5 1/2 well-bore w/ 2 sks. cmt. to surface.

¬D cmt. pump.

ill RD plugging rig Tuesday.

Hoad crew to Odessa Texas.

Daily total = 12,098.50

Off turn key total = 707.50- disposal & vacuum truck wash-out

Turn Key total = 11,391.00

Total = 12,098.50

Regards,

Garry Jones

Basic Energy Services Confidentiality Notice:

The information in this email is confidential. It is intended solely for the addressee. Access to this email by anyone else is unauthorized. If you are not the intended recipient, any disclosure, copying, distribution or any action taken or omitted to be taken in reliance on it, is prohibited and may be unlawful.

Last ticket of Job: Y N

. . ., ., .

manna, texas /971
432-563-3355
46,200,000,000

- 4	assement rexas (A) H		1.5						4.0	
•	432-563-3355					g-reu				
	45,500,000,000	** /			Date	The same	- 7	Land	7	
	10 St. 10				in in a		d'ann	1 .4	C. C.	2.11.
٩.	A THE STATE OF	Spenier Colleges.	- 2	 . ,			. *			

Job #			•				-24	the same of the same.
		*******	F	&A T	ICKET			
Customer Name		. / . /		Custome	AFE + Cus	stomer P/O #		
Malling Address	L'institution	<u> </u>	Lana &	- 12 - 12 - 12 - 12 - 12 - 12 - 12 - 12		State Zi		
Block	Section					Stole Zi	•	
	section -		Survey		: Township Tokit		Field	
ease VVICXXV	1. 1 14 1.		17	Well# /	County		State	
Veli Dapining		***************************************			4_		2 Ph. W.	ic <u>y</u>
Von Leitertage		Working De	oth: C o	'-4,000' CI	1,001 - 8,000   E 8,000	Well Type: COL	- TISTGA TOOND	S Ú OTHER
	ź			BILL	.ING			2133.5
DESCRIPTION	· RA	TE .		TOTAL	OEB WORKOVER EQUIPMENT	ojv.	RATE HE / Day / Eas	TOTAL
IQ & CHEW TK		-2:75	Pér Hç	16500	Bring Weier			·
IG'S CREW DIK	2.5 Hrs.()	275	PerHr.	622	Frésh Water 3			
UPERVISOR , .	· · ∠ · · · · · · · · · · · · · · · · ·	1000	Per Day	100000	Disposal		ļ	
RAVELTIME TK	His: (9		Por Hr.		[-[]80P			ļ.,
ravel time, "Otk EB	I Hrs. W		Perria		Coment Und		1520	250.0
) Tongs		onv.	BL PATE		Gement . TK	100	16	16000
Misc.		1+			Cement OTK		16	1600
Misc. Casing J	ack				Sáli Gel.		14	24000
Peř Diem	mon.		x 59	60000	Galcium Chloride	2	20	1800
H2S & Safety 8	Services are	. : . اکتاب	120	600	Wireline_Setup		1	1
Water, Tank	.qoqiment				Misc. Wireline 1 - 1 / 17			
Misc.					GIBP of CICR Size			
Windt Truck					Misc.			
THE THREE WITH CONTRACT CONTRA	*******				Misc.		ļ	ļ. 4i
Trenenori / Voc		1			Perforate		.l	
Transport / Vac	***************************************					······································		
] Misc.					Jet Cutter / Altro Gal Cut			<u> </u>
Misc. Workstring / Ri					☐ Misc.			
Misc. Workstring / Ri Misc.	g Mat				☐ Misc. ☐ Backnoe			
Misc	g Mat				☐ Misc. ☐ Backhoe ☐ Misc.			
Misc. Workstring / Ri Misc. Miscellaneou	g Met			pater Rid	☐ Misc. ☐ Backhoe ☐ Misc. ☐ Welder,			
Misc.  Workstring / Ri Misc.  Misc.  MiscELLANEOL  OFF Estimated Bi  SAFETY MEETING T	g Mel de 2287 40 OPIC:		E.STIII		☐ Misc. ☐ Backhoe ☐ Misc. ☐ Welder,  37/70  Úaí	ly Total 24		
Misc. Workstring / Ri Misc. Mi	g Met :::::::::::::::::::::::::::::::::::		Estiv		☐ Misc. ☐ Backhoe ☐ Misc. ☐ Welder,  37/70  Úaí			
Misc. Workstring / Ri Misc. Misc. Miscellaneot  DFF Estimated Bi AFETY MEETING T  LIDE PE	g Met  IS:  0 2287 30  OPIC:  33000		Estió		☐ Misc. ☐ Backhoe ☐ Misc. ☐ Welder,  37/70  Úaí	ly Total 24		
Miso. Workstring / Ri Miso. Miso. Miscellaneou  OFF Estimated Bi  AFETY MEETING T  ARE Properties  Wo ARE  DESCRIPTION OF W	9 Met	lor 4		TIME STA	☐ Misc. ☐ Backhoe ☐ Misc. ☐ Welder,  3/20 Dai  ARTED 4 17 11M	ly Total 74/	3 C for	
Misc. Workstring / Ri Misc. Miscellaneou  OFF Estimated Bi AFETY MEETING T  LIBER POR DESCRIPTION OF WI	9 Met  18.  d 2287 50  OPIC:  330 C	loca 1		TIME ST	☐ Misc. ☐ Backhoe ☐ Misc. ☐ Welder,  3/70 Dai  ARTED 4 A TIM	by Total 74	2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	3 42
Misc. Workstring / Ri Misc. Mi	9 Met  18:  18:  18:  18:  18:  18:  18:  18	4		TIME STA	Misc.  Backnoe  Misc.  Welder,  3/70 Dai  ARTEO 64 On TIM	ly Total 74/2	30/2	
Misc. Workstring / Ri Misc. Mi	9 Met  18:  18:  18:  18:  18:  18:  18:  18	4		TIME STA	☐ Misc. ☐ Backhoe ☐ Misc. ☐ Welder,  3/70 Dai  ARTED 4 A TIM	ly Total 74/2	30/2	3 42
Misc. Workstring / Ri Misc. Mi	9 Met  18:  18:  18:  18:  18:  18:  18:  18	4		TIME STI	Misc.  Backhoe  Misc.  Welder,  3/20  Dai  ARTEO 16-61  TIM	ly Total 74/2	30/2	3 42
Misc. Workstring / Ri Misc. Mi	9 Met  18:  18:  18:  18:  18:  18:  18:  18	4	124 L	TIME STI	Misc.   Backhoe   Misc.   Misc.   Welder,   Misc.	ly Total 74/2	30/2	3 42
Misc. Workstring / Ri Misc. Workstring / Ri Misc. Misc	9 Met  18:  18:  18:  18:  18:  18:  18:  18	4	100 - 100 -	to for so Ra star star so for	Misc.  Backnoe  Misc.  Welder,  3/70 00 0al  ARTEO 64 00 TIM  Por p 8 845  1 10 345 14  Marken 10 100 11	ly Total 74/2	30/2	3 42
Miso.  Workstring / Ri Miso.	9 Met  18:  18:  18:  18:  18:  18:  18:  18	4	100 - 100 -	TIME STI	Misc.   Backhoe   Misc.   Misc.   Welder,   Dail   Misc.   M	ly Total 74/2	30/2	3-12
Miso.  Workstring / Ri Miso.	9 Met  18:  18:  18:  18:  18:  18:  18:  18	4	100 - 100 -	TIME STI	Misc.  Backnoe  Misc.  Welder,  3/70 00 0al  ARTEO 64 00 TIM  Por p 8 845  1 10 345 14  Marken 10 100 11	ly Total 74/2	30/2	3-12
Misc. Workstring / Ri Misc. Mi	9 Mel  9 Mel  15:  0 228750  OPIC: 233000  1573 f  25 5 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9	4 - 9 4 30 4 3 0 C	(24, 1) E54 (25, 1) (25, 1) (25, 1)	TIME STI SE /d S. SES Com SES DO SES DO S	Misc.  Backhoe  Misc.  Welder,  3/70  Dal  MARTED LAGA TIM  ARTED LAGA SAGE  Purp 8 34/8  ACC SAGE 120  ACC SAGE 1	De Sopre 2	30/2	3 42
Misc. Workstring / Ri Misc. Mi	9 Mel  9 Mel  15:  0 228750  OPIC: 233000  1573 f  25 5 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9	4 - 9 4 30 4 3 0 C	(24, 1) E54 (25, 1) (25, 1) (25, 1)	TIME STI SE /d S. SES Com SES DO SES DO S	Misc.   Backhoe   Misc.   Misc.   Welder,   Dail   Misc.   M	De Sopre 2	30/2	3 42
Misc. Workstring / Ri Misc. Mi	9 Mel  9 Mel  15:  0 228750  OPIC: 233000  1573 f  25 5 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9	4 - 9 4 30 4 3 0 C	1:04 (1) 254 25 (1) 5 (m) 4 d	TIME STI	Misc.  Backhoe  Misc.  Welder.  3/7000 Dai  ARTEO Lan TIM  ARTEO Lan Side Land  ARTEO Land	De Sopre 2	30/2	3-12
Misc. Workstring / Ri Misc. Mi	9 Mel  9 Mel  15:  0 228750  OPIC: 233000  1573 f  25 5 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9	4 - 9 4 30 4 3 0 C	1:04 (1) 254 25 (1) 5 (m) 4 d	TIME STI	Misc.  Backnoe  Misc.  Welder,  3/70 Dai  ARTEO Lange TIM  Perf 1920 Ships  ACC Sold 12	De Sopre 2	30/2	3-12
Misc. Workstring / Ri Misc. Workstring / Ri Misc. Misc	9 Mel  18:  18:  18:  18:  18:  18:  18:  18	4 30 1 30 1 60 1 25 1 25 4 8 7 6	104 10 103 10 100 100 100 100 100 100 100 100 100	TIME STO  SE SE SES  SES  SES SES  SES SES  SES  SES SES  SES	Misc.  Backnoe  Misc.  Welder,  3/70 Dai  ARTED Lang Bakks  Fer Pump Bakks  Looker Sold Harman States  Accessed Harman States	DE STOPPED Z  DE	30/2	3-12
Misc. Workstring / Ri Misc. Mi	9 Mel  18:  18:  18:  18:  18:  18:  18:  18	4 30 1 30 1 60 1 25 1 25 4 8 7 6	104 10 103 10 100 100 100 100 100 100 100 100 100	TIME STI	Misc.  Backnoe  Misc.  Welder.  3/7000 Dai  ARTEO Lan TIM  ARTEO Lan Silver  Pump Blissel  Joostf. Station  Accident Sta	DE STOPPED Z  DE	30/2	3-12
Misc. Workstring / Ri Misc. Mi	g Mel  18.  d 2287 50  GPIC:  GREN	4 30 1 30 1 60 1 25 1 25 4 8 7 6	104 10 103 10 100 100 100 100 100 100 100 100 100	TIME STI	Misc.  Backnoe  Misc.  Welder,  JOSE Date of TIM  ARTED LANGE SALE  ARTED LANGE SALE	Le STOPPED Z		
Misc.  Workstring / Ri  Misc.	9 Mel  18:  18:  18:  18:  18:  18:  18:  18	4 30 1 30 1 60 1 25 1 25 4 8 7 6	104 10 103 10 100 100 100 100 100 100 100 100 100	TIME STI	Misc.  Backnoe  Misc.  Welder.  3/7000 Dai  ARTEO Lan TIM  ARTEO Lan Silver  Pump Blissel  Joostf. Station  Accident Sta	Le STOPPED Z	30 p	3 42
Misc. Workstring / Ri Workstring / Ri Misc. Misc	g Mel  g	130 130 100 100 100 100 100 100 100 100	100 100 100 100 100 100 100 100 100 100	TIME STI	Misc.  Backnoe  Misc.  Welder,  3/20 Dail  ARTEO Lana TIM  ART	ESTOPPED Z  A F. H. L. L.  A F. H. L. L.  A F. H. L. L.  A F. H. L	30 p	
Misc. Workstring / Ri Workstring / Ri Misc. Misc	g Mel  g	4 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3	100 100 100 100 100 100 100 100 100 100	TIME STI	Misc.  Backnoe  Misc.  Welder,  TIM  ARTED Lang TIM  ARTED Lan	ESTOPPED Z  A F. H. L. L.  A F. H. L. L.  A F. H. L. L.  A F. H. L	30 p	
MISC. Workstring / Ri Misc. Workstring / Ri Misc. Miscellaneou  OFF Estimated Bi  SAFETY MEETING T  LIDE Pro  NO ACC. DESCRIPTION OF W  ROAD  LIDE Pro  LIDE Pro  NO ACC. DESCRIPTION OF W  REASON FOR ADDITION  OPPERATOR  DEBRICK G	g Mel  g	130 130 100 100 100 100 100 100 100 100	100 100 100 100 100 100 100 100 100 100	TIME STI	Misc.  Backnoe  Misc.  Welder,  3/20 Dail  ARTEO 16-62 TIM  ARTEO 16-62 TIM  ACC 500 TO SECULOR  SECTION  Emp. # Revenue Hours  2 2 5 5	ESTOPPED Z  A F. H. L. L.  A F. H. L. L.  A F. H. L. L.  A F. H. L	30 p	
Misc. Workstring / Ri Workstring / Ri Misc. Misc	9 Mel  9 Mel  15:  15:  15:  15:  15:  15:  15:  15	130 130 100 100 100 100 100 100 100 100	1.04 1) 2.54 2.54 2.54 2.56 2.60 2.60	TIME STI	Misc.  Backnoe  Misc.  Welder.  3/7000 Dail  ARTEO 16-62 TIM  For p 8 3/45  A 100 16-62  A 100 1	ESTOPPED Z  A F. H. L. L.  A F. H. L. L.  A F. H. L. L.  A F. H. L	30 p	

BASIC EVERGY SERVICES PERVICE HEPRESENTATIVE

CUSTOMER / AGENT

## Gonzales, Elidio L, EMNRD

:om:

Jones, Garry [Garry.Jones@basicenergyservices.com]

Sent:

Wednesday, May 23, 2012 5:11 PM

To:

Gonzales, Elidio L, EMNRD; markwhitaker@state.nm.us; maxey.brown@state.nm.us;

burrowsmarvin@rocketmail.com; Eggleston, Gary; Minear, Randall

Subject:

P&A job

5-23-2012 Mexico 'U' # 3

Road crew to location, held safety meeting

Open well

RU wireline & tag cmt. plug @ 1450 ft. Perf. @ 200 ft. RD wireline

PU perf. sub & 29 its. to 956 ft. Spot 25 sks. cmt. across jole in 5 ½ csq. (247 ft.) LD 29 its.

NDBOP & NUWH

Est. circ. down 5 ½ x 8 5/8 csg. to surface.

Pump 60 bbls. cmt. down 5 ½ x 8 5/8 csg to surface.

Cut-off well-head & anchors. Clean location. Install dry hole marker.

RDMO plugging equipment

Daily Total = 10,213.00

Turn key total = 8345.00 Off turn key = 1868.00

½ Supervisor charge for extra day to complete well. 500.00

Disposal cost = 693.00 25 sks. cmt. = 400.00 Pig & crew = 275.00 tal = 1868.00

Hegards,

Garry Jones

Mexico "U" # 1

Road crew to location, held safety meeting.

MI rig mat. MIRU plugging rig.

MI steel pit, tbg. trl. Frac tank, cmt. pump.

Blow down well to steel pit.

NDWH & NUBOP

Call out vacuum truck to hole vacuum on 5 ½ csg.

PU 5 ½ pkr. & 48 jts. to 1583 ft.

Load hole & set pkr.

Est. Ing. Rate.

Pumping into well @ 1 1/2 bbl./min. @ 1000 psi. Pumped 40 bbls. BW

Will pump cement in am.

Shut well in & road crew to Hobbs, NM

Daily Total = 4075.00

Regards,

Garry Jones

Basic Energy Services Confidentiality Notice:

The information in this email is confidential. It is intended solely for the addressee. Access to this email by anyone else is unauthorized. If you are not the intended recipient, any disclosure, copying, distribution or any action taken or omitted to a taken in reliance on it, is prohibited and may be unlawful.

5-23-2012