
State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL C	ONSERV.	ATION DIVISION		
<u>DISTRICT I</u> 1625 N. French Dr. , Hobbs, NM 88240	HOBBS OCD		St. Francis Dr. NM 87505	WELL API NO. 30-025-05493	
DISTRICT II		~,		5. Indicate Type of Lease	
1301 W. Grand Ave, Artesia, NM 88210	JUN 2 4 2013			STATE X	FEE
DISTRICT III				6. State Oil & Gas Lease No).
1000 Rio Brazos Rd, Aztec, NM 87410					
SUNDRY NOTICES AND REPORTS ON WELLS				7. Lease Name or Unit Agre	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)			North Hobbs (G/SA) Ur	nit '	
1. Type of Well:	APPLICATION FOR FER	WITT (FOINT C-	101) for such proposals.)	Section 25 8. Well No. 744	
Oil Well X Gas Wg/l Other				744	/ /
Name of Operator Occidental Permian Ltd.			,	9. OGRID No. 157984	
3. Address of Operator				10. Pool name or Wildcat	Hobbs (G/SA)
HCR 1 Box 90 Denver City, 4. Well Location	TX 79323				
Unit Letter P : 330	Feet From The	South	Line and 330 Feet	From The East	Line
Section 25	Township	18-S	Range 37-E	NMPM	Lea County
	11. Elevation (Show 3661' RKB	whether DF, Ri	KB, RT GR, etc.)		
Pit or Below-grade Tank Application	or Closure				
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water					
Pit Liner Thickness mil	Below-Grade Tank:	Volume	bbls; Construction Mat	erial	
	eck Appropriate Box to	o Indicate Na	ture of Notice, Report, or C	other Data SEQUENT REPORT (OF:
PERFORM REMEDIAL WORK	PLUG AND ABAND	ои 🦳	REMEDIAL WORK	X ALTERI	NG CASING
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRILLING OPN	NS. PLUG 8	ABANDONMENT
PULL OR ALTER CASING	Multiple Completion		CASING TEST AND CEMEN	т ЈОВ	
OTHER:	•		OTHER:		
13. Describe Proposed or Completed	0 - 1 - (01 - 1 - 1 - 1	11			<u> </u>
proposed work) SEE RULE 11 1. RUPU & RU. 2. RU wire line & perforate 3. NU BOP/ND wellhead. 4. POOH and lay down ESI 5. RU wire line & run casin 6. R1H w/bit. Tag @4407'.	o3. For Multiple Completing @4156'. RD with a completion of the co	ions: Attach v			
7. RU wire line & perforate	casing at 4187-4202', 4	208-4284' @	4 JSPF. RD wire line.		
8. RIH w/PPI packer set @4054°. RU acid truck and perform acid job in 2 stages w/1450 gal of PAD acid. RD acid truck. RU pump truck and pump scale squeeze w/100 gal of 6490 chemical in 100 bbl of fresh water. Flush w/100 bbl 10# brine. POOH w/PPI packer.					
9. RIH w/ESP equipment so				10# brine, POOH W/PPI	раскег.
ND BOP/NU wellhead.	·				
11. RDPU & RU. Clean loca	ation and return well to p			2013 RD 03/02/2013	
I hereby certify that the information above constructed or	•			المراجع والمرسون ويتواجعا برواجة والمراجع والمراجع والمراجع والمراجع	, han hann haill ha
	•	best of my know	ledge and belief. I further certify t	nat any pit or below-grade tank	c has been/will be
closed according to NMOCD guideling	is true and complete to the b		ledge and belief. I further certify t or an (attached) alternative plan		K nas been/will be
closed according to NMOCD guideling	e is true and complete to the b		or an (attached) alternative	OCD-approved	
SIGNATURE MUNA	e is true and complete to the b		or an (attached) alternative	OCD-approved	TE <u>06/20/2013</u>
SIGNATURE TYPE OR PRINT NAME Mendy A	e is true and complete to the b	permit	or an (attached) alternative plan TITLE Administrative a	OCD-approved Associate DA TELEPHONE NO	TE <u>06/20/2013</u> O. <u>806-592-6280</u>
SIGNATURE Mendy A	e is true and complete to the bases, a general particular of the bases	permit	or an (attached) alternative plan TITLE Administrative a	OCD-approved Associate DA TELEPHONE NO	TE <u>06/20/2013</u>

JUL 0 8 2013

Work Plan Report for Well:NHSAU 744-25



Survey Viewer