

Submit 1 Copy To Appropriate District Office
 District I - (575) 393-6161
 1625 N. French Dr., Hobbs, NM 88240
 District II - (575) 748-1283
 811 S. First St., Artesia, NM 88210
 District III - (505) 334-6178
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV - (505) 476-3460
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources
OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

Form C-103
 Revised July 18, 2013

HOBS OCO
JUL 25 2013
RECEIVED

WELL API NO. 30-025-07916
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. 16881
7. Lease Name or Unit Agreement Name SOUTH CARTER SA UNIT
8. Well Number 101
9. OGRID Number 009338
10. Pool name or Wildcat CARTER; SAN ANDRES, SOUTH
4. Well Location Unit Letter J : 1650 feet from the SOUTH line and 330 feet from the EAST line Section 5 Township 18S Range 39E NMPM County LEA
11. Elevation (Show whether DR, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well Gas Well Other

2. Name of Operator GREAT WESTERN DRILLING

3. Address of Operator PO BOX 1659 MIDLAND, TX 79702

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY SUSPEND OPERATIONS <input type="checkbox"/> APPROVED FOR PLUGGING OF WELL BORE ONLY <input type="checkbox"/> LIABILITY UNDER BOND IS RETAINED PENDING RECEIPT OF C-103 (SPECIFICALLY FOR SUBSEQUENT REPORT OF WELL PLUGGING) WHICH MAY BE FOUND AT OCD WEB PAGE <input type="checkbox"/> UNDER FORMS <input type="checkbox"/> www.emnrd.state.nm.us/ocd <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> P AND A <input checked="" type="checkbox"/> CASING/CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/>
---	--

Proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of completion or recompletion). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

05/16/13 POH LD rods & pump. RU & pump 120 bbls 9# wtr w/31 sx of salt gel. Pumped 27 bbls bbls before well circ. RU & POH w/2 3/8" tbg.

05/17/13 ND WH & csg head. RU Warrior & run CBL f/1700' to surface. Look like cmt f/1420 to surface. NU 5 1/2" lift sub. Pull 50K on pipe moved. Pulled to 120K to get slips. Pipe move 3" f/50K to 120K. RU Run free point 1000', 8000', 750', 713', 100% stuck. 683 60% free, 660', 653', 100% free. RD WL. Talked w/Maxey G. Brown, OCD. Have new proposal to plug well Spot 30 sx plug @ 5170' & tag. Perf @ 1060' 30 sx & tag. 400' perf, cmt to surface. TIH w/2 3/8" tbg to 2174'. Pump 30 sx, pull 25 stands & reverse out.

05/20/13 TIH, tag plug @ 5064' (101') plug. Pull & LD 2 3/8" tbg to 2060' then POH standing back tbg. RU Warrior & perf 5 1/2" csg @ 2060' & 400'. RD WL. TIH to 1854' w/AD-1 pkr set & get pump in rate, 900 psi @ 1/2 bpm. Pump 30 sx plug. Pumping @ 800 psi until last 2 bbls psi went to 1100 psi. After 5 mins press went to 0 psi, 8 5/8" on vacuum. POH. Pkr swabbed hole when POH. Had Red Bed in pkr rubbers. WOC 2 hrs. TIH to 2135' did not find any cmt 75' below perf. POH. Run 5 1/2" pkr to 40' below perf @ 2060', press to 800 psi, held okay. Pull pkr back to 1854', pump 30 sx plug @ 900 psi @ 1/2 bpm. Spot cmt to pkr. SIP to 200 psi in 20 mins, to 0 psi in 35 mins. TOH w/pkr.

05/21/13 TIH w/tbg, tag plug @ 2036' (24') plug. Talk w/NMOCD said pump 25 sx & tag. Pump plug & WOC 3 hrs. TIH, tag plug @ 1838' (198') plug total, plug @ 2060' (232'). POH LD 2 3/8" tbg. RU & pump 110 sx plug @ surface. Pump down 5 1/2" csg up 8 5/8" perf @ 400' to surface. RD plugging equipment.

Spud Date: 02/28/1957 Rig Release Date: 05/21/2013

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Louie M Cure TITLE: CONSULTANT DATE July 23, 2012

Type or print name LOUIE M. CURE E-mail address: engineer@gwdc.com PHONE: 432-682-5241

APPROVED BY: [Signature] TITLE: Dist Mgr DATE: 7-30-2013

Conditions of Approval (if any):

JUL 31 2013