

State of New Mexico
Energy, Minerals and Natural Resources Department
HOBBS OCD

Form C-103
Revised 5-27-2004

FILE IN TRIPLICATE

DISTRICT I

1625 N. French Dr., Hobbs, NM 88240

DISTRICT II

1301 W. Grand Ave, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd, Aztec, NM 87410

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
AUG 28 2013

WELL API NO. 30-025-07464
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name North Hobbs (G/SA) Unit Section 30
8. Well No. 121
9. OGRID No. 157984
10. Pool name or Wildcat Hobbs (G/SA)
11. Elevation (Show whether DF, RKB, RT GR, etc.) 3650' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐
2. Name of Operator Occidental Permian Ltd.
3. Address of Operator HCR I Box 90 - Denver City, TX 79323
4. Well Location Unit Letter <u>E</u> : <u>2310</u> Feet From The <u>North</u> Line and <u>330</u> Feet From The <u>West</u> Line Section <u>30</u> Township <u>18-S</u> Range <u>38-E</u> NMPM Lea County
5. Pit or Below-grade Tank Application ☐ or Closure ☐ Pit Type _____ Depth of Ground Water _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____ Pit Liner Thickness _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☒
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: _____	PLUG & ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: _____

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. RUPU & RU.
2. ND BOP/NU wellhead.
3. RU wire line & perforate tubing @3726'. RD wire line.
4. POOH and lay down ESP equipment.
5. RIH w/new ESP equipment on 114 jts of 2-7/8" tubing. Intake set @3762'.
6. ND BOP/NU wellhead.
7. RDPU & RU. Clean location and return well to production.

RUPU 07/26/2013
RDPU 07/29/2013

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or

closed according to NMOCD guidelines ☐ , a general permit ☐ or an (attached) alternative OCD-approved plan ☐


SIGNATURE Mendy A Johnson TITLE Administrative Associate DATE 08/27/2013
TYPE OR PRINT NAME Mendy A Johnson E-mail address: mendy_johnson@oxy.com TELEPHONE NO. 806-592-6280

For State Use Only

APPROVED BY [Signature] TITLE Dist. Mgr DATE 08-29-2013
CONDITIONS OF APPROVAL IF ANY:

August 26, 2013

Work Plan Report for Well:NHSAU 121-30



Survey Viewer