Submit 1 Copy To Appropriate District	State of New Mexico		Form C-103
Office <u>District 1</u> – (575) 393-6161	Energy, Minerals and Natural Re	esources	Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240	D	WELL API NO.	
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178	OIL CONSERVATION DIV	ISION 30-025-23277 5. Indicate Type	of Lanca
District III - (505) 334-6178	1220 South St. Francis D	Or. STATE	FEE X
1000 Rio Brazos Rd., Aztec, NM 87410 1 8 2 <u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505	6. State Oil & C	
1220 S. St. Francis Dr., Santa Fe, NM 87505			
	AND REPORTS ON WELLS	7. Lease Name	or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		CK TO A North Hobbs (_ / 1
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		Section 28	
1. Type of Well: Oil Well 🛛 / Gas Well 🔲 Other		8. Well Number	132
2. Name of Operator / Occidental Permian Ltd.		9. OGRID Num	ber: 157984
3. Address of Operator		10. Pool name o	or Wildcat
2611 State Hwy 214 Denver City,	TX 79323	Hobbs (G/SA)	/
4. Well Location			
Unit LetterL_:1880_	feet from theSouth line and	750feet from theW	/estline
Section 28 Township 18S Range 38-E NMPM Lea County			
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
3649' GL			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTE	NTION TO:	SUBSEQUENT RE	EPORT OF:
PERFORM REMEDIAL WORK ☑ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐			
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ P AND A			P AND A
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB			
DOWNHOLE COMMINGLE			
OTHER:	П ∣отн	ER:	. П
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of			
proposed completion or recompletion. During this procedure we plan to use			
the closed-loop system with a steel			
1. RUPU and POOH W/Beam equipment tank and haul contents to the required			
2. C/O and treat if necessary disposal per ODC Rule 19.15.17			
3. Run ESP equipment			
4. RDPU and clean location	•		
	• •		
والمستود والما المستفاد ويدودون والمستواة المستعود والمتابعة المستعود المستعودة المستع		ويستنقص فطالها المستسعدون والمالون الشاعد بالمستعد ومستقط والماسوي	
Spud Date:	Rig Release Date:		
			
I hereby certify that the information above	ve is true and complete to the best of r	my knowledge and belief.	
SIGNATURE Steve Snow TITLE Lift Specialist DATE 9/11/2013			
Type or print nameSteve Snead E-mail address: <u>steve_snead@oxy.com_PHONE</u> : <u>806-592-6312</u>			
For State Use Only			
APPROVED BY DATE 9-19-2013			
APPROVED BY	PITLE WIS!	IVKIZ D.	ATE 7-19-2013
Conditions of Approval (if any):			