orm 3160-5		ΙΝΙΤΕΊ ΥΤΑ ΤΕΥ		0		FORM	APPROVED
August 2007) DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT				OCD Hobbs		OMB NO. 1004-0135 Expires: July 31, 2010	
	NOTICES AND REPO	ELLS		5. Lease Serial No. NMLC029405B			
Do abai	not use thi ndoned we	is form for proposals to II. Use form 3160-3 (API	drill or to re)) for such p			6. If Indian, Allottee of	or Tribe Name
SUB	MIT IN TRI	PLICATE - Other instruc	tions on rev	verse side.	OBBS OC	7. If Unit or CA/Agree	ement, Name and/or No.
1. Type of Well		SEP 1 9 2013		8. Well Name and No. RUBY FEDERAL 14			
2. Name of Operator CONOCOPHILLIP		Contact:	SUSAN B M aunder@cono		<u> </u>	9. API Well No. 30-025-41010-0)0-X1
3a. Address 3300 N "A" ST BLDG 6 MIDLAND, TX 79705			3b. Phone No. (include area code) Ph: 432-688-6913 Fx: 432-688-6017			10. Field and Pool. or Exploratory MALJAMAR	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			17. 402 000 0017			11. County or Parish, and State	
Sec 17 T17S R32E NWSE 2160FSL 2237FEL					LEA COUNTY, NM		
12. CH	IECK APPI	ROPRIATE BOX(ES) TO	INDICATE	NATURE OF	NOTICE, R	L EPORT, OR OTHE	R DATA
TYPE OF SUBMI	SSION	TYPE OF ACTION					
🛛 Notice of Intent		□ Acidize □ Dee				ion (Start/Resume)	Water Shut-Off
Subsequent Repo	rt	Alter Casing	—	cture Treat	Reclam		Well Integrity
				Construction Recom		arily Abandon	Other Change to Original A
-		Convert to Injection			□ Vater I	10	
Attach the Bond under following completion of	which the wor of the involved leted. Final At	ally or recomplete horizontally, p rk will be performed or provide operations. If the operation res bandonment Notices shall be file inal inspection.)	the Bond No. or ults in a multipl	n file with BLM/BIA le completion or rec	 Required su ompletion in a 	bsequent reports shall be new interval, a Form 316	filed within 30 days 0-4 shall be filed once
ConocoPhillips Co regarding circulation	ng cement te I without per	pectfully requests a variand o surface of the production forming remedial cement	n casing. A v	ariance is sough	nt to continue	e ure	ROVED
Wednesday, July during the cement through other mea	15th, 2013, job, but did ins and doci	nent to surface during the we cemented 5-1/2" 17# L not get cement returns to umentation provided to BL	-80 LTC pro surface. We M under sep	duction casing. Il integrity was d parate cover.	We had full lemonstrated		. 7 .00 \
		n records of monitorin	ng the pres	sure on the a	nnulus.	BUREA	U U USBAD ME
Operator t				WFANT, Sentio	me nobbs	i System 🖉	
Committed to AFMSS for processing by KU Name(Printed/Typed) SUSAN B MAUNDER				Title SENIOR REGULATORY SPECIALIST			
Signature	(Electronic S	Submission)		Date 09/16/2	2013		
		THIS SPACE FO	R FEDERA			SE	<u> </u>
							Date 00/17/2012
Approved By EDWARD FERNANDEZ conditions of approval, if any, are attached. Approval of this notice does not warrant or ertify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.				TitlePETROLEUM ENGINEER Date 09/17/2013			
				Office Hobbs			
tle 18 U.S.C. Section 100 States any false, fictitiou	or translutent s	U.S.O. Section 1212, make it a c statements of representations as	rine for any pe to any matter w	erson knowingly and ithin its jurisdiction.	l willfully to m	ake to any department or	agency of the United
**		ISED ** BLM REVISED	** BLM B				
			201111			SEP 2	
						JEL 2	

J.



32. Additional remarks, continued

In accordance with BLM requests, we performed and submitted documentation on the following: ? a CBL log, ? monitored backside annulus pressure during frac?ing operations, and ? pressure tested annulus.

· Frank .

Based on information gathered and submitted, we concluded that cement lapped the surface casing shoe to provide good mechanical integrity. Therefore, we propose no further remediation is necessary and request variance approval.

A pressure gauge will be maintained on the backside annulus and monitored for pressure. In the event pressure is detected ConocoPhillips will take appropriate action.