Submit 3 Copies To Appropriate District State of New Mexico Form C-103 Office Energy, Minerals and Natural Resources March 4, 2004 District I WELL API NO. 1625 N. French Dr., Hobbs, NM 88240 District II 30-025-37032 **OIL CONSERVATION DIVISION** 1301 W. Grand Ave., Artesia, NM 88210 5. Indicate Type of Lease District III 1220 South St. Francis Dr. STATE | FEE X 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 6. State Oil & Gas Lease No. District IV 1220 S. St. Francis Dr., Santa Fe, NM 34389 87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH T. D. Pope 35 PROPOSALS.) 8. Well Number 1. Type of Well: 2 Oil Well X Gas Well Other 2. Name of Operator 9. OGRID Number Platinum Exploration, Inc. 227103 3. Address of Operator 10. Pool name or Wildcat 550 W. Texas Ave, Ste 500, Midland, TX 79705 Denton; Devonian 4. Well Location BHL P 1070 330 E Unit Letter 2550 feet from the line and 330 feet from the Ε line Section 35 Township 14S Range 37-E **NMPM** Lea County 11. Elevation (Show whether DR. RKB, RT, GR. etc.) 3804' GR Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached) Sect Twp Rng Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water______ Below-grade Tank Location UL_____Sect___ Twp feet from the _____line and ____ ____feet from the ___ line 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data SUBSEQUENT REPORT OF **NOTICE OF INTENTION TO:** PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ALTERING CASING PLUG AND **TEMPORARILY ABANDON CHANGE PLANS** COMMENCE DRILLING OFNS. **ABANDÖNMENT** PULL OR ALTER CASING **MULTIPLE** CASING TEST AND COMPLETION **CEMENT JOB** OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 06/14/05-07/09/05 RU PU. ND WH & NU BOP. TIH & tag Arrowpak packer @12010'. Retrieve pkr. RDMO PU. RU Allens. TIH w/cmt ret & set @ 12003'. RU Schlumberger, test lines. Pump 1160 sx cmt - 15.6# cmt sqz 0.9 BPM @ 1500 psi. RD Schlumberger. TIH & PU swivel. Drill cmt retainer from 12296'-12314'. Try to drill CIBP from 12314'-12316'. Drill out CIBP. RIH & tag TD, circ cln. Run GR & CCL. PU swivel & mill 12256'12569'. RU Gyro Data & RIH w/Gyro. Drill from 12569'-14467'. RD. 07/13/05-07/19/05 MIRU Basic WS. PU Sprinkler system. RIH w/pkr to 12392', bottom of sprinkler system @ 14418'. RU Schlumberger & load BS w/250 bbls FW & test to 1000 psi-OK. Acdz w/ 15,000 gals 15% NEFE. RD Schlumberger. RIH & set pkr @ 12010'. RIH w/ ESP equipment. ND BOP. NU WH. Clean location & RDPU. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or belowgrade tank has been/will be constructed or closed according to NMOCD guidelines [], a general permit [] or an (attached) alternative OCD-approved plan []. **SIGNATURE** TITLE Agent DATE 07/27/05 Type or print name Gloria Holcomb E-mail address: gholcomb@t3wireless.com Telephone No. (432) 687-1664 (This space for State use)

DATE OCI 14

PETROLEUM ENGINEER

APPPROVED BY

Conditions of approval, if any