

Submit 1 Copy To Appropriate District Office
 District I - (575) 393-6161
 1625 N. French Dr., Hobbs, NM 88240
 District II - (575) 748-1283
 811 S. First St., Artesia, NM 88210
 District III - (505) 334-6178
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV - (505) 476-3460
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Minerals and Natural Resources

Form C-103
 August 1, 2011

RECEIVED
DEC 26 2013
CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

WELL API NO. 30-025-10656
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. 301940
7. Lease Name or Unit Agreement Name Skelly Penrose B Unit
8. Well Number 036
9. OGRID Number 012444
10. Pool name or Wildcat LanglieMattix (37240)

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well Gas Well Other

2. Name of Operator
Providence Energy Services, Inc. dba Kelton Operating

3. Address of Operator
PO Box 928, Andrews, TX 79714-0928

4. Well Location
 Unit Letter **P** : **990 660** feet from the **S** line and **990 660** feet from the **E** line
 Section **6** Township **23-S** Range **37-E** NMPM County **Lea**

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check to indicate Nature of Notice, Report or Other Data

PERFORMED Approved for Plugging of well bore only.
 Liability under bond is retained pending receipt of C-103 (Specifically for Subsequent Report of Well Plugging) which may be found at OCD web page under forms/
www.emnrd.state.nm.us/oocd

OTHER:

SUBSEQUENT REPORT OF:
 REMEDIAL WORK ALTERING CASING
 COMMENCE DRILLING OPNS. P AND A
 CASING/CEMENT JOB

proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

12/12/13 MIRU plugging equipment. Dug out cellar. NU BOP. RIH w/ tbg and tagged CIBP @ 3560'. Circulated hole with mud laden fluid. Spotted 25 sx cement @ 3560-3460. POH to 2726'. Spotted 140 sx cement @ 2726-1400. POH w/ cement WOC. 12/13/13 Tagged plug @ 1397'. Spotted 25 sx cement @ 1357-1200, (per Mark Whitaker). POH w/ tbg. Perf'd csg @ 401'. Sqz'd 90 sx cement @ 401 to surface. ND BOP. Rigged down and moved off. 12/17/13 Moved in Backhoe and welder. Dug out cellar. Cut off wellhead. Welded on Above Ground Dry Hole Marker. Backfilled cellar. Cut off deadmen. Cleaned location and moved off.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Dale Kelton* TITLE PRESIDENT DATE 12-23-13

Type or print name DALE KELTON E-mail address: providenceenergy@subdenlink.net PHONE: 432-661-1364

APPROVED BY: *Mary Brown* TITLE Compliance Officer DATE 12/27/2013

Conditions of Approval (if any)

DEC 30 2013