Submit Copy To Appropriate District Office District ! – (575) 393-6161	Francis Minimula and National December		Form C-103 Revised July 18, 2013	
1625 N. French Dr., Hobbs, NM 88240		WELL API NO. 30-025-03216		
811 S. First St., Artesia, NM 88210			5. Indicate Type of Lease	
District III - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 District IV - (505) 476-3460 1220 South St. Francis Dr. Santa Fe, NM 87505			X	
1220 S. St. Francis Dr., Santa Fe, NM		6. State Oil & Gas Lease No.		
87505 SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreeme	nt Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			East Pearl Queen Unit	
1. Type of Well: Oil Well Gas Well Other Injection Well			8. Well Number 18	·
2. Name of Operator State of NM formerly Xeric Oil & Gas Corp			9. OGRID Number	
3. Address of Operator			10. Pool name or Wildcat Pearl Queen	
1625 N French Drive 4. Well Location	Hobbs, NM 8824	0	Pearl Queen	
Unit Letter B: 990 feet from the North line and 1650 feet from the East line				
Section 27 Township 19S Range 35E NMPM County Lea				
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
12. Check A	Appropriate Box to Indicate N	ature of Notice,	Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK			K ALTERING CASING	
TEMPORARILY ABANDON L PULL OR ALTER CASING	TEMPORARILY ABANDON			Z¥
DOWNHOLE COMMINGLE				
CLOSED-LOOP SYSTEM OTHER:		OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of				
proposed completion or recompletion.				
5/31/2013 MIRU Equipment				
6/3/2013 GIH open ended. Tag CIBP at 4642'. Spot 25 sx on CIBP.				
6/4/2013 Tagged cmt at 4342'. Circ mud laden fluid and pressure test				
csg. POOH to 3385'. Spot 25 sx cmt. POOH to 1786'. Spot 25 sx cmt.				
POOH to 376'. Fill to surface w/ cmt. Install dry hole marker.				
<u></u>				
Spud Date:	Rig Release Da	te:		
I hereby certify that the information	above is true and complete to the be	est of my knowledge	e and belief.	
\(\(\) \(
SIGNATURE Washer title Compliance Officer DATE 02/13/2014				
Type or print name	E-mail address		PHONE:	
For State Use Only				
APPROVED BY: Maly Stown TITLE Compliance Office DATE 2/14/2014.				
Conditions of Approval (if any):				
V				W P J W
FEB :				014 0
			₩ ८० % • • • • • • • • • • • • • • • • • •	