Submit 1 Copy To App. Office		State of New Mexi Energy, Minerals and Natura			Form C-103 Revised July 18, 2013			
1625 N. French Dr., Hobbs, NM 88240					WELL API NO.			
District II – (575) 748-1283 811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION					30-025-03295			
District III - (505) 334-6178 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410					5. Indicate Type of Le STATE	rase FEE 🔀		
District IV – (505) 476-3460 Santa Fe, NM 87505 1220 S. St. Francis Dr., Santa Fe, NM 87505					6. State Oil & Gas Lea			
SUNDRY NOTICES AND REPORTS ON WELLS					7. Lease Name or Uni	t Agreement Nam	ie	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)					East Pearl Queen Unit			
1. Type of Well: Oil Well Gas Well Other					8. Well Number 39			
2. Name of Operator State of NM formerly Xeric Oil & Gas Corp.					9. OGRID Number			
3. Address of Operator					10. Pool name or Wild	dcat	\neg	
1625 N French Drive Hobbs, NM 88240					Pearl Queen			
4. Well Location	Z\ .	660 feet from the N	To so to b	1:	560 feet from the	. Fact ii		
Unit Letter A : 660 feet from the North line and 660 feet from the East line Section 34 Township 19S Range 35E NMPM County Lea								
11. Elevation (Show whether DR, RKB, RT, GR, etc.)								
$R_{m{p}}$								
	10 01 1 4			C21	D O.I . D .			
	12. Check A	ppropriate Box to Indi	cate Na	ature of Notice,	Report or Other Data	a		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:								
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR						ERING CASING	_	
TEMPORARILY ABANDON						ND A	X	
DOWNHOLE COMMINGLE								
CLOSED-LOOP S OTHER:	YSTEM		_	OTHER:				
13. Describe p of starting	any proposed wo	eted operations. (Clearly s	tate all p	ertinent details, and	d give pertinent dates, inc mpletions: Attach wellbo	cluding estimated ore diagram of	date	
	mpletion or recompletion. MIRU Basic Plugging Services.							
5-11-13	GIH w/ tbg. Tag at 4433'. Circ mud laden fluid. Spot 25 sx cmt							
at 4433'.								
5-13-13	Tag at 4272'. Perf at 3400'. Unable to pump in. GIH to 3462'.							
3 13 13	Spot 25 sx cmt. WOC. Tag at 3312'.							
5-14-13	Perf at 1800'. Sqz w/ 25 sx cmt. WOC. Tag at 1735'. Perf at							
9 14 19		250'. Circ 100 sx cmt to surface inside/outside 5 1/2" csq.						
5-15-13 Top well off w/ cmt. RDMO. Install dry hole marker.								
3-13-13	tob well	OII W/ CIIIC. RDI	iO. II	istail dry	noie marker.			
	Mes	·		 				
Spud Date:		Rig Rel	ease Dat	te:				
-		· · · · · ·						
I hereby certify that	the information a	above is true and complete	to the be	est of my knowledg	e and belief.			
SIGNATURE	alw	TITLE	Con	ystiance (Officer DATE	02/13/20	14	
Type or print name		E-mail	address		PHONE	?•	1	
For State Use Only								
APPROVED BY: Alex Strown TITLE Compliance Office DATE 2/14/2014								
Conditions of Approval (if any):								
w ska								
FEB 18 2014 X								
					I ED 1	0 2014	•	