Submit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103
<u>District I</u> – (575) 393-6161	District I – (575) 393-6161 Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240 District H. (575) 748-1383		Revised August 1, 2011 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283			30-025-34980
811 S. First St., Artesia, NM 88210	OIL CONSERVATION I		5. Indicate Type of Lease
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE STEE
<u>District IV</u> – (505) 476-3460	Santa Fe, NM 875	505 .	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			
SUNDRY NOT	ICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPO	SALS TO DRILL OR TO DEEPEN OR PLUC CATION FOR PERMIT" (FORM C-101) FOR	G BACK-TO A	North Hobbs (G/SA) Unit
PROPOSALS.)		S OCD	Section 33
1. Type of Well: Oil Well	Gas Well Other		8. Well Number
2. Name of Operator	AAAD 6	2014	513 9. OGRID Number: 157984
Occidental Permian Ltd.	WAR	9 1 2017	9. OGRID Number: 137984
3. Address of Operator			10. Pool name or Wildcat
2611 State Hwy 214 Denver C	ity, TX 79323 REC	EIVED	Hobbs (G/SA)
4. Well Location			
Unit Letter L: 1659 feet from the South line and 918 feet from the West line			
Section 33	Township 18S Rang	ge 38E	NMPM Lea County
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
3637' GL			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK ☑ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐			
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ P AND A ☐			
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB			
DOWNHOLE COMMINGLE			
OTHER: Any angle to a control of their and a following the control of t			
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of			
proposed completion or rec			
	Ţ	During this prod	cedure we plan to use
1 PUDIL and BOOH W/ESD.		the closed-loop	system with a steel
tank and haul C			ontents to the required
3. Run ESP equipment disposal per ODC Rule 19.15.17			OC Rule 19.15.17
4. RDPU and clean location			
		41	
Spud Date:	Rig Release Date	e:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE TITLE Lift Specialist DATE 3/20/2014 .			
Type on print name Staya Spand Email address: staya spand@ayy cam DUONE, 906 500 6212			
Type or print name Steve Snead E-mail address: steve snead@oxy.com PHONE: 806-592-6312			
APPROVED BY: Water Stown TITLE Compliance of the Date 3/27/2014			
Conditions of Approval (if any):			