<ul> <li>Submit al Copy To Appropriate Distri Office</li> </ul>	State of New Me	exico		Form C-103
District I – (575) 393-6161	Energy, Minerals and Natu	ral Resources		ed July 18, 2013
1625 N. French Dr., Hobbs, NM 882	10		WELL API NO.	
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION	DIVISION	30-025-11301	
District III – (505) 334-6178	1220 South St. Fran		5. Indicate Type of Lease	- 🖂
1000 Rio Brazos Rd., Aztec, NM 874	Santa Fe, NM 87		STATE FEE	
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	•	303	6. State Oil & Gas Lease No.	,
87505				
SUNDRY 1	NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agree	ement Name
	ROPOSALS TO DRILL OR TO DEEPEN OR PLUCATION FOR REPMIT! (FORM C. 101) FO			
PROPOSALS.)	PPLICATION FOR PERMIT" (FORM C-101) FO		LANGLIE JAL UNIT	
1. Type of Well: Oil Well	Gas Well Other INJECTOR	710003 000	8. Well Number 17	
2. Name of Operator			9. OGRID Number	
	Y RESERVES OPERATING LP 🖊 🖡	PR 1 1 2014	240974	
3. Address of Operator			10. Pool name or Wildcat	
	10848, MIDLAND, TX 79702	RECEIVED	LANGLIE MATTIX;7RVRS	-Q-G
4. Well Location		KECLIVED		
Unit Letter <u>J</u>	: 1980 feet from the SOUT	<u>H line and1</u>	930 feet from the <u>EAS</u>	STline
Section 31	Township 24S	Range 37E	NMPM Co	unty LEA
	11. Elevation (Show whether DR)	RKB, RT, GR, etc.,	)	
	3244' DR			
12. Che	ck Appropriate Box to Indicate N	ature of Notice,	Report or Other Data	
			•	_
	F INTENTION TO:		SEQUENT REPORT OF	
PERFORM REMEDIAL WOR	<del>_</del>	REMEDIAL WOR	<del></del> -	GCASING _
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI	<del></del>	
PULL OR ALTER CASING		CASING/CEMEN	TJOB 📙	
DOWNHOLE COMMINGLE				
CLOSED-LOOP SYSTEM OTHER:		OTHER:		
	completed operations. (Clearly state all p	<u> </u>	d give pertinent dates, including	estimated date
of starting any propose	ed work). SEE RULE 19.15.7.14 NMAC	For Multiple Co.	mpletions: Attach wellhore diag	gram of
proposed completion of				5
1 1				
				,
SEE ATTACHED P&	A PROCEDURE ALONG WITH CUR	RENT & PROPOSI	ED WELLBORE DIAGRAMS-	
			•	
•				
				•
Spud Date:	Rig Release Da	ate:		
<u> </u>				
I hereby certify that the information	tion above is true and complete to the b	est of my knowledg	e and belief.	
TOWN THE TOWN		DEGLE AMONYAM	D	
SIGNATURE (X WWW LA	TITLE	REGULATORY T	ECHDATE_04/10/2	014
Type or print name I AID	A DINIA E mail address:	lpina@legacylp.co	от DUONIE. 422	680 5200
Type or print name <u>LAUR</u> For State Use Only A	A PINA E-mail address: _	трина(шледасугр.сс	om PHONE: _432-	·069-3200
TOI State Ose Offi	MK	11		[]
APPROVED BY:	LIDIOUN TITLE DI	J DUDENY	DATE 11	12014
Conditions of Approval (if any	1122		2001	
rr ( may)	J		APR 16 201	4-
			. *	

### PROCEDURE TO PLUG AND ABANDON

# Langlie Jal Unit #17 Langlie Mattix (7-Rivers, & Queen) Field Lea County, New Mexico 4/4/14 AFE #614027

# **GENERAL WELL DATA**

- 8-5/8" 40# surface csg @ 1,150', cmt'd w/450 sxs. TOC @ 484' calc'd @ 75%
- 5-1/2" 15# prod. csg @ 3,554', cmt'd w/200 sx. TOC @ 2,601' by temp survey
- TD @ 4,006'
- PBTD @ 3.546'
- 7-Rivers perfs: 3,283'-3,515'
- Queen perfs: 3,515'-3,538'

# OBJECTIVE: Plug and Abandon Well.

## **PROCEDURE**

- 1. Hold Safety Meeting. High concentrations of H2S may be present. MIRU plugging equipment.
- 2. Kill well if necessary and ND WH, remove any tubing joints, and NU BOP.
- 3. PU work string and RIH to set CIBP @ 3230'.
- 4. Circulate well with mud.
- 5. Spot 40 sxs of cement on top of CIBP, 3230' 2,835'.
- 6. POOH with work string. TO 2651'. SPOT 255X5 CMT.
- 7. MIRU WL. Pick-up-perf-gun and perf 5-1/2" csg @ 1,400'.
- 8. POOH wireline and RIH with tubing and packer.
- 9. Pump & squeeze 26 sxs of cement into perfs at 1,400' and flush to 1,300'.
- 10. POOH with work string and WOC.
- 11. Tag top of plug @ 1,300'.
- 12. Pick up perf gun and perf 5-1/2" csg @ 1,200'.
- 13. POOH wireline and RIH with tubing and packer.
- 14. Pump & squeeze 62 sxs of cement into perfs at 1,200' and flush to 954'.
- 15. POOH with work string and WOC.

16. Tag top of plug @ 954'.	
17. Pick up perf gun and perf 5-1/2" and 8-5/8" csg @ 350'.	
18. POOH wireline.	
19. Pump & squeeze 178 sxs of cement down casing into perfs at 3 surface. Cement should be on backside of 5-1/2" and 8-5/8" ca	_
20. RDMO plugging equipment.	
21. ND BOP.	
22. Cut off well head and weld on marker.	
PREPARED BY:Martin Staelens	DATE:4/9/14
APPROVED BY: Shawn Young	DATE: 4/10/14

	COMPLETION SCHEMATIC	LEASE NAME	Langlie	Jal Unit		WELL NO. 17' WIW
		STATUS:	inj in	ection 0		API# 30-025-11301
		LOCATION: SPUD DATE:	08/14/57 TD	31, T - 24S, R - 37E; Lee County, 4006	New Mexico KB	DF 3241'
Surface Csg	1     1	INT. COMP. D	ATE: 09/17/57 PBTD	3546 GEOLOGICAL D	GL 3,233'	GR
Size: 11"	1   1   1		ELECTRIC LOGS:	GEOLOGICAL D		S, DST'S or MUD LOGS:
G Size: 8 5/8" @ 1150'	1   1   1	İ				
: 450 sx Cl C		į.				
: @ 484'	TOC @ 484' Calc'd @ 75%	1		HYROCARBON BEARING ZO	NE DEPTH TOPS:	
<b>9</b> 4		Yates @ 2959'	7-Rivers @ 3185'	Queen @ 3496'		
* 4				CASING PROF	:II F	
		Surf Csg	8 5/8" - 40#, H - 40 set @ 1150' Cmt'			
ь -		PROD.	5 1/2" 15# J-55 set @ 3,554'. Cemer			
(a) a		Liner				
A				CURRENT PERFORA	TION DATA	
		CSG. PERFS	3:	OURRENT FERT ORA	OPEN HOLE	: 3554'-4006'
			Perf'd 7-Rivers & Queen f/ 3,504'-09',			
		01-Dec-81	Perf'd 7-Rivers & Queen f/ 3283'-92', 3	296'-3302', 3327'-3335', 3353	'-3358', & 3374'-3386'.	
	1 1 1 1	TUBING DE	TAIL 2/25/2002		ROD DETAIL	
	1 1 1 1	100MODE	TAIL LIEUTEUR		1100000177712	
	1					
	1   1	3235				
	TOC @ 260°	1' 3240	-			
	Temp Surve					
i.						
		WELL HISTO	ORY SUMMARY			
		40.0	Barfel 7. Bivora 9 Overs - 512 FOALOO	3 511'-18' 8 3 530' 30' 64'- 7	000 gale Sandail mined 4	Dumning 27 hand 9 24 kmm²
		18-Sep-57	Perf'd 7-Rivers & Queen f/ 3,504'-09',	J,JII-10 @ 3,330-38". 58M 5	оче сыр сынасын турд	j. + umping 27 bopu & 21 bwpd.
		25-May-72	Convert to Injection. Ran 2 3/8" IPC tub	ing with Guiberson 2 3/8" x 5	1/2" Uni - PKR. Set at 3,384'	
			•	_		
		I	POOH with injection string. Tagged at 3		ized perfs 3,504'-3,538' with 3	i,000 gals 20% w/ 1 1/2" AFA.
1 is			Injection after treatment: 300 bwpd @	9 590 psig.		•
12 23		01-Dec-81	Perf'd 7-Rivers & Queen f/ 3283'-92', 3	296'-3302'. 3327'-3335'. 3353	'-3358', & 3374'-3386', Frac'd	with 15,000 gals 15% HCI carrying
-1;		01-560-01	15,500 # sand. After W/O Rate: 1,000			, , , , , , , , , , , , , , , , , , ,
i i		08-Jul-00	Acidized with 500 gals 15% NEFE HCI.			
	PKR @ 3,240'					
	Yates @ 2879'					
	1 Tales @ 2679	-				
oduction Casing		1				
le Size: 7 7/8 in		1				
g. Size: 5 1/2 in	<b>1</b>					
Set@: 3554:11	. # ·	-				•
Cmt: 200 C @ 2,601' by TS.	7-R @ 3100'			i.		
	3283'-3292'					
T.	<b>.</b>					
	3296'-3302'					
	3327'-3335'					
	\$ .					
	3353'-3358'					
<u> </u>	3374'-3386'					
	Š.					
	8					٠
Į.	3504'-3409'					
है <sub>है</sub> यह	Queen @ 3515	5'				
2	3511-3518'					
	3530'-3538'					
,	CICR @ 3546'					
Shoo @ 2 ccu						
Shoe @ 3,554*						
	90 sx					
	Class C		•			
	48.35 (F. C.) (F. C.)					
TD @ 4,006'		1				
TD @ 4,006'		l l				
TD @ 4,006'						
TD @ 4,006'						
	OH ID: 6 1/4"					
	OH ID: 6 1/4"					

.

				WELLBORE SCHEN PROPOSED F		DRY			
	CURRENT COMPLETION SCHEMATIC		ASE NAME		Langlie Ja			WELL NO.	17 WIW
			ATUS: CATION:	lnj 1980 FSL & 19	Inject 30 FEL. Sec 31. T	on O - 24S, R - 37E; Lee County,		API#	30-025-11301
		SPU	UD DATE: L. COMP. DATE	08/14/57	TD	4006 3546	K8 GL 3,233	DF GR	3241'
Surface Csg		rf & Sqz 178 sxs	. COMP. DATE		FBTO	GEOLOGICAL D	ATA		
le Size: 11" G Size: 8 5/8"	350	)' - surface		ELECTRIC LOGS:			COR	S, DST'S or M	UD LOGS:
t @ 1150' nt: 450 sx Cl C									
rc: @ 484"		C @ 484'			H,	ROCARBON BEARING ZON	IE DEPTH TOPS:		
alc'd @ 75%		lc'd @ 75%	tes @ 2959'	7-Rivers @ 31	85'	Queen @ 3496*			
The second secon			O O	5/8" - 40#, H - 40 set @	1150' Cmt'd w	CASING PROF			
				1/2" 15# J-55 set @ 3,5					
		<del> </del>	ner .						
		ļ				CURRENT PERFORA	TION DATA		
		cs	SG. PERFS:			CORRENT FERFORA	OPEN HOL	E:	3554'-4006'
•	5.0 - 1 - 500 - A	18-	-Sep-57 Pe	erf'd 7-Rivers & Queen f/					
	46	POT 25 01-	-Dec-81 Pe	erf'd 7-Rivers & Queen f/	' 3283'-92', 3296	'-3302', 3327'-3335', 3353	'-3358', & 3374'-3386'.		
	26.50	- シスタ -1400:-1200: TU	IBING DETAI	IL 2/25/2002			ROD DETAIL		
		\		_					
		ا 'وسر د	2025	o out IDO T	<b>4</b> 1				
	7 /2	1651	3235 5	2 3/8" IPC Tu 2 3/8" x 7" Un					
		TOC @ 2601'	3240	25.0 %. 01					
		Temp Survey							
		1275	ELL MICTOR	Y SUMMARY					
		VVE	ELL HISTOR	T SUMMARY					
	3	18-	-Sep-57 Pe	erf'd 7-Rivers & Queen f/	3,504'-09', 3,51	1'-18' & 3,530'-38'. Stim 5	000 gals Sandoil mixed 1 p	og. Pumping	27 bopd & 21 bwpd.
		25-	-May-72 Co	onvert to Injection. Ran 2	3/8" IPC tubing v	vith Guiberson 2 3/8" x 5	/2" Uni - PKR. Set at 3,384		
		10-	-Mar-78 PC	OOH with injection string.	Tagged at 3.544	'. Set PKR @ 3.472'. Acid	ized perfs 3,504'-3,538' with	3,000 gals 2	0% w/ 1 1/2" AFA.
		.5		jection after treatment:				-, 3	
			_						
		01-		erf'd 7-Rivers & Queen t/ 5,500 # sand. After W/O F			'-3358', & 3374'-3386'. Frac	d with 15,000	gais 15% HCI carrying
				7,000 // Suita. 74101 1110 1	10.00 0.10				
		08-	-Jul-00 Ad	cidized with 500 gals 15%	NEFE HCI.				
	PKR @ :	3,240'							
	f a.								
	40 sxs	3230' - 2835'					•		
oduction Casing									
ole Size: 7 7/8	200 T 000 C	@ 2879'							
sg. Size: 5 1/2 Set @: 3554'	*** The state of t	1							
s Cmt; 200	"								
OC @ 2,601' by TS.	7-R @	3100'							
	3283'-3	@ 3230'							
	3283-3	3292							
	3296'-3	3302'							
	3327'-3	3335'							
	nom Hills	3358						•	
<b>Y</b>	33531-3			•				•	
1	3353'-3	·							
•	3353-3 3374-3	3386'							
¥		3386'							
,		3386'							
1									
1	3374-2 3504-3 Qu	3409' een @ 3515'							
1	3374°-3 3504°-3	3409' een @ 3515'							
•	3374-3 3504-3 Qui 3511-3	3409' een @ 3515' 3518'							
,	350413 Qui 351113	3409' een @ 3515' 3518'							
,	3574-3 3504-3 Qui 3511-3 3530-3 CICR (	3409' een @ 3515' 3518'							
Shoe @ 3	3574-3 3504-3 Qui 3511-3 3530-3 CICR (	3409' een @ 3515' 3518'							
Shoe @ 3	3574-3 3504-3 Qui 3511-3 3530-3 CICR (	3409' een @ 3515' 3518'							
\ Shoe @ 3	3574-3 3504-3 Qui 3511-3 3530-3 CICR (	3409' een @ 3515' 3518'							
` Shoe @ 3	3374-3 3504-3 Qur 3511-3 3530-3 CICR (	3409' een @ 3515' 3518'							
\ Shoe @ 3	350413 Qui 351113 353013 CICR (	3409' een @ 3515' 3518'							
`Shoe @ 3	3374-3 3504-3 Qur 3511-3 3530-3 CICR (	3409' een @ 3515' 3518'							
Shoe @ 3	3374-3 3504-3 Qur 3511-3 3530-3 CICR (	3409' een @ 3515' 3518'							
Shoe @ 3	3374-3 3504-3 Qur 3511-3 3530-3 CICR (	3409' een @ 3515' 3518'							
	3374*3 Que 3511*3 3530*3 CICR (6	3409' een @ 3515' 3518'							
TD @ 4,0	3374*3 Que 3511*3 3530*3 CICR (6	3409' een @ 3515' 3518'							
	3374*3 Que 3511*3 3530*3 CICR (6	3409' een @ 3515' 3518'							
	3374*3 Que 3511*3 3530*3 CICR (6	3409' een @ 3515' 3518'							
	3374-3 3504-3 Que 3511-3 3530-3 CICR (6	3409' een @ 3515' 3518'							
	3374-3 3504-3 Qui 3511-3 GCICR 6 CICR 6	3409' een @ 3515' 3518'							