Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Hobbs

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

5. Lease Serial No. LC-069052

6. If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an

abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit of CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on page 2. WEST DOLLARHIDE QUEEN SAND UNIT 1. Type of Well 8. Well Name and No. WEST DOLLARHIDE QUEEN SAND UNIT #113 Oil Well Gas Well √ Other INJECTOR 9. API Well No 30-025-30231 Name of Operator CHAPARRAL ENERGY, LLC 3a, Address 701 CEDAR LAKE BLVD, OKC, OK 73114 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area DOLLARHIDE QUEEN 405-478-8770 4. Location of Well (Footage, Sec., T.R.M., or Survey Description) 330' FNL & 2360' FWL, UNIT C, SECTION 31-T24S-R38E 11. Country or Parish, State LEA COUNTY, NM 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Deepen Acidize Production (Start/Resume) Water Shut-Off ✓ Notice of Intent Alter Casing Fracture Treat Reclamation Well Integrity Other REPAIR WELL Casing Repair New Construction Recomplete Subsequent Report Change Plans Plug and Abandon Temporarily Abandon Final Abandonment Notice Convert to Injection Plug Back Water Disposal 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) MIRU WORK OVER RIG. DETERMINE WHY WELL FAILED BRADENHEAD TEST. REPAIR AS NEEDED must have BLM approval ubmit-1001 for specific FIELD OPERATIONS WILL BE CONDUCTED USING CLOSED LOOP SYSTEM. HOBBS OCD APR 28 2014 RECEIVED 14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) LINDSAY REAMES Title ENGINEERING TECH ILREGUL Date 09/30/2013 Signature THIS SPACE FOR FEDERAL OR STATE OFFICE US Approved by Title DAGNO MANAGEMEN Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify CARLSBAD FIELD OFFICE

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false

(Instructions on page 2)

entitle the applicant to conduct operations thereon.

MSB/OCD 4/29/2014

that the applicant holds legal or equitable title to those rights in the subject lease which would

fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

APR 3 0 2014

