New Mexico OS Conservation 1211-1011, Desirie! I

1625 N. French Drive

Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR

Hobbs, NM 88240

BUREAU OF LAND MANAGEMENT

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

5. Lease Designation and Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS

Use "APPLICATION FOR F	PERMIT—" for such proposals	Servoir.
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation
Sec. 27 T-245	, Florida 33012	8. Well Name and No. 12-101 U. LANGLIE MAHTIX Ubolwarth 9. APT Well No. 30-025-1125 7 10. Field and Pool, or Exploratory Area LANGLIE MAHTIX QUEE 11. County or Parish, State LEA N.M. REPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF	<u> </u>
Notice of Intent Subsequent Report Final Abandonment Notice	Abandonment Recompletion Plugging Back Casing Repair Altering Casing Other	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*



Approved as to plugging of the well frame wability under bond is retained until surface restoration is completed.

14. I hereby certify that the foregoing is true and correct Signed	Title_AgeNT	Date 10-5-05
(This space for Federal or State office use) Approved by Conditions of approval, if any:	Tide STROLEUM ENGINEER	OCT 1 4 2005

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

MAYO MARRS CASING PULLING INC. BOX 863 KERMIT, TEXAS 79745

BETWELL OIL & GAS

Lease: LANGLIE MATTIX WOOLWORTH UNIT # 707

Project: P & A – CEMENTING REPORT

09-08-05 - SET CIBP @ 3100'-SPOT 25 SXS ON TOP-2951'

09-08-05 - SPOT 25 SXS @ 2700'-2547'

09-08-05- PERFORATE @ 1200' - SQUEEZE 50 SXS - TAG @ 1044'

09-09-05 - PERFORATE @ 412'- SQUEEZE 85 SXS - TAG @ 274'

09-09-05 - SPOT 25 SXS @ 90' TO SURFACE

INSTALL DRY HOLE MARKER CIRCULATE 10# MUD

