

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised August 1, 2011

CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

HOBBS OCD

WELL API NO. 30-025-03241
5. Indicate Type of Lease STATE FEE XX
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name West Pearl Queen Unit
8. Well Number 117
9. OGRID Number 25482
10. Pool name or Wildcat Pearl Queen
11. Elevation (Show whether DR, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well XX Gas Well <input type="checkbox"/> Other <input type="checkbox"/>
2. Name of Operator State of New Mexico formerly Xeric Oil & Gas Corp
3. Address of Operator 1625 N. French Drive Hobbs, NM 88240
4. Well Location Unit Letter K : 1980 feet from the S line and 1980 feet from the W line Section 29 Township 19S Range 35E NMPM Lea County
11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A XX
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

4/17/2014 MIRU. Dug out cellar and worked to get wellhead cap off.

4/18/2014 Installed BOP. POOH with tubing. RIH with tubing and circulated MLF from existing CIPB at 4752'. Spotted 25 sx class c cement on top of CIBP. POOH and spotted 25 sx cement at 3402'. POOH and SION.

4/21/2014 Perforated at 1800'. RIH with packer and pressured up on perms. Held 525#. Released packer and spotted 25 sx class c cement across perms from 1858'. POOH and WOC. RIH and tagged at 1657'. Perforated at 200' and circulated cement down 5 1/2" casing to perms and up annulus to surface. Pumped 105sx. Rigged down, cut off wellhead and filled both string of casing to surface with 15 sx cement. Installed marker and cut off anchors.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE _____ TITLE _____ DATE _____

Type or print name _____ E-mail address: _____ PHONE: _____

For State Use Only

APPROVED BY: Mary Brown TITLE Dist. Supervisor DATE 5/1/2014
Conditions of Approval (if any) _____