

District I - (575) 393-6161
1625 N. French Dr., Hobbs
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

Energy, Minerals and Natural Resources

Revised August 1, 2011

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-03244
5. Indicate Type of Lease STATE FEE XX
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name West Pearl Queen Unit
8. Well Number 112
9. OGRID Number 25482
10. Pool name or Wildcat Pearl Queen
11. Elevation (Show whether DR, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)
1. Type of Well: Oil Well [ ] Gas Well [ ] Other [ ] Injection Well [ ]
2. Name of Operator State of New Mexico formerly Xeric Oil & Gas Corp
3. Address of Operator 1625 N. French Drive Hobbs, NM 88240
4. Well Location Unit Letter F: 1980 feet from the N line and 1980 feet from the W line
Section 29 Township 19S Range 35E NMPM Lea County
11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK [ ] PLUG AND ABANDON [ ]
TEMPORARILY ABANDON [ ] CHANGE PLANS [ ]
PULL OR ALTER CASING [ ] MULTIPLE COMPL [ ]
DOWNHOLE COMMINGLE [ ]
OTHER: [ ]
SUBSEQUENT REPORT OF:
REMEDIAL WORK [ ] ALTERING CASING [ ]
COMMENCE DRILLING OPNS. [ ] P AND A XX
CASING/CEMENT JOB [ ]
OTHER: [ ]

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

4/14/2014 MIRU. Dug out cellar and installed BOP. Started Picking up work string.

4/15/2014 Tagged up at 2979'. POOH and picked up bit. RIH and attempt to wash down. Made no progress. POOH with bit and RIH open ended circulated MLF and spotted 25 sx class c cement. SION.

4/16/2014 RIH and tagged cement at 2838'. POOH and perforated at 1850'. Picked up packer and pressured up to 550# and held for 15 minutes. Released packer and POOH. RIH open ended and spotted 25 sx cement at 1917'. WOC and tagged at 1775'. POOH and perforated at 200'. Established circulation and attempted to circulated cement down 7" casing to perfs @ 200' and up annulus to surface. Pumped 145 sx. No cement to surface.

4/17/2014 Rigged down. Cur off wellhead. One inched annulus to surface. Took 15 sx cement. Installed marker and cut off anchors.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE TITLE DATE

Type or print name E-mail address: PHONE:

For State Use Only
APPROVED BY: Mary Brown TITLE Dist. Supervisor DATE 5/1/2014
Conditions of Approval (if any):