Submit 3 Copies To Appropriate District Office.	State of New Me		Form C-103	
District I	Energy, Minerals and Natu	iral Resources	WELL ADIAIO	June 19, 2008
1625 N. French Dr., Hobbs, NM 87240 District II	OH GONGERMATION PHYRION		WELL API NO: 30-025-08706	
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.		5. Indicate Type of Lease	
District III 1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505		STATE 🗷	FEE 🗆
District IV 1220 S. St. Francis Dr., Santa Fe, NM	· · · · · · · · · · · · · · · · · · ·		6. State Oil & Gas Le	ease No.
87505				
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Un Eunice Monument S	• •
1. Type of Well: Other Injection			8. Well Number 221	
2. Name of Operator			9. OGRID Number	
XTO Energy, Inc.			005380	
3. Address of Operator 200 N. Loraine, Ste. 800 Midland, TX 79701			10. Pool name or Wildcat Funice Monument; Grayburg-San Andres	
200 N. Loraine, Ste. 800 Midland, TX 79701 Eunice Monument; Grayburg-San Andres 4. Well Location				
Unit Letter N :	33300 feet from the Sou	uth line and	1980 feet from t	he <u>West</u> line
Section 6	Township 21S	Range 36E	NMPM	County Lea
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
NOTICE OF INTENTION TO: SUB			SEQUENT REPO	ORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK				ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLI	ING OPNS. 🔲	P AND A
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT J	ов 🗆	
DOWNHOLE COMMINGLE				
DO WITHOUT OOK MININGER				
OTHER:		OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
03/26/2014: XTO Energy. T	nc ran a failed bradenhead	l test. Well is sh	ut-in, waiting on n	ulling mit.
1. MIRU PU.	DC 1011 & 101164 Droughes	z ceser nezz zo ez		OBBS OCD
2. POOH w/tbg & pkr.			•	*
3. Reset pkr.			A.A	AY 08 2014
4. Run good MIT. 5. RUMO PU.			JA):	MI VV
5. KARD FU.				
A closed-loop system will	be used to perform these	operations.		RECEIVED
				7
Spud Date:	Rig Rele	ase Date:		
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
At about Phanes				
SIGNATURE THE YOUR	<u> Kadaani</u> Tit	TLE <u>Regulato</u>	ry Analyst D	ATE 04/01/2014
	,	stephanie_rabadue@		1103 THE 120 COA CET 4
Type or print name Stephanie Rab	acue E-ņ	nail address:	P	HONE <u>432-620-6714</u>
For State Use Only	Arrantad #-	Da.		
APPROVED BY	Accepted for	TECOTO CILIY	DA	TE
Conditions of Approval (if any):	YMA 5	18/2014		1