Submit 1 Copy To Appropriate District	State of New 1	Mexico	Form C-103
Office <u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources		Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240	strict II – (575) 748-1283 I S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION strict III – (505) 334-6178 1220 South St. Francis Dr. 2000		WELL API NO. 30-025-34258
811 S. First St., Artesia, NM 88210			5. Indicate Type of Lease
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410			STATE FEE
<u>District IV</u> – (505) 476-3460	Santa Fe, NM		6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		10 510Y 1 9 2014	
SUNDRY NOTICES AND REPORTS ON WELLS WAY			7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Gettysburg 16 State SWD
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			8. Well Number
1. Type of Well: Oil Well Gas Well Other SWD			1
2. Name of Operator			9. OGRID Number 229137
COG Operating LLC 3. Address of Operator			10. Pool name or Wildcat
2208 W. Main Street, Artesia, NM 88210			SWD; Delaware
4. Well Location			
Unit Letter J: 1980 feet from the South line and 1980 feet from the East line			
Section 16 Township 23S Range 34E NMPM Lea County			
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
3423' GR			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSE			SEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK			K ☐ ALTERING CASING ☐
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI	_
PULL OR ALTER CASING DOWN HOLE CONTROL TO THE CON	MULTIPLE COMPL	CASING/CEMENT	T JOB
DOWNHOLE COMMINGLE			
OTHER:		OTHER: F	Re-Entry Operations
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of			
proposed completion or recompletion.			
4/25/14 to 5/8/14 MIRU WSU. Test csg & BOP to 2000#. Test ok. Drill cmt & clean out to 6800'. Circulate clean. Set pkr @			
5009' & test csg to 1000# for 30 mins. Good test. Unset pkr. RIH open-ended to 6761' & pump 100 sx Class C cmt. WOC &			
tag @ 6581'. Pump 50 sx on top of 1 st plug. WOC & tag @ 6520'. Set 4 ½' 11.6# L-80 Glassbore internally-lined tbg & pkr @ 4957'. Circ w/340 bbls pkr fluid. Pressure tested csg to 560# for 30 mins. Witnessed by NMOCD rep, Bill Sonnamaker.			
(Chart is attached. Order SWD-1416)			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE	TITLE:	Regulatory Analyst	DATE: 5/13/14
Type or print name: Stormi Da		lress: sdavis@concho	
For State Use Only \\\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \			
APPROVED BY: VALUE SUBJECT SUBJECT STATES DATE 5/19/2014			
Conditions of Approval (if any):	THE		
` '' U			

