Submit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103		
District I = (575) 393-6161 Energy, Minerals and Natural Resources			Revised July 18, 2013 WELL API NO.		
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283 OH. CONSERNATION DIVISION			30-025-03063		
811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION		1 1	5. Indicate Type of Lease		
District III – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 JUN 2 6 2011/220 South St. Francis Dr. District IV – (505) 476-3460 Santa Fe, NM 87505			STATE FEE		
1220 S. St. Francis Dr. Santa Fe. NM	, , , , , , , , , , , , , , , , , , , ,	6. St	tate Oil & Gas Lease No. B-2131		
87505 g	RECEIVED				
(DO NOT USE THIS FORM FOR PROPOSA	ËŠ AND REPORTS ON WELLS LS TO DRILL OR TO DEEPEN OR PLUG BA TION FOR PERMIT" (FORM C. 101) FOR SU	CK TO A	ease Name or Unit Agreem		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			Vacuum Abo Unit Tract 14 8. Well Number		
1. Type of Well: Oil Well Gas Well Other			001 /		
2. Name of Operator			9. OGRID Number		
ConocoPhillips Company 3. Address of Operator			217817 10. Pool name or Wildcat		
P.O. Box 51810, Midland, TX 79710			Vacuum; Abo Reef		
4. Well Location					
Unit LetterK:19	80feet from theSouth	line and1980	feet from theWest	:line	
Section5	Township 18-S Range 35-	-E NMPM	Lea County		
	11. Elevation (Show whether DR, RKE	RT/GR, etc.)			
3958' GR					
12 Chook Ar	propriate Box to Indicate Nature	a of Nation Pana	rt or Other Data	,	
12. Check Ap	propriate Box to indicate Nature	e of Notice, Repo	n or Other Data	Ÿ	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR					
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRIL			OPNS. P AND A	\boxtimes	
PULL OR ALTER CASING					
DOWNHOLE COMMINGLE					
CLOSED-LOOP SYSTEM OTHER:		HER:		□ ·	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date					
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of					
proposed completion or recompletion.					
6/5/14MIRU.	. 4				
6/6/14Dig out cellar 133/8 bad p	oipe - fix it. 4½ & 85/8 blow gas & oil.				
6/9/14NUBOP. RIH 23/8 to 820					
6/10/14Spot 25 sxs @ 8205' CTOC 7804', POOH to 6200' spot 25 sxs CTOC @ 5818', PUH to 4600' spot 25 sxs					
6/11/14Tag @ 4433'. RIH w/ WL perf @ 4080' sqz 40 sxs. 6/12/14Tag @ 3920'. RIH w/ WL perf @ 3250' sqz 100 sxs.					
6/12/141ag @ 3920 : KIH W/ V 6/13/14Tag @ 2834'. RIH w W		4		·	
	VL perf @ 365' sqz 413 sxs fill 4½ & 8	R ⁵ / ₈ .	٠	1541.7°	
6/17/14Tag @ 83'. RIH w/ WL perf @ 83' sqz 63 sxs bring 8\% & 13\% to surface.					
6/18/14RIH Tag @ 77' – OCD advise not to fill wellbore until cut off. RDMO.					
Verity CMT-ALL STRINGS TO SURFACE.					
	•			i i	
Spud Date: 6/18/61	Rig Release Date:	7/15/6	51	,	
<u> </u>	<u>.</u> .				
I hereby certify that the information ab	ove is true and complete to the best of	my knowledge and b	pelief.		
SIGNATURE	TITLE	P&A Tech	DATE6/23/14	_4v	
Town and the Control of the Control	Parallada		DIJONE 400 560 0055	7	
Type or print nameGreg Bryant_ For State Use Only \ \(\)	E-mail address:		_ PHONE: _432-563-3355		
Walk a sur Diet Su Danle de la					
APPROVED BY: 1 WWW DELOW TITLE DUL! SURWING DATE 6/50/014					
Conditions of Approval (if any):					
			JUL W. A. L.		