Office	f New Me			/ F	form C-103	
District I Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240 HOBBS OCD		WELL API NO.				
OIL CONSERVATION DIVISION			30-025-05394   5. Indicate Type of Lease			
District III 1301 W. Grand Ave., Artesia, NM 88210 District III 1000 Rio Brazos Rd., Aztec, NM 87410 JUN 3 0 2014220 Sour Santa I	th St. Fran	cis Dr.	STATE	] FEE		
District IV Santa Fe, NM 1220 S. St. Francis Dr., Santa Fe, NM 87505 RECEIVED	Fe, NM 87	303	6. State Oil & Gas 306871	Lease No.		
SUNDRY NOTICES AND REPORTS (			7. Lease Name or U	Juit Agree	ment Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DE DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FO PROPOSALS.)			D.E. Meyers 8. Well Number	/		
1. Type of Well: Oil Well 🛛 Gas Well 🗌 Other			1			
2. Name of Operator / Saber Oil & Gas Ventures, LLC			9. OGRID Number	•		
3. Address of Operator			10. Pool name or <b>X</b>		/	
400 W. Illinois, Ste. 950 Midland, TX 79701			Lovington Paddock	, Tubb		
4. Well Location Unit Letter L : 660 feet from the West	line and	1980 feet fr	om the South line			
Section 33 Township 16-S	Range			ounty LEA		
11. Elevation (Show the second	whether DR,	RKB, RT, GR, d				
3798' D.F.   Pit or Below-grade Tank Application or Closure		<u> </u>				
Pit typeDepth to GroundwaterDistance from r	nearest fresh w	ater well	Distance from nearest surfac	e water		
Pit Liner Thickness: mil Below-Grade Tank: V	Volume	bbls;	Construction Material			
12. Check Appropriate Box to I	Indicate N	ature of Notic	ce, Report or Other I	Data		
NOTICE OF INTENTION TO:		SI SI	JBSEQUENT REP			
PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING     TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS   P AND A						
TEMPORARILY ABANDON CHANGE PLANS		COMMENCE		P AND A		
OTHER:		OTHER:			Ē	
13. Describe proposed or completed operations. (Clea of starting any proposed work). SEE RULE 1103.		pertinent details,				
or recompletion.		·	Ū.			
5-30-14 – RIH w/tbg OL w/PS. Tag CIBP @ 8105'. Circ hc 6-2-14 – Perf @ 7700'. Sqz 25sx cmt. WOC. Tag @ 7614' 6-3-14 – Perf @ 6160'. Sqz 25sx cmt. POOH w/pkr. WOC. 6-4-14 – Perf @ 5000'. Sqz 30sx. WOC. Tag @ 4560'. 6-5-14 – Perf @ 2970'. Set pkr @ 2659'. Load hole, pressu cmt 50' under the perfs. WOC & tag. RIH w/Tbg, tag cmt @	OK. & tag @ 56 re up to 180	14'.		was told ok	ay to spot 40sx.	
		- / · · · · · ·				
6-6-14 – Perf @ 2100. RIH w/tbg to 1818'. Load hole, set p	okr, pressure	up to 1500' psi.	Did not sqz, spoke w/M	ark.		
6-9-14 – Was told okay to spot 25sx cmt @ 2150'. WOC & WOC & tag @ 1848'.	tag @ 2073	'. Spoke w/Mar	k, was told to spot 25 mo	ore sx of cn	nt @ 2073'	
6-10-14 – Perf @ 385'. RIH w/tbg to 435'. Load hole, close valve. 6-10-14 – Pump cmt to surf. Visual. POOH w/tbg. WOC & dry hole marker.	·					
I hereby certify that the information above is true and comp grade tank has been/will be constructed or closed according to NMOC	olete to the b D guidelines [	est of my knowl □, a general permi	edge and belief. I further t 🗌 or an (attached) alterna	r certify that tive OCD-ap	any pit or below- proved plan □.	
SIGNATURE Ulayne Pinetto		General	Manager	_date_ <b>6</b>	·20.14 N	
Type or print name	E-mail ac		•	lephone No	. Pu	
APPROVED BY:	, TITLE	sent S.	Puriou >	DATE L	30/2014	
Conditions of Approval (if any):		<u> </u>	1 111	0 1 20	14	
•			JUL		<b>7</b>	

APPROVED BY:		M	μυ
Conditions of App	roval (if a	ny):	